Software Maintenance Release Note

Maintenance Version 291-20

for AR415S, AR440S, AR441S, AR442S, AR450S, AR725, AR745, AR750S, AR750S-DP, and AR770S routers and AT-8600, AT-8700XL, Rapier i, Rapier w, AT-8800, AT-8900, x900-48, AT-9900, and AT-9800 Series switches

This software maintenance release note lists the issues addressed and enhancements made in Maintenance Version 291-20 for Software Version 2.9.1. Version details are listed in the following table:

Models	Series	Release File	Date	Size (bytes)	GUI file
AR415S, AR440S, AR441S, AR442S, AR450S	AR400	54291-20.rez	22 July 2009	4918136	415s_291-20_en_d.rsc 440s_291-20_en_d.rsc 441s_291-20_en_d.rsc 442s_291-20_en_d.rsc 450s_291-20_en_d.rsc
AR750S, AR750S-DP, AR770S	AR7x0S	55291-20.rez	22 July 2009	4051476	750s_291-19_en_d.rsc (AR750S and AR750S-DP)
AR725, AR745	AR7x5	52291-20.rez	22 July 2009	4051476	_725_291-20_en_d.rsc _745_291-20_en_d.rsc
AT-8624T/2M, AT-8624PoE, AT-8648T/2SP	AT-8600	sr291-20.rez	22 July 2009	2546744	8624t_291-20_en_d.rsc 8624poe_291-20_en_d.rsc 8648t_291-20_en_d.rsc
AT-8724XL, AT-8748XL	AT-8700XL	87291-20.rez	22 July 2009	2453752	8724_291-20_en_d.rsc 8748_291-20_en_d.rsc

Models	Series	Release File	Date	Size (bytes)	GUI file
Rapier 24i, Rapier 48i, Rapier 16fi	Rapier i	86291-20.rez	22 July 2009	4661784	r24i_291-20_en_d.rsc r16i_291-20_en_d.rsc r48i_291-20_en_d.rsc
Rapier 48w	Rapier w	86291-20.rez	22 July 2009	4661784	-
AT-8824, AT-8848	AT-8800	86291-20.rez	22 July 2009	4661784	8824_291-20_en_d.rsc 8848_291-20_en_d.rsc
AT-8948, AT8948i, x900-48FE, x900-48FE-N, x900-48FS	x900-48	89291-20.rez	22 July 2009	4952332	-
AT-9924T, AT-9924SP, AT-9924T/4SP	AT-9900	89291-20.rez	22 July 2009	4952332	9924_291-20_en_d.rsc
AT-9812T, AT-9816GB	AT-9800	sb291-20.rez	22 July 2009	4037532	9812_291-20_en_d.rsc 9816_291-20_en_d.rsc

Caution: Using a maintenance version on the wrong model may cause unpredictable results, including disruption to the network.

This maintenance release note should be read in conjunction with the following documents:

- the Release Note for Software Version 2.9.1, available from www.alliedtelesis.co.nz/documentation/relnotes/relnotes.html, which describes the new features since Version 2.8.1
- your router or switch's document set for Software Release 2.9.1. This document set is available on the CD-ROM that shipped with your router or switch, or from www.alliedtelesis.co.nz/documentation.html

Caution: Information in this release note is subject to change without notice and does not represent a commitment on the part of Allied Telesis, Inc. While every effort has been made to ensure that the information contained within this document and the features and changes described are accurate, Allied Telesis, Inc. can not accept any type of liability for errors in or omissions arising from the use of this information.

Enabling and installing this version

To use this maintenance version you must have a release license suitable for Software Release 2.9.1. To check for a suitable license ('291' or 'ANY release'), before upgrading enter the command:

show release

If no '291' or 'ANY release' license exists, then contact your distributor or reseller to obtain an upgrade license.

If an earlier revision 291 release license exists, enter the commands:

enable rel=xx291-20.rez num=2.9.1

set install=pref rel=xx291-20.rez

If an 'ANY release' license exists, enter the command:

set install=pref rel=xx291-20.rez

where *xx* is the prefix to the filename, as shown in the table on page 1. For example, to install the version on an x900-48FE switch, use the commands:

enable rel=89291-20.rez num=2.9.1

set install=pref rel=89291-20.rez

Levels

Some of the issues addressed in this maintenance version include a level number. This number reflects the importance of the issue that has been resolved. The levels are:

- Level 1 This issue will cause significant interruption to network services, and there is no work-around.
- Level 2 This issue will cause interruption to network service, however there is a work-around.
- Level 3 This issue will seldom appear, and will cause minor inconvenience.
- Level 4 This issue represents a cosmetic change and does not affect network operation.

Features in 291-20

Software Maintenance Version 291-20 includes the resolved issues in the following tables. In the tables, for each product series:

- "Y" indicates that the resolution is available in Version 291-20 for that product series.
- "-" indicates that the issue did not apply to that product series.

No Level 1 CRs

Level 2

CR	Module	Level	Description	AR44x/AR450S/AR415S	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00026009	Port Auth	2	Using MAC based port authentication and DHCP, clients were being assigned to the wrong port. This issue has been resolved.	_	_	_	Y	Y	Y	Y	Y	-	-	-
CR00026075	core	2	Previously, the CAS latency on the memory was set too low which risked causing memory errors. This issue has been resolved.	_	_	Y	Ι	_	_	-	_	_	_	-
CR00026654	OSPF	2	If external LSAs were deleted due to 'maxage' for any reason(for example the link to the OSPF neighbour from where they were imported went down), then the redistribution count was not being correctly maintained and could result in routes not being readded when the LSAs were re-added. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR44x/AR450S/AR415S	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00026726	IPv4	2	It is possible for a system reboot to occur when processing a BPDU with iP enabled. This has been fixed.	-	_	_	_	_	_	_	_	Y	Y	Y
CR00026755	OSPF	2	A system reboot could occassionally occur when an excessive number of OSPF neighbours and LSAs were processed. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00008803	Switching	2	Previously, when slowly inserting a GBIC into a AT-9800, the GBIC would fail to be detected. This issue has been resolved.	-	_	_	_	_	_	_	_	_	_	Y
CR00014132	Firewall	2	Previously, SIP clients sent on one port of the router, but listened on another would not be able to traverse the firewall/NAT and establish connections. This issue has been resolved.	Y	Y	Y	Y	Y	Y	_	_	-	-	Y
CR00017077	Switching	2	Previously, switch port link up and link down events were not logged on: AR 750S/750s-DP. AR 570S, AR 415S and AR450S devices. This issue has been resolved.	Y	_	Y	_	_	_	_	_	-	-	_
CR00019099	ASYN	2	On AR44xS and AR415S routers, the AR024 4-port ASYN PIC would occasionally not configure correctly. When this occurred, parity errors were displayed in output from the show asyn=14 count command, even though the parity was set to none . Also, the issue could result in incorrect flow control or parity type settings. This issue has been resolved.	Y	_	_	_	_	_	_	_	_	_	_
CR00019424	Switching	2	Jumbo frame support would not be switched on for tri-speed ports when they were set to 100M. This issue has been resolved.	-	_	-	_	_	_	_	_	_	Y	_

CR	Module	Level	Description	AR44x/AR450S/AR415S	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00019985	VLAN	2	Under certain conditions, incorrect dynamic configuration Delete Vlan ?? Port=?? commands could be generated. This could occur when STP was enabled and ports were being removed from the default VLAN to another VLAN, then deleted from the Default VLAN. This issue has been resolved.	_	_	_	Y	Y	Y	Y	Y	Y	Y	-
CR00019991	SNMP	2	Previously, a corrupted SNMP request packet could cause the router or switch to reboot. This issue has been resolved.	_	_	_	_	_		_	Ι	_	-	Y
CR00020239	IPG	2	Previously, when encountering DNS responses which did not include a byte sequence to indicate whether standard or compressed DNS names were used, an unexpected system reboot could occur. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00020528	IPv6	2	Previously, enabling MLD on a specific interface caused a system reboot. This issue has been resolved.	Y	Y	Y	Y	Y	Y	-	-	Y	-	_
CR00020650	IPv4	2	Previously, the hardware switching view of the default route could become inconsistent and direct packets to be switched by the CPU rather than being hardware switched even though the switching hardware knew the MAC address of the default route's next hop. This could result in high CPU usage and poor swithing performance or even packet loss. This issue has been resolved. A software audit can now be enabled to detect and correct this situation.	_	_	_	_	_	_	-	_	Y	-	-
CR00020787	STP	2	Previously, if a port was in a rapid mode STP instance that was disabled, on boot the port's STP state would be incorrectly set to Blocking/Listening. This issue has been resolved.	-	-	-	_	_	_	-	_	Y	Y	Y

CR	Module	Level	Description	AR44x/AR450S/AR415S	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00021075	OSPF	2	Previously, when the switch was running OSPF and was not the designated router on a network, and an interface went down, any routes to destinations that had next hop addresses over that interface were marked as unavailable for the length of the router dead interval (default 40 seconds) before transitioning over to the alternative. This has been resolved - the alternative routes will now be selected within 5 seconds of the interface going down.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00021278	Firewall	2	Previously, firewall proxies would not close TCP connections correctly in some circumstances, leading to the connection being closed with a RESET. This would leave the connection closed as expected but the RESET could lead to problems in some applications. This issue has been resolved.	Y	Y	Y	Y	Y	Y		_	_	_	Y
CR00022019	IPv6	2	The returned value of protocol in show log when an IPv6 ESP packet has undergone filtering was previously incorrect. This issue has been resolved.	Y	Y	Y	Y	Y	Y	_	_	Y	Y	Y
CR00022191	Firewall	2	When a TCP connection was being established through a firewall from a public interface to a private interface, then the Maximum Segment Size (MSS) option transmitted in the SYN packet towards the destination from the firewall was set to the default of 536, even if the originating end sent a value greater than 536 and if the interface from the firewall towards the terminating host was capable of supporting packets greater than 536 bytes of TCP data. This prevented establishing a connection to certain hosts on the private side of the firewall. This has been changed so that the MSS value is selected to be the smaller of the incoming MSS in the SYN packet from the originator and the maximum value supported by the outgoing interface. This now conforms to RFC 1122 and RFC 1191.	Y	Y	Y	Y	Y	Y	_	_	_	-	Y

CR	Module	Level	Description	AR44x/AR450S/AR415S	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00022213	IPG	2	Previously, when the switch filter was configured to discard packets destined for a particular MAC address, then ARP messages for this same MAC address was being accepted, incorrectly resulting in an ARP entry. This issue has been resolved. Now the ARP is ignored in this case.	_	_	_	-	Ι			I	Y	Y	_
CR00022220	VRRP	2	 Previously, VRRP did not perform correct IP address validation. 1) VRRP would only check the network address of an IP interface against the classic ABC netmasks instead of the actual netmask that was in use on the interface. 2) It was not possible to configure VRRP with an IP address that belonged to an interface configured with a /31 netmask. These issues have been resolved. 	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00022461	BGP	2	Previously, if BGP on the switch was not configured to accept route refresh messages and it received a route refresh message from another BGP peer, the device would restart. This issue has been resolved.	Y	Y	Y	Y	Y	Y	_	_	Y	Y	Y
CR00022641	IKMP IPSEC	2	Previously, when specifying an isakmp/ipsec policy peer which included a subnet prefix (for example 192.168.1.1/16), the peer would be interpreted incorrectly as a hostname. This has now been resolved. Specifying a peer as 192.168.1.1/16 (which addresses a subnet) will be interpreted as 192.168.1.1. The trailing /16 is stripped, leaving a valid IP.	Y	Y	Y	Y	Y	Y	_	_	_	-	-
CR00022693	IPv6	2	Previously the show ipv6 mld and show ipv6 mld interface commands would not show a source in a group's source list if that source had a source timer value greater then zero. This has been changed to show all source information for the group, regardless of the timer value on each source.	Y	Y	Y	Y	Y	Y			Y	Y	Y

CR	Module	Level	Description	AR44x/AR450S/AR415S	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00022695	IPv6	2	Previously, a group record would not switch the filter mode to INCLUDE when the last listener in EXCLUDE mode left.	Y	Y	Y	Y	Y	Y	_	_	Y	Y	Y
			This issue has been resolved.											
CR00022771	PIM∨6	2	Previously, the commands show pim6 and show pim6 route could generate a system reboot when trying to index the IPv6 interface.	Y	Y	Y	Y	Y	Y	_	_	Y	Y	Y
			This issue has been resolved.											1
CR00022807	IPv6 PIM6	2	Previously, the router did not refresh its (S,G) group expire timer although the router received the join message to (S,G) in source specific MLDv2 include mode. This issue has been resolved.	Y	Y	Y	Y	Y	Y	I	_	Y	Y	Y
			The router software has been altered to maintain the (*.G) interfaces when an (S,G) interface exists.											
CR00024116	IPv6	2	Previously, modification of an interfaces link MTU value as a result of the reciept and processing of a 'Too Big' message, would cause a SET IPv6 MTU command entry in the output of the dynamic configuration. This issue has been resolved.	Y	Y	Y	Y	Y	Y	_	_	Y	Y	Y
CR00024443	IPv6	2	Previously, when IPv6 on a PPP interface was disabled on the AR415S router, then the PPP interface was destroyed, a subsequent show ipv6 interface command would result in an unexpected restart. This issue has been resolved.	Y	Y	Y	Y	Y	Y	_	_	Y	Y	Y
CR00024527	Switching	2	Previously, multicast traffic arriving on an interface that differed from that specified in the multicast route entry ,would fail the reverse path forwarding check and be dropped on i-series switches (8948i, Raptor-i), instead of being switched at Layer- 2, as in the non-i series switches. This issue has been resolved.	_	_	_	_	_	_		_	Y	_	

CR	Module	Level	Description	AR44x/AR450S/AR415S	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00024687	OSPF	2	Previously, improper router fast memory buffer management could lead to a system reboot.	Y	Y	Y	_	-	-	-	_	-	-	-
			This issue has been resolved.											
CR00024726	LLDP	2	Previously, if an LLDP management address had been set and the configuration saved, that management address would not be saved. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00024751	IPsec	2	Previously, when an IPsec SA tunnel via NAT router by NAT Traversal was set up, the TOS value in IP header of ESP packet was set to a random value during translation. This issue has been resolved.	Y	Y	Y	Y	Y	Y	_	_	-	_	-
CR00024756	Firewall	2	Previously, when the firewall code was performing Network Address Translation it randomly selected a TCP port number for use on the public side of the firewall. It was found that in rare cases when a particular one of the approximately 60000 possible port numbers was selected and in use for a session, all subsequent session initiations would fail until the particular session was terminated or timed out. This issue has been resolved.	Y	Y	Y	Y	Y	Y	_	_	_	_	Y
CR00024939	BRG	2	The router failed to bridge VLAN tagged packets, with the VLAN tag intact, via Ethernet ports, even if the stripvlantag parameter was set to no . This issue has been resolved.	Y	_	-	_	_	_	_	_	-	_	_
CR00024987	ENCO	2	In rare circumstances the encoding or decoding of large (>1600 byte) SSH packets could cause a router reboot. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00025032	IPv6	2	Previously, when IPv6 routes were deleted a small memory leak could occur. This issue has been resolved.	Y	Y	Y	Y	Y	Y	_	_	Y	Y	Y

CR	Module	Level	Description	AR44x/AR450S/AR415S	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00025205	ICMP	2	If an ICMP tracert or TRACE command was executed across an unnumbered PPP link (IP=0.0.0.0) then tracert would timeout because the returned message source address was 0.0.0.0. This issue has been resolved with the router returning the Local IP address. If this is not set then the router returns the IP address of the interface the ICMP message was received on. If this is set to 0.0.0.0 then the first non-zero IP address found on the router is used.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00025305	MSTP	2	Previously, disabling all ports on a device, that were taking part in MTSP, could make the device reboot when the ports were re-enabled. This issue has been resolved.	-	_	-	Y	Y	Y	Y	_	Y	Y	-
CR00025348	Switching	2	Previously, when the commands add swi hwfilter or show swi hwfilter were used in, some circumstances memory would leak. This issue has been resolved.	-	_	_	_	_	_	_	_	_	Y	-
CR00025362	Firewall	2	Previously when an FTP control connection was being passed through a firewall doing NAT and the client closed the connection with an RST flagged packet (rather than the usual FIN flag), then the sequence or acknowledgment number in the packet could be incorrect. This issue has been resolved.	Y	Y	Y	Y	Y	Y	_	_	_	_	Y
CR00025371	Switching VLAN	2	Previously, when an ARP was to be switched or flooded, it was possible to send out two ARPs for every ARP that was received. This issue has been resolved.	-	_	-	_	_	_	_	_	Y	Y	-

CR	Module	Level	Description	AR44x/AR450S/AR415S	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00025396	IPG DHCP Snooping	2	Previously, if an IP interface had its Proxy ARP setting set to local and the device received a gratuitous ARP, the device would respond to that gratuitous ARP with the same address information. That would cause the host that initiated the gratuitous ARP to detect duplicate IP addresses on the network. This has been resolved so that the deivce will not reply to gratuitous ARPs in this situation.	-	_	_	Y	Y	Y	Y	Y	Y	Y	Y
CR00025482	РКІ	2	Previously, PKI certificates that contained UTF-8 strings were being misread and would not authenticate. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00025615	Switching	2	The mechanism to detect activity on a multicast route has been changed to a hardware based one from a software based one. This prevents occasional high CPU usage in environments with large numbers of multicast routes.	-	-	_	-	_	_	_	_	Y	Y	_
CR00025859	DHCP Snooping	2	Previously, DHCP Snooping was unable to process the DHCP messages because of an incorrect calculation of the protocol identifier. This issue has been resolved.	-	_	_	Y	Y	Y	Y	Y	Y	Y	Y
CR00025888	SCC	2	Previously, in rare circumstances when a PPP over SYN link partner was disabled and re-enabled the SYN interface would enter a mode where received packets were significantly delayed by the hardware, causing the PPP not to open. This issue has been resolved.	Y	Y	Y	Y	Y	_	_	_	_	_	_
CR00025916	Switching	2	Previously, on the SB 4000, it was not possible to clear a port description by issuing the command set swi po= . This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR44x/AR450S/AR415S	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00025920	IKMP PKI	2	 An ISAKMP negotiation would not authenticate if the client certificate contained an email address or domain components in its subject field. An ISAKMP negotiation would cause the router to crash if the client certificate had more than 8 attributes in its subject field. This has been resolved. Also the limit has now been raised to 16. Note that certificates with more than 16 attributes in their subject field will not authenticate. The display of subject and issuer fields in certificates would be truncated in the output of the show pki cert=ccc command. The fields output in the show isakmp policy command would not be aligned with the field headings. 	Y	Y	Y	Y	Y	Y	_	_	_	_	
CR00025929	DHCP Snooping	2	Previously, while a classifier was being created, if the user specified a source IP address of dhcpsnooping , although it was then possible to specify a destination IP, this IP address was not added to the classifier, nor was the dynamic configuration updated. Note this issue effected Marvell devices only. This issue has been resolved.	_	_	_	_	_	_		_	Y	Y	
CR00025968	OSPF	2	Previously, OSPF would not recover from adding and withdrawing a large number of LSAs.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00025970	OSPF	2	Previously, a broadcast storm of OSPF Hello messages could exhaust the free memory on the switch. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00025984	BGP	2	Previously, the switch did not correctly handle overflowing BGP AS path segments. This has now been corrected and the BGP path overflow is handled as recommended in RFC4271, section 5.1.2 b) 1) and RFC 5065, section 4.1 b) 1) for confederation peers.	Y	Y	Y	Y	Y	Y	_	_	Y	Y	Y

CR	Module	Level	Description	AR44x/AR450S/AR415S	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00026031	OSPF	2	Previously, if an interface of an OSPF Designated Router failed which carried either all or a significant portion of the OSPF interfaces defined on the system, then the DR may have ended up retransmitting the Network LSAs it originally generated ad infinitum with its neighbours OR the recovery could result in no response at the terminal and eventually a system reboot if many routes were affected. This issue has been resolved.	Y	Y	Y	Y	Υ	Υ	Y	Y	Y	Y	Y
CR00026197	L2 switching	2	The mechanism for switch FDB entry aging can now be configured by a command set swi ageingcontrol . The default is hardware based ageing. The user can change this to CPU based ageing if required. NOTE : It is strongly recommended not to change this setting unless advised to do so by Allied Telesis technical support.	_	_	_	_	_	_	_	_	Y	_	_
CR00026239	OSPF	2	Previously, some OSPF links were not successfully updated when device was also configured with VRRP. Now all OSPF routes are updated correctly when used with VRRP.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00026290	PKI	2	A System Distinguished Name (DN) with more that seven elements would cause the device to reboot if a certificate enrollment request was created. This issue has been resolved. The limit has been raised to 16 elements in the DN. If more than 16 elements are present the resulting certificate will not authenticate.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00026609	Load Balancing	2	Previously, WAN Load Balancing would not allow ATM interfaces to be configured as resources. This issue has been resolved.	Y	_	-	_	_	_	_	_	_	_	_
CR00020651	ENCO	2	If an ENCO channel was destroyed while processing a packet, the switch would reboot. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR44x/AR450S/AR415S	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00021163	DHCP snooping	2	DHCP Snooping ARP Security should discard an ARP if the source MAC address in the Ethernet frame's MAC header does not match the sender hardware address in the ARP packet, but previously did not discard these. This issue has been resolved.	_	_	_	Y	Y	Y	Y	Y	Y	Y	Y
CR00021651	DHCP snooping	2	When using DHCP Snooping ARP Security, maliciously formed ARPs destined for a unicast address would not be discarded. This issue has been resolved.	_	-	_	Y	Y	Y	Y	Y	Y	Y	Y
CR00021664	IPG	2	The device would eventually reboot when utilising Jumbo packets (~9000 bytes) on ICMP echo request messages. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00021693	IPG	2	If a Jumbo packet was received at the CPU for forwarding, the device would reboot. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

Level 3

CR	Module	Level	Description	AR44x/AR450S/AR415S	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00008752	Mirroring	3	If you enabled switch mirroring before setting the switch mirror port, when you set the mirror, port mirroring would not occur until you enable mirroring again. This issue has been resolved.	_	_	-	_	_	_	-	-	_	-	Y

CR	Module	Level	Description	AR44x/AR450S/AR415S	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00013401	Switching	3	Previously, the command to create a trunk group on the switch was not checking to see if ports could be added to the trunk group. This issue has been resolved.	-	_	_	-	-	_	_	_	Y	Y	_
CR00013572	IPG	3	Previously, the first ICMP request on an AT-9924T switch could fail. This issue has been resolved.	-	_	_	_	_	_	_	_		Y	_
CR00016701	DHCP	3	Previously, when entering the show DHCPSnooping database command on an AT-9924SP, an incorrect lease expiry date was shown for DHCP Servers with a lease expiry of infinity . This issue has been resolved.	-	_	_	_	_	-	_	_	_	Y	_
CR00019319	Switching	3	Previously, when entering the show switch register=all command, some low level register information for registers that didn't exist in that hardware configuration could cause the system to reboot. This issue has been resolved.	-	_	_	_	_	-	_	_	Y	Y	_
CR00019647	QoS	3	 Previously: after a purge qos purge command was issued, the show swi trunk command would still show QoS policies that had been linked to trunk groups. The same problem occurred when the destroy qos policy=<> (or all) command was issued, with the affected policies still being displayed in trunk group information. after a purge qos command was issued, any existing port group configuration infomation would remain. QoS port groups associated associated with a port would not be displayed by the show qos port=<> command if there was no QoS policy associated with the port. Now, policy group information is now always displayed if a port is part of a group. These issues have been resolved. 	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR44x/AR450S/AR415S	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00021320	EPSR, RSTP	3	It was not possible to dynamically add VLANs on a EPSR ring port if the switch was running RSTP. VLANs could only be added by editing the boot configuration script and restarting the switch. This issue has been resolved.	_	_	_	Y	Y	Y	Y	Y	Y	Y	Y
CR00021848	ETH	3	Previously, the AR-770S router would show high CPU usage values if the ETH interface was brought down when traffic was being forwared out of the interface. This issue has been resolved.	_	_	Y	_	_	_	_	_	-	_	-
CR00022178	IPv6	3	IPv6 Routing Header Type 0 (RH0) processing is deprecated and has been disabled by default, for interoperability with older IPv6 implementation, RH0 processing maybe enabled by using the command enable ipv6 rh0processing . To disable RH0 processing, use the command disable ipv6 rh0processing . When RH0 processing is enabled from the command line interface, a warning indicating that the use of RH0 is deprecated and the device might be succeptible to DOS attack is printed - to remind users that this feature should only be used in full caution.	Y	Y	Y	Y	Y	Y	_	_	Y	Y	Y
CR00022995	Firewall HTTP TCP	3	Previously, if http proxy was configured in the router firewall configuration then the packets passed through the http proxy checking were re-originated and sent directly out on the public interface, therefore potentially ignoring other firewall rules designed to act on the IP address of the private interface from which the packets were received. This issue has been resolved. A method of configuring http proxy has been made possible so that packets can have both http proxy and subsequent firewall rules apply in sequence.	Y	Y	Y	Y	Y	Y	_	_	_	_	Y

CR	Module	Level	Description	AR44x/AR450S/AR415S	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00023417	ISAKMP IPSec	3	Previously, if either IPSec or ISAKMP policies specified peers using DNS names, then a single packet sent across the connection, where the connection had not yet been set up, failed to establish the connection. Multiple packets are required before the connection is established. This is in contrast to the case where peers are specified using fixed IP addresses where is a single packet is sufficient. This has been resolved and these two configurations now work in the same way.	Y	Y	Y	Y	Y	Y	_	_			-
CR00023452	Firewall	3	Previously, an inbound multicast event in the firewall module would be logged as outgoing. This issue has been resolved.	Y	Y	Y	Y	Y	Y	_	_	_	- Y	1
CR00024025	КМР	3	An ISAKMP policy can be specified in the create ipsec policy command. Previously, the IPsec tunnel was not created when the ISAKMP policy's peer was specified with an IP and the IPsec policy's peer is specified with a peer dns name. Also, previously, if both the ISAKMP and IPsec policy specified their peers using an IP address, AND the isakmppolicy parameter had been specified in the create ipsec policy command, the 2 policies would be considered a match when the two IP addresses differed. These issues have been resolved. (This error has not been seen in the field)	Y	Y	Y	Y	Y	Y	_	_	_		
CR00024117	ΙΡν6	3	Previously, the dynamic updating of the IPv6 inteface AdvCurHopLimit field as the result of the recipt of a Router Advertisement would result in the output of show conf dyn=ipv6 being modified. Specifically, the set ipv6 nd int=<> hop=<> 'hop' parameter would show the modified value, rather than that configured by the user. This issue has been resolved.	Y	Y	Y	Y	Y	Y	_	_	Y	YY	·

CR	Module	Level	Description	AR44x/AR450S/AR415S	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00024315	IPhelper	3	Previously, telnetting to the router's public IP address resulted in a telnet session to the router, not the other host. This issue has been resolved.	Y	Y	Y	Y	Y	Y	_	-	-	-	Y
CR00024347	IPv6	3	Previously, if an IPv6 ping was given a length of 1445 - 1452 bytes, there would be no reply through an intermediary router. This issue has been resolved.	Y	Y	Y	Y	Y	Y	_	_	Y	Y	Y
CR00024476	IPsec	3	An IPSec policy attached to an unnumbered PPP interface would display its local IP address as that of the first non-zero IP address found on the router before the PPP interface had received its IP address from its peer. It would then change to that received from its peer once this had been received. If the IPSec module was disabled at the time PPP received its IP address, it would never be updated. This issue has been resolved. The IPSec policy now displays not set before an unnumbered PPP receives its IP address, which changes to the correct IP address once received, regardless of whether the IPSec module is enabled or disabled.	Y	Y	Y	Y	Y	Y	_	_	_	-	_
CR00024497	FRAME RELAY	3	Previously, when the Frame Relay default encapsulation was configured to "CISCO", a dynamically learned DLCi would randomly insert "IETF" encapsulation into the dynamic configuration. This could result in a communication problem with the router. This issue has been resolved.	Y	Y	Y	Y	Y	_	_	-	_	_	_
CR00024573	VLAN	3	Previously, with DHCP Snooping enabled it was the expected behaviour that all messages that failed to meet various criteria would be dropped. In some circumstances a spoofed ARP message was passed onto an upstream device. This issue has been resolved.	_	_	-	Y	Y	Y	Y	Y	Y	Y	_

CR	Module	Level	Description	AR44x/AR450S/AR415S	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00024608	Trigger	3	Previously, the create trigger module = [module id] command would fail if more than one script parameter was entered. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Υ	Y
CR00024621	DHCP Snooping	3	Previously, the switches ingress bandwidth filtering and dhcpsnooping would not co-exist. More specifically, adding dhcpsnooping would break ingress bandwidth filtering. This issue has been resolved.	_	_	_	Y	Y	Y	Y	Y	-	_	_
CR00024671	IPv6	3	Previously, a router configured as an MLD router that was not elected as the querier on the network, would use its own timeout values to calculate the timeout of the All Routers group rather than those received from the querier. This issue has been resolved.	Y	Y	Y	Y	Y	Y	_	_	Y	Y	Y
CR00024738	IPv6	3	Previously, if an MLD Group and Source Specific Query was generated with a large number of sources that packet may have been larger than the MTU of the interface it was to be transmitted on. This could cause the packet to be transmitted in a corrupted manner. This issue has been resolved.	Y	Y	Y	Y	Y	Y	_	_	Y	Y	Y
CR00024741	GUI	3	Previously, the MAC Based Authentication menu item was missing from the AT- 8624T/2M's GUI. This issue has been resolved.		_	_	_	_	_	Y	_	-		_
CR00024750	IPsec	3	Previously a peer address could be specified for an IPSec of ISAKMP policy with a subnet prefix. Since a peer address should only specify a single host, this didn't make sense. This has been resolved by generating an error message if a subnet prefix is supplied.	Y	Y	Y	Y	Y	Y	_	_	-	_	

CR	Module	Level	Description	AR44x/AR450S/AR415S	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00024863	IPv6	3	Previously, when an IPv6 IPSec selector was specified as any , an ipv4_addr_subnet string was transmitted in the packet when it should have be an ipv6_addr_subnet string. This issue has been resolved.	Y	Y	Y	Y	Y	Y		l	-	_	
CR00025265	Firewall	3	Previously, when the firewall TCP handling code was operating with tcpsetupproxy disabled and the public side resent a TCP Syn message, then the message's checksum was not being adjusted before being forwarded to the private side. This issue has been resolved.	Y	Y	Y	Y	Y	Y	_	_	-	_	Y
CR00025266	Firewall IPG IPSEC PPP TCP	3	An MSS Clamping option is configurable for PPPoE interfaces. The MSS Clamping option is designed to reserve space in the packet for the expansion of packet size due to headers created by the various protocol layers. This it specifically to avoid the resulting packet growing to such a size that fragmentation is required. Previously, if a router was operating as an IPSEC endpoint, and a firewall, on a PPPoE public interface, then, for TCP sessions going through this interface, the TCP Maximum Segment Size set in the packets did not respect the MSS Clamping value set on the PPPoE interface. This issue has been resolved. The TCP MSS is now set correctly within TCP packets, so avoiding fragmentation of the packets.	Y	Y	Y	Y	Y	Y	_	_	_	_	_
CR00025385	Firewall	3	Previously, ENAPT type NAT entries were not being deleted correctly from the command line. This issue has been resolved.	Y	Y	Y	Y	Y	Y	_	_	_	_	Y
CR00026185	Portauth	3	The output of the show portauth=8021x and show portauth=mac displaying the number of (Multi) Supplicants and the port numbering was different from the documentation. This issue has been resolved.	_	_	_	_	_	Y	_	_	_	-	

CR	Module	Level	Description	AR44x/AR450S/AR415S	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00026264	ARP	3	After deleting the subnet VLAN association from a port, the port still had a port based VLAN association. Now, subnet based VLANS work correctly.	-	_	_	_	-	-	-	_	Y	Y	_
CR00026389	Core	3	The switch fan has been made quieter.	-	_	-	-	-	Y	-	-	-	-	-
CR00026581	Secure Shell	3	Previously, the SSH server failed to correctly receive a message bigger than 1584 bytes and the client could prematurely close the session due to not receiving a correct response to the message. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00026626	OSPF	3	Previously, when using the command show ospf neighbour full after OSPF had been disabled, and the neighbour had been manually configured, the switch could undergo a system reboot. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00026631	OSPF	3	Previously, when the network type of an OSPF interface was changed from broadcast to a non-broadcast interface type or the OSPF interface was disabled, duplicate timers would appear or the timers would not be stopped when they should have been stopped. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

Level 4

CR	Module	Level	Description	AR44x/AR450S/AR415S	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00021066	LED	4	Previously, the AR7x5 routers security LED light would light up when a security user logged in, however when they logged out the LED light would remain lit. This issue has been resolved. The light now will turn off when the last security user logs out of the device.	_	Y	_	_	_	_	_	_	_		-
CR00024181	IPv6	4	Previously, in some cases the device may have incorrectly transmitted an MLD version 2 source specific query containing no source addresses. This issue has been resolved.	Y	Y	Y	Y	Y	Υ	Ι	_	Y	Y	Y
CR00025271	КМР	4	Previously, if ISAKMP debugging was turned on, IPv6 peer addresses were incorrectly displayed as IPv4 addresses. Also, ISAKMP policy debug output did not include the policy name. These issues have been resolved.	Y	Y	Y	Y	Y	Y	1	_	Y	Y	Y
CR00014252	DDNS	4	The ? help output for the command set ddns port=? displayed 0 to 65535 as valid values. In fact, the only valid values are 80 or 8245 for HTTP and 443 for HTTPS. This issue has been resolved so that the ? help output is correct.	Y	Y	Y			_	_		_		-

Enhancements

CR	Module	Level	Description	AR44x/AR450S/AR415S	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00023375	Firewall	-	See "Firewall Public Interface Dynamic Assigned IP Address (CR00023375)" on page 26	Y	Y	Y	Y	Y	Y	-	-	-	-	Y
CR00023463	IPv6	-	A new feature has been addded, MLD Proxy. This feature allows the router to be configured as a simple proxy device to forward multicast traffic. It performs the host portion of the MLDv2 protocol on a single upstream interface and the router portion of the MLDv2 protocol on a number of downstream interfaces. The implementation is as per RFC 4605.	Y	Y	Y	Y	Y	Y	_	_	Υ	Υ	Y
CR00025844	dhcp, portauth, MIBs	-	Project 1089: SNMP MIB Enhancement. See "Support for SNMP MIB (CR00025844)" on page 27	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00026520	Log	-	New functionality has been added to the log modules syslog functionality. It is now possible to to specify a startup delay period which has the effect of delaying the transmission of syslog messages. This has been implemented in order to allow for syslog servers that are connected via routing protocols (e.g. OSPF, BGP) that may take some time to negotiate network paths at startup. The user can specify the time to wait (DELAY) before sending log messages generated at device startup, and the the number of messages to save (MESSAGES) for transmission when the delay period has expired. New command: SET LOG SYSLOG DELAY= ?? MESSAGES=?? See "Logging Facility (CR00026520)" on page 26	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR44x/AR450S/AR415S	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00026718	Port Auth	-	It is now possible to configure a device such that when MAC based authentication sends a request for a MAC address to be authorised, the username and password (which are the MAC address) can now be formatted either with hyphens (i.e. 00-00-cd-12-34-56) or without hyphens, (ie. 0000cd123456).	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00020742	User Authenticat ion	-	This enhancement enables you to set rules for valid characters, lifetime, and history of passwords for user accounts in the User Authentication Database with manager or security officer privilege. These rules apply when connecting via Telnet or an asynchronous port and logging in to the command line interface, and you can apply the same rules to SSH clients by configuring SSH users to use passwords from the User Authentication Database. For more information and command details, see "User Authentication Database Password Enhancement (CR00020742)" on page 46.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00020926	DHCP Snooping	-	A new feature has been added to DHCP Snooping that allows a port to be disabled if DHCP Snooping ARP Security discards an ARP. To turn this feature on, use the command: set dhcpsnooping arpsecurity action=disable To turn it off, use the command: set dhcpsnooping arpsecurity action=none	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00026527	Switching	-	The Loop Detection and Protection enhancement serves as a fall-back feature so as to disable a port involved in a network loop in the event of failure of STP, or other higher layer protocol. See, "External Loop Detection and Termination Mechanism (CR00026527)" on page 61	_		_	Y	Y	Y	Y	Y	Y	Y	_

Firewall Public Interface Dynamic Assigned IP Address (CR00023375)

When a firewall public interface is being dynamically assigned an IP address, and therefore does not have pre-assigned ip address, and Enhanced NAT is defined on this interface, rules which specify global ip ({gblip}) normally set {gblip=0.0.0.0}. When the router learns the ip address of the interface then the {gblip} is set to this value and private traffic's source address is substituted with this value when it is sent out through the public interface.

If in a rule, the $\{ip\}$ address parameter is also specified, then incoming packets which match the rule are directed to the private interface which bears that IP address. If the desire is that traffic being allowed inwards is to terminate on the address of the public interface (but because the interface is being dynamically assigned its IP address, this address is not known at configuration time), then it is now possible to specify $\{ip=0.0.0.0\}$ in the rule. When both $\{gblip=0.0.0.0\}$ and $\{ip=0.0.0.0\}$ then packets received matching this rule will be terminated on the public interface ie: $\{ip\}=\{gblip\}=address of the public interface.$

Logging Facility (CR00026520)

New Log module feature for syslog. - Syslog Start-up Delay.

The Syslog sub feature of the logging facility has been enhanced to provide a functionality similar in concept to that of the SNMP features SNMP TRAP DELAY. The new 'feature' applies to ALL and ONLY log output definitions created (or set) with a destination of 'syslog' (e.g. create log out=1 dest=syslog server=172.20.133.1).

The feature applies only to log messages generated at device startup and allows the transmission of syslog log messages generated during device startup to be delayed. The intent is that syslog servers accessed via a link using a routing protocol such as OSPF will be able to receive device start-up log messages, even if the network path does not become available for some time. Currently such log messages are lost because they are transmitted before the network path comes up.

A new command SET LOG SYSlog {DELay= | MESSage=} allows the user to set:

DELAY: A delay time period (seconds).

Syslog messages will not be transmitted from the device until the specified delay has expired.

MESSAGES: The number of log messages to be saved for transmission after the DELAY period has expired.

In Summary

The AW device will save MESSAGES number of log messages for DELAY number of seconds. Then, the saved log messages will be transmitted to the specified syslog server and normal syslog behaviour will resume.

The command:

SET LOG SYSlog DELAY= {0-600 seconds} MESSages= {0-50 messages}

One or both of DELAY or MESSAGES parameters must be present on the command line. Setting DELAY to 0 disables the feature.

Support for SNMP MIB (CR00025844)

This software release includes support for the user interface and Simple Network Management Protocol (SNMP) Management Information Base (MIB) changes that will be introduced to facilitate the enhancements requested for the Tokyo Metropolitan Office.

The four main areas of enhancements include:

1. A Dynamic Host Configuration Protocol (DHCP) MIB trap, triggered on the IP address allocation of a DHCP range exceeding a specified threshold.

This is achieved via:

- a new parameter to set a threshold for DHCP pool address usage.
- an SNMP MIB trap sent to a specified server/NMS to inform it that the DHCP range address pool is about to be exhausted, when the number of leased IP addresses exceed the threshold.
- 2. Host Name logging to Syslog

Monitoring of the **hostname** parameter in the DHCP packet. A log message is sent to the syslog server when an IP address is leased. The log contains the following parameters:

- MAC address of the DHCP Client
- IP Address leased to the DHCP Client
- Lease Time allocated to the DHCP Client
- Port Number that the Client is connected on
- Management IP Address of DHCP server
- Name of DHCP Client

3. RADIUS Permit Mode (Authentication automatic invalidity function)

In a customer's network there are any number of configured RADIUS servers, either IEEE802.1x or MAC Based. If the switch loses contact with ALL RADIUS servers, users are automatically authenticated, bypassing the normal authentication procedures.

This is achieved via:

• a new parameter that will enable/disable the automatic authentication functionality.

When the Radius Permit Mode is enabled, the switch will indicate that the RADIUS permit mode is active and the log will contain the following parameters:

- Port Number that the supplicant is connected to
- User Name of the supplicant
- MAC address of the supplicant
- 4. Authentication-user Limit enhancement

Currently the authentication-user limit is 480/unit and 320/port. This has been increased to 480/unit and 480/port.

Modified Commands

Selective command descriptions are shown, with changes shown in bold.

The following commands have been modified to implement the requested **DHCP** functionality. These modified commands will be available on ALL devices:

- SET DHCP RANGE
- SHOW DHCP CLIENT
- SHOW DHCP RANGE

The following commands have been modified to implement the requested **authentication** functionality. These commands will only be available on the AT86 (Rapier) devices:

- ENABLE PORTAUTH PORT
- SET PORTAUTH PORT
- SHOW PORTAUTH PORT

SET DHCP RANGE

Syntax

SET DHCP RANge=name [PRObe={ARP | ICMP}] }] [THREshold={ENABLED | DISABLED}] [UPperthreshold=0..100] [LOWerthreshold=0..100] [LOG={ENABLED | DISABLED}]

Description

This command modifies the server's attributes.

The **probe** parameter specifies how the DHCP server checks whether an IP address is being used by other hosts. If arp is specified, the server sends ARP requests to determine if an address is in use. If ICMP is specified, the server sends ICMP Echo Requests (pings). The **default** is icmp.

Note that arp cannot be specified if the range includes a gateway (by specifying the gateway parameter when it was created), or if the network uses Proxy ARP.

The **threshold** parameter determines if an SNMP DHCP MIB trap is generated when the number of allocated IP addresses from a particular range pool exceeds a pre-defined threshold. The **default** setting for this parameter is disabled.

The **upperthreshold** parameter specifies at what percentage of utilised client addresses the SNMP MIB trap should be generated. The **default** is 80% of IP addresses allocated from a particular range pool. The upper threshold value must be equal to or greater than the lower and vice-versa.

The **lowerthreshold** parameter specifies at what percentage of utilised client addresses that the threshold breach is considered to have cleared itself. No trap will be generated to indicate that the condition has been cleared. The SHOW DHCP RANGE command will display the threshold status. The **default** is 75% of IP addresses allocated from a particular range pool.

The **log** parameter specifies whether or not to enable logging of the DHCP clients login. This may generate a lot of log messages depending on refresh timers and clients. The **default** setting for this parameter is enabled.

Example

To set the range office to use ARP packets to probe IP addresses, an upper threshold of 70% and a lower threshold of 65%, use the command:

set dhcp range=office pro=arp thre=ena up=70 lo=65 log=dis

Related commands add dhcp range create dhcp range delete dhcp range destroy dhcp range

SHOW DHCP CLIENT

Syntax

SHow DHCP CLIEnt[=ipaddress] [RANge=name] [DETail]

Description

This command displays information about the currently defined range client entries.

If the range parameter is specified, then the clients in the specified range are displayed.

If an IP address is specified on the client parameter, then information for that IP address is displayed.

If the detail option is supplied then extra information about the clients is displayed.

Parameter details are contained in Table 1 Parameters in output of the SHOW DHCP CLIENT command on page 31.

Details of the show command are shown in Figure 1 Example output from the SHOW DHCP CLIENT command on page 31 and Figure 2 Example output from the SHOW DHCP CLIENT DETAIL command on page 32.

Examples

To display detailed information about the clients in a range named **remote**, use the command:

sh dhcp clie ran=remote **det**

Related commands show dhcp show dhcp policy show dhcp range

Table 1: Parameters in output of the SHOW DHCP CLIENT command

Parameter	Meaning					
Show DHCP C	Show DHCP CLIENT					
IP Address	IP address from the range of available IP addresses.					
ClientId Hardware address of the client, if any, that has been assigned the IP address						
State	State of the IP address:					
	Unused - not currently in use and is available for assignment					
	Inuse - currently assigned to a client					
	Reclaim - currently being reclaimed					
Expiry	Date for dynamically allocated IP addresses.					
Hostname	The host name of the client as supplied in the DHCP Request message.					
	Note that by default the Hostname of the client comes from the system name (SET SYS NAME) and as such has a possible length of 255 characters on the client machine. We have restricted the length of the name we record to 64 characters.					

Figure 1: Example output from the SHOW DHCP CLIENT command

DHCP Client IP Address	Entries ClientI	d	State	Туре	Expiry	
202.36.163.2 202.36.163.2 202.36.163.2 202.36.163.2 192.168.100 192.168.100	4 00-00-c 20 08-00-5 23 28 00-40-1 92 00-00-c 93 118	0-00-00-01 a-a1-02-3f 0-02-e8-a3 0-c9-c6-21	unused inuse unused inuse inuse unused reclaim	static auto auto dyn dyn dyn dyn	never never never never 19-Jun-1997	12:30:51

31

Figure 2: Example output from the SHOW DHCP CLIENT DETAIL commandSHOW DHCP RANGE

DHCP Client Entr IP Address	cies ClientId Host Name	State	Туре	Expiry
202.36.163.14	00-00-c0-00-00-01	unused	static	never
202.36.163.20	08-00-5a-a1-02-3f	inuse	auto	never
202.36.163.23		unused	auto	never
202.36.163.28	00-40-10-02-e8-a3	inuse	auto	never
192.168.100.92	00-00-c0-c9-c6-21	inuse	dyn	19-Jun-1997 12:30:51
192.168.100.93	DHCP Client	unused	dyn	
192.168.100.118		reclaim	dyn	

Syntax

SHow DHCP RANge[=name]

Description

The format of this command is unchanged. The command output has been enhanced to display detailed threshold and **client usage** information.

The details of the new display information are detailed in Table 2 Parameters in output of the SHOW DHCP RANGE command on page 33.

Examples of the new output are detailed in Figure 3 Example output from the SHOW DHCP RANGE command on page 35.

Table 2: Parameters in output of the SHOW DHCP RANGE command

Parameter	Meaning				
Show DHCP RANGE	- "CLIENT INFORMATION"				
Number In Range	The number of clients configured for this range.				
Number Allocated	The number of clients actually allocated from this range and in the inuse state.				
Percentage Allocated	The percentage of inuse clients against the clients configured. Note that this is only the inuse clients, not the reclaim or unused clients.				
Logging Status	The logging of client connections may be enabled or disabled on a per range basis. This field will display the logging status for this particular range and will display enabled or disabled.				
Show DHCP RANGE	- "SNMP MIB THRESHOLD INFORMATION"				
Status	This field will display the status of the threshold functionality - enabled or disabled. This will determine if the SNMP DHCP MIB trap is raised when the IP address allocation upper limit threshold has been exceeded.				
Upper Limit	The upper client allocation threshold for Percentage Allocated . When this limit is exceeded the device will generate an SNMP DHCP MIB trap.				

Table 2: Parameters in output of the SHOW DHCP RANGE command

Parameter	Meaning
Lower Limit	The lower client allocation threshold for Percentage Allocated . This is the value at which the threshold exceed condition is considered to be cleared. It is to stop any hysteresis in the system where the number of clients hover around the upper threshold and generate multiple traps as it rises above and drops below the threshold. Note that there is no SNMP MIB trap generated when the condition is cleared.
SNMP MIB Trap Status	When the Percentage Allocated exceeds the Upper Limit an SNMP DHCP MIB trap will be generated. This field will then display RAISED. When the Percentage Allocated drops below the Lower Limit the condition is declared to be cleared and the field will display LOWERED. No SNMP DHCP MIB trap will be generated when the condition is cleared.

Figure 3: Example output from the SHOW DHCP RANGE command

Manager DHCP Server> sh dhcp range=range2					
Name: range2 Policy Probe Type Start Address End Address Reclaim status Used Address(es) Free Address(es)	centrecom ICMP 192.168.2.100 192.168.2.104 Stopped 192.168.2.101 192.168.2.100 192.168.2.102				
Reclaiming Address(es)In DHCP MessagesIn Discover MessagesIn Request MessagesIn Decline MessagesIn Release MessagesOut DHCP MessagesOut Offer MessagesOut Ack MessagesOut Nak MessagesIn BOOTP MessagesOut BOOTP Messages	none 268 1 267 0 268 1 267 0 0 268 1 267 0 0 0				
Client Information: Addresses In Range Addresses Allocated Percentage Allocated Logging Status SNMP Threshold Information: Status Upper Limit Lower Limit SNMP MIB Trap Status	5 1 20 ENABLED 19 10 RAISED				

ENABLE AND SET PORTAUTH PORT

Syntax

```
ENAble PORTAuth[=8021x] POrt={ALL|switch-port}
TYpe=Authenticator CONTrol={AUTHorised|AUTO|
UNauthorised}] [MAXReq=1..10] [MODe={MUlti|SIngle}]
[PIGgyback={TRue|FAlse}] [QUIETperiod=0..65535]
[REAUTHENAbled={TRue|FAlse}] [REAUTHMax=1..10]
[REAUTHPeriod=1..86400] [SERVERTimeout=1..60]
[SUPPTimeout=1..60] [TXperiod=1..65535]
[GUEstvlan={1..4094|vlan-name|NONe}] [SECurevlan={ON|
OFF}] [VLANAssignment={ENAbled|DIsabled}]
[MIBReset={ENAbled|DIsabled}] [TRap={SUCcess|FAILure|
BOTh|NONe}] [AUTOAuthenticate={TRUE|FALSE}]
```

- SET PORTAuth[=8021x] POrt={ALL|switch-port} TYpe=AUthenticator [CONTrol={AUTHorised|AUTO|UNauthorised}]
 [MAXReq=1..10] [MODe={MUlti|SIngle}][PIGgyback={TRue|FAlse}] [QUIETperiod=0..65535][REAUTHENAbled={TRue|FAlse}]
 [REAUTHMax=1..10][REAUTHPeriod=1..86400] [SERVERTimeout=1..60][SUPPTimeout=1..60] [TXperiod=1..65535]
 [GUEstvlan={1..4094|vlan-name|NONe}] [SECurevlan={ON|OFF}] [VLANAssignment={ENAbled|DIsabled}]
 [MIBReset={ENAbled|DIsabled}] [TRap={SUCcess|FAILure|BOTh|NONe}] [AUTOAuthenticate={TRUE|FALSE}]
- ENAble PORTAuth=MACbased POrt={ALL|switch-port} [CONTrol={AUTHorised|UNauthorised|AUTO}][REAUTHENAbled={TRue|FAlse}]
 [REAUTHPeriod=1..86400] [QUIETperiod=0..65535] [SECurevlan={ON|OFF}] [VLANAssignment={ENAbled|DIsabled}]
 MIBReset={ENAbled| DIsabled}] [TRap={SUCcess|FAILure|BOTh|NONe}] [AUTOAuthenticate={TRUE|FALSE}]
- SET PORTAuth=MACbased POrt={ALL|switch-port} [CONTrol={AUTHorised|UNauthorised|AUTO}] [REAUTHENAbled={TRue|FAlse}]
 [REAUTHPeriod=1..86400] [QUIETperiod=0..65535] [SECurevlan={ON|OFF}] [VLANAssignment={ENAbled|DIsabled}]
 [MIBReset={ENAbled|DIsabled}] TRap={SUCcess|FAILure|BOTh|NONe}] [AUTOAuthenticate={TRUE|FALSE}]

Description

The ENABLE PORTAUTH and SET PORTAUTH commands have been amended to incorporate a new automatic authentication value - AUTOAuthenticate.

Ordinarily, a user attempts to gain authorisation to join a network by passing certain criteria via an authenticating switch to a RADIUS authentication server. When the RADIUS server is unavailable then all supplicants will be unable to connect to the network as this is deemed a failure to authenticate by the authenticating switch.
Multiple RADIUS servers can be configured (ADD RADIUS). When communication with all RADIUS servers (1-n) is lost then this command will provide the opportunity for the customer to automatically authenticate all users requesting access to the network. The **default** value of this field is FALSE.

SECURITY NOTE: this command exposes the customer to a high degree of vulnerability. When the RADIUS servers return to operational status the clients automatically authenticated will remain authenticated.

Note that there is functionality in the PORTAUTH (SET PORTATUH REAUTHENABLE and REAUTHPERIOD) that will re-authenticate users after a certain timeout period. This functionality is disabled by default and it is recommended that this functionality is enabled in conjunction with the automatic authentication functionality.

The AUTOAuthenticate parameter refers exclusively to the authentication switch and will have no effect on the supplicant.

SHOW PORTAUTH PORT

Syntax

SHow PORTAuth[={8021x | MACbased}] POrt={ALL | port-name}

Description

The format of the SHOW PORTAUTH PORT output will be altered to display the AUTOAuthentication status. This is shown in Figure 4 Example output from the SHOW PORTAUTH PORT command below.

Figure 4: Example output from the SHOW PORTAUTH PORT command

Manager PAE Auth> sh portauth port=9				
Portauth Port Information - 802.1X Based Configuration				
Portauth Port Information - 802.1X Based Configuration Interface: port9 PAE Type Authenticator Authenticator PAE State AUTHENTICATING Port Status unauthorised Backend Authenticator State RESPONSE AuthControlPortControl Auto quietPeriod				
Auto Authenticate True				

Log Message Descriptions

No new logs will be generated by these enhancements. However, existing logs will be updated:

Module	DHCP	
Туре	LOG_TYPE_DHCP, 27, "DHCP"	
SubType	LOG_STY_DHCP_BIND, 1	
Severity	LOG_SEV_INFO	

Description

The existing DHCP log has been updated to reflect the addition of the MAC address, the lease period, the port, the serverId and the client hosts name. The enhanced log has this output:

05 15:55:33 3 DHCP DHCP 00001 mac=00-00-cd-1d-9e-b3, ip=192.168.2.101 lease=60, port=2, serverId=192.168.2.1, host=DHCP Client

Reference field: None

String Format

"mac=%E, ip=%I, lease=%u, port=%p, serverId=%I, host=%s"

Parameters

- %I The IP address of the server
- %E The MAC address of the server
- %p The port number
- %s The clients host name.

Routine(s) logged from:

dhcpmain.c: dhcpLogEvent

Recommended action: No action is required.

Name	PORTAUTH_LOG_MACBASED_AUTHSUCCESS
Module	DHCP
Туре	LOG_TYPE_DHCP, 27, "DHCP"
SubType	LOG_STY_DHCP_BIND, 1
Severity	LOG_SEV_INFO

Description

The existing DHCP log has been updated to reflect the addition of a new reason. The enhanced log has this output:

05 12:10:24 3 PORT PORTA MACB Auth Success : Port=port9 User=john MAC=00-00-cd-05-da-80 PreAuthVLAN=default PostAuthVLAN=default **Reason=Auto Auth**

Reference field: None

String Format "Auth Success : Port=%w MAC=%E PreAuthVLAN=%s PostAuthVLAN=%s Reason=%s"

Parameters

- %w The port as a string "portxx" where xx is the port number.
- %I The IP address of the server
- %E The MAC address of the server

%s The vlan settings or the success reason. The "reason" field has been enhanced to display the value "Auto Auth" when communication has been lost with the RADIUS server and a timeout has occurred and the "AUTO AUTHENTICATE" field has been set for the range - "SET DHCP RANGE=rangeX AUTOA=TRUE".

Routine(s) logged from:

pamacstate.c: portAuthMacAuthPaeStateMachineUpdate

Recommended action: This log indicates that the communication between the switch and the RADIUS server has been lost. There will be additional logs indicating this loss but investigation of this log would be prudent.

Name	PORTAUTH_LOG_AUTHSUCCESS
Module	PORTAUTH
Туре	LOG_TYPE_PORTAUTH, 64, "PORTA"
SubType	LOG_STY_PORTAUTH_AUTH, 2, "AUTH
Severity	LOG_SEV_INFO

Description

The existing DHCP log has been updated to reflect the addition of a new reason. The enhanced log has this output:

05 12:10:24 3 PORT PORTA AUTH Auth Success : Port=port9 User=john MAC=00-00-cd-05-da-80 PreAuthVLAN=default PostAuthVLAN=default **Reason=Auto Auth**

Reference field: None

String Format "Auth Success : Port=%w User=%s MAC=%E PreAuthVLAN=%s PostAuthVLAN=%s Reason=%s"

Parameters

- %w The port as a string "portxx" where xx is the port number.
- %I The IP address of the server
- %E The MAC address of the server

%s The vlan settings or the success reason. The **reason** field has been enhanced to display the value **Auto Auth** when communication has been lost with the RADIUS server and a timeout has occurred and the AUTO AUTHENTICATE field has been set for the range - SET DHCP RANGE=rangeX AUTOA=TRUE.

Routine(s) logged from:

pamain.c: portAuthAuthSuccessNotify

Recommended action: This log indicates that the communication between the switch and the RADIUS server has been lost. There will be additional logs indicating this loss but investigation of this log would be prudent.

DHCP SNMP MIB TRAPS

The ATL Enterprise MIB will be updated to reflect two new SNMP MIB Traps.

The first trap, dhcpRangeExceededThresholdTrap, will be generated when the number of clients allocated from the range exceed the upper threshold value.

The contents of this SNMP Trap are detailed in Table 3 SNMP MIB Parameters for the threshold exceeded and cleared traps on page 42.

The MIB definition is detailed in Figure 5 SNMP MIB Properties for dhcpRangeExceededThresholdTrap on page 43.

A screen dump of the MIB console is detailed in Figure 6 SNMP MIB Screen Dump on page 44.

The second trap, dhcpRangeExceededThresholdClearTrap, will be generated when the number of clients allocated from the range fall below the lower threshold value.

This trap will utilise the same parameters as detailed in Table 3 SNMP MIB Parameters for the threshold exceeded and cleared traps on page 42.

The MIB definition is detailed in Figure 7 SNMP MIB Properties for dhcpRangeExceededThresholdClearTrap on page 45.

A screen dump of the MIB console is detailed in Figure 8 SNMP MIB Screen Dump for dhcpRangeExceededThresholdClearTrap (Trap #3) on page 45.

Note that the AT-DHCP.MIB file will require updating in the customers configuration to fully interpret the new trap information.

Table 3: SNMP MIB Parameters for the threshold exceeded and cleared traps

Parameter	Meaning
sysUpTime	The duration the system has been in operation.
snmpTrapOID	The Object Identifier (OID) of the trap –
	dhcpRangeExceededThresholdTrap
dhcpRangeExhaustedInterface	The interface upon which the range resides.
dhcpRangeExceededRange	The name of the DHCP range.
dhcpRangeExceededClients	The number of clients statically allocated to the DHCP range.
dhcpRangeExceededRemaining	The number of DHCP clients that are still available to be allocated.
dhcpRangeExceededPercentage	The current percentage of DHCP clients that are allocated.

Version 291-20 C613-10488-00 REV S Figure 5: SNMP MIB Properties for dhcpRangeExceededThresholdTrap

Name:dhcpRangeExceededThresholdTrap Type:NOTIFICATION-TYPE OID:1.3.6.1.4.1.207.8.4.4.4.70.0.2 Full Path: iso(1).org(3).dod(6).internet(1).private(4).enterprises(1).alliedTele sis(207).mibObject(8).brouterMib(4).atRouter(4).modules(4).dhcp(70).d hcpTraps(0).dhcpRangeExceededThresholdTrap(2) Module:AT-DHCP-MIB Parent:dhcpTraps Prev sibling:dhcpRangeExhaustedTrap Status:current Objects:1: dhcpRangeExhaustedInterface 2: dhcpRangeExceededRange 3: dhcpRangeExceededClients 4: dhcpRangeExceededRemaining 5: dhcpRangeExceededPercentage Description: This trap is generated when a DHCP client makes a request for an IP address and a pre-defined usage threshold has been exceeded.

The IP addresses will continue to be allocated until the range is

exhausted.



Figure 6: SNMP MIB Screen Dump for dhcpRangeExceededThresholdTrap (Trap #19)

Figure 7: SNMP MIB Properties for dhcpRangeExceededThresholdClearTrap

Name:dhcpRangeExceededThresholdClearTrap Type:NOTIFICATION-TYPE OID:1.3.6.1.4.1.207.8.4.4.4.70.0.3 Full path: iso(1).org(3).dod(6).internet(1).private(4).enterprises(1).allied Telesis(207).mibObject(8).brouterMib(4).atRouter(4).modules(4).dh cp(70).dhcpTraps(0).dhcpRangeExceededThresholdClearTrap(3) Module:AT-DHCP-MIB Parent:dhcpTraps Prev sibling:dhcpRangeExceededThresholdTrap Status:current Objects:1: dhcpRangeExhaustedInterface 2: dhcpRangeExceededRange 3: dhcpRangeExceededClients 4: dhcpRangeExceededRemaining 5: dhcpRangeExceededPercentage Description: This trap is generated when the number of allocated clients in a designated range falls below a pre-defined usage threshold

Figure 8: SNMP MIB Screen Dump for dhcpRangeExceededThresholdClearTrap (Trap #3)



User Authentication Database Password Enhancement (CR00020742)

This enhancement enables you to set rules for valid characters, lifetime, and history of passwords for user accounts in the User Authentication Database with manager or security officer privilege. These rules apply when connecting via Telnet or an asynchronous port and logging in to the command line interface. They do not apply to user accounts used for authenticating calls.

You can also apply the same rules to SSH clients by configuring SSH users to use passwords from the User Authentication Database.

Valid Password Characters

Valid password characters are divided into four categories:

- uppercase letters (A–Z)
- lowercase letters (a–z)
- digits (0–9)
- special symbols (any printable character not covered by one of the other categories)

You can set the minimum number of character categories that must be present in a password, by using the command:

```
set user pwdmincat=1..4 [other-options...]
```

The **pwdmincat** parameter sets the minimum number of character categories that must be present in a password. The default is 1.

For example, if you set the minimum number of categories to 2, the following passwords are valid:

- ABCDefgh
- ABCD1234
- 1234!**#**\$%
- ABCDef12
- abcd12#\$

and the following passwords are invalid:

- ABCDEFGH
- abcdefgh
- 12345678
- !#\$%^&*(

If you try to set a password with less than the minimum number of character categories using the **add user**, **set user** or **set password** commands, an error message is displayed and the password is rejected.

You can display the global setting for the minimum number of character categories by using the command:

show user configuration

Password Lifetime and Expiry

You can force passwords for all manager and security officer accounts to expire after a set number of days, using the command:

set user pwdlifetime={0..1000} [other-options...]

The **pwdlifetime** parameter sets the lifetime of the password, in days. The default is 0, which means passwords have an unlimited lifetime and never expire. The lifetime is calculated in days from 00:00 local time on the day the password lifetime is set. This lifetime applies to current and new passwords.

The current lifetime for each user is saved in the file userpwd.sec in either NVS or flash memory, and is retained over a power cycle or restart. On the SwitchBlade 4000 Series, the file is synchronised between switch controller cards. You can not view the file, or move it from the device.

When a user with manager or security officer privilege logs in, a message is displayed showing the number of days remaining until the password expires.

If users try to log in via the command line interface with a password that has expired, they will be allowed to log in, but they will be reminded to change their password:

```
B1L2 login: manager
Password:
Warning (2045309): User password has expired, please change
password.
Manager B1L2>
```

You can force users to change an expired password immediately after logging in, using the command:

```
set user pwdforce={yes|no|on|off|true|false} [other-options...]
```

Then, when users log in with an expired password, they are immediately prompted for a new password:

```
B1L2 login: manager
Password:
Warning (2045310): User password has expired, please enter a
new password.
New password:
Confirm:
Manager B1L2>
```

Users cannot log in via the GUI using an expired password.

When you change the password lifetime, your current password is checked against the new setting. If your password doesn't comply with the new setting, you are prompted to change your password.

You can display the global settings for password lifetime using the command: show user configuration

Password History

When you configure a password lifetime, you can prevent users from re-using old passwords by enabling password history, using the command: set user pwdhistory={0|1..15} [other-options...]

The **pwdhistory** parameter sets the number of passwords to save for each user. A separate password history is created for each manager and security officer account. The password history includes the current password and all previous passwords up to the limit set. The default is 0, which disables password histories.

The password histories are saved in the file userpwd.sec in either NVS or flash memory, which is retained over a power cycle or restart. On the SwitchBlade 4000 Series, the file is synchronised between switch controller cards. You can not view the file, or move it from the device. The file size is limited to 30KBytes. You can not add a user if it would increase the file size beyond this limit. In this case, you can either delete a user that is no longer required, or reduce the size of the password history.

When password history is enabled and users try to change their password using the **set user** or **set password** commands, the new password is checked against previous passwords saved in the password history. If an identical password is found in the history, the password is rejected.

When you enable password history, each user's current password is added to the password history.

If you reduce the size of the password history by setting **pwdhistory** to a lower value, and an account has a password history with more entries than the new limit, then the oldest passwords are removed from the account's password history until the password history is reduced to the new limit.

If you disable password history by setting pwdhistory to 0, all existing password histories are destroyed.

The password history for an account is also destroyed when you:

- delete the user
- purge the user
- change the user's privilege level from manager or security officer to user.

You can display the global setting for password history using the command:

show user configuration

Version 291-20 C613-10488-00 REV S

Secure Shell Users

Secure Shell maintains its own user database separate from the User Authentication Database. However, you can apply the rules for minimum length, valid characters, lifetime, and history of passwords from the User Authentication Database to an SSH user by configuring the SSH user to use a password from the User Authentication Database.

To apply password rules to SSH users:

1. Set the password rules:

set user [pwdforce={yes|no|on|off|true|false}] [pwdhistory=0..15] [pwdlifetime=0..1000] [pwdmincat=1..4] [other-options...]

2. Create a user in the User Authentication Database with manager or security officer privilege:

add user=username password=password privilege={manager|securityofficer} [other-options...]

3. Create an SSH user with the same name and configure it to use the password from the User Authentication Database:

add ssh user=username useuserpwd [other-options...]

You can modify an existing SSH user, by using the command:

set ssh user=username [{password=password|keyid=key-id|useuserpwd}] [ipaddress={ipadd|ipv6add}] [mask=mask]

You can display information about SSH users, including which users are configured to use a password from the User Authentication Database, by using the commands:

show ssh user
show ssh user=username

Command Changes

The following table summarises the new and modified commands:

Table 1:

Command	Change
add ssh user	New parameter useuserpwd .
set ssh user	New parameter useuserpwd .
set user	New parameters pwdforce , pwdhistory , pwdlifetime , and pwdmincat .
show ssh user	Asterisk indicates that the SSH user uses a password from the User Authentication Database.

Table 1:

Command	Change
show user	New field Password Lifetime.
show user configuration	New fields minimum password categories to match, previous passwords to match, password lifetime, and force password change at logon.

Command Reference Updates

This section describes each new command and the changed portions of modified commands and output screens. For modified commands and output, the new parameters, options, and fields are shown in bold.

add ssh user

Syntax

ADD SSH USER=username {PASSword=password | KEYid=key-id | USEuserpwd} [IPaddress={ipadd / ipv6add}] [MASk=mask]

Description

This command adds a user to the list of registered users who can connect and log in via Secure Shell. If the registered user is also a member of the User Authentication Database, then the user has the associated privileges. If the SSH session username is not found in the list of registered users, and one or more RADIUS servers are defined, the user is authenticated using RADIUS. If authentication fails, the Secure Shell server will not accept the connection.

This command requires a user with security officer privilege when the device is in security mode.

The **useuserpwd** parameter specifies that the password for the corresponding user in the User Authentication Database password will be used for Secure Shell authentication. The corresponding user must exist. The parameters **password**, **keyid** and **useuserpwd** are mutually exclusive—you can only specify one.

Examples

To create an SSH user named Admin and use the password from the User Authentication Database, use the command:

add ssh user=Admin use

set ssh user

Syntax

SET SSH USER=username [{PASSword=password|KEYid=key-id|USEuserpwd}] [IPaddress={ipadd/ipv6add}] [MASk=mask]

Description

This command modifies a user in the list of registered users who can connect and log in via Secure Shell. This command requires a user with security officer privilege when the device is in security mode.

The **useuserpwd** parameter specifies that the password for the corresponding user in the User Authentication Database password will be used for Secure Shell authentication. The corresponding user must exist. The parameters **password**, **keyid** and **useuserpwd** are mutually exclusive—you can only specify one. To stop using the password from the User Authentication Database, you must specify an alternative authentication method using either **password** or **keyid**.

Examples

To modify the SSH user named Admin to use the password from the User Authentication Database, use the command:

set ssh user=Admin use

set user

Syntax

SET USEr [LOgin={True|False|ON|OFf|Yes|No}] [LOGINFail=1..10] [LOCkoutpd=1..30000] [MANpwdfail=1..5]
[MInpwdlen=1..23] [PWDForce={Yes|No|ON|OFf|True|False}] [PWDHistory=0..15] [PWDLifetime=0..1000] [PWDMincat=1..4]
[Securedelay=10..3600] [TACRetries=0..10] [TACTimeout=1..60]

Description

This command modifies global parameters affecting the User Authentication Facility. It requires a user with security officer privilege when the router or switch is in security mode.

The **pwdforce** parameter specifies whether users are forced to enter a new password after logging in with an expired password. If you specify **yes**, users are forced to set a new password immediately after they log in with an expired password. If you specify **no**, a message is displayed asking the user to set a new

password, but the user is not forced to set a new password. The **pwdforce** parameter applies only to users with manager and security officer privilege, and is only valid when a password lifetime has been set using the **pwdlifetime** parameter.

The **pwdhistory** parameter specifies the number of passwords to save in a password history for each user with manager or security officer privilege. Specify 0 to disable password histories. The default is 0. When you enable password histories and a user with manager or security officer privilege changes their password, the new password is checked against the list of previous passwords in the user's password history. If an identical password is found in the history, the password is rejected.

The **pwdlifetime** parameter specifies the lifetime, in days, of passwords for users with manager or security officer privilege. Specify 0 to disable password histories. The default is 0, which means passwords have an unlimited lifetime and never expire. When you set a password lifetime, and a user with manager or security officer privilege logs in, a message is displayed showing the number of days left until the password expires. When a user logs in with a password that has expired, they are prompted to change the password. If **pwdforce** is set to **yes**, the user is forced to change the password immediately after logging in.

The **pwdmincat** parameter specifies the minimum number of character categories that must be present in passwords for users with manager or security officer privilege. The default is 1. Valid password characters are divided into four categories:

- uppercase letters (A–Z)
- lowercase letters (a–z)
- digits (0–9)
- special symbols (any printable character not covered by one of the other categories)

Examples

To force users with manager or security officer privilege to combine uppercase and lowercase letters, digits, and special characters in their passwords, use the command:

set user pwdmincat=4

To set a password lifetime of 60 days, save a history of the last five passwords, and force a user logging in with an expired password to change the password immediately, use the command:

set user pwdlifetime=60 pwdhistory=5 pwdforce=yes

show ssh user

Syntax

SHow SSH USER[=username]

Description

This command displays information about the users allowed to make connections to the Secure Shell server.

The **user** parameter specifies the user name being displayed.

If a user is not specified, summary information about all users is displayed (Figure 9, Table 4). The **Auth** field now includes an asterisk if the password used is from the User Authentication Database.

If a user is specified, details are displayed about that user (Figure 10 on page 55, Table 5 on page 55).

Figure 9: Example output from the **show ssh user** command

Secure Shell User List				
User	IpAddr	Auth	KeyId	Status
test4 test2 secoff 800 admin john	fe80:230:84ff:fe0e:263e fe80:230:84ff:fe0e:263d 0.0.0.0 0.0.0.0 0.0.0.0 192.168.2.1	Pass Pass RSA RSA RSA Pass*	0 0 5 4 7 0	enabled enabled enabled enabled disabled enabled

Table 4: Modified parameters in output of the **show ssh user** command

Parameter	Meaning
Auth	The authentication method; one of "RSA" or "Pass" (password). Pass is followed by an asterisk ("*") if the password from the User Authentication Database is used.

Figure 10: Example output from the **show ssh user** command for a specific user

Table 5: Modified parameters in output of the **show ssh user** command for a specific user

Parameter	Meaning
Authorisation method	The authentication method; one of "RSA" or "Password". Password is followed by "(user database)" if the password from
	the User Authentication Database is used.

show user

Syntax

SHow USEr[=login-name]

Description

Version 291-20

This command displays the contents of the User Authentication Database (Figure 1-1 on page 56, Table 6 on page 57).

The output of this command includes a new **Password Lifetime** field.

Figure 1-1: Example output from the **show user** command

Number of logged in Security Officers currently active1				
Number of Radius-backup users 0				
User Authentication Database	3			
Username: dave () Status: enabled Privil Callback number: 00613935 Calling number: 5554491 Logins: 2 Fails: Authentications: 0 Fails: Password Lifetime: expire	ege: Sec Off Telnet: yes 546786 0 Sent: 0 0	Login: yes Rcvd: 0	RBU: no	
Username: manager (Manager A Status: enabled Privil Logins: 4 Fails: Authentications: 0 Fails: Password Lifetime: 1 days	account) .ege: manager Telnet: yes 0 Sent: 0 0	Login: yes Rcvd: 0	RBU: no	
Username: tony () Status: enabled Privil Ip address: 192.168.1.5 IPX network: c0e7230f Apple network: 22 Apple	ege: user Telnet: no Netmask: 255.255.255.0 e zone: Finance	Login: no Mtu: 1500	RBU: no	
Logins: 0 Fails: Authentications: 0 Fails:	2 Sent: 0 0	Rcvd: 0		
Active (logged in) Users				
User Port/Device Login Time	Location			
manager Asyn 0 14:33:22 18-Apr-2002 manager Telnet 1	local			
14:33:22 18-Apr-2002	10.1.1.1			

Table 6: New parameters in output of the **show user** command

Parameter	Meaning
Password Lifetime	The number of days left until the user's password expires, or "expired" if the password has expired.

show user configuration

Syntax

SHow USEr Configuration

Description

This command displays global configuration parameters and counters for the User Authentication Facility (Figure 1-2 on page 58, Table 7 on page 58).

The output of this command includes new fields.

57

Figure 1-2: Example output from the **show user configuration** command

Security parameters					
login failures before loc			4		(LOGINFAIL)
lockout period			20	seconds	(LOCKOUTPD)
manager password failures	s before log	off	3		(MANPWDFAIL)
maximum security command	interval		30	seconds	(SECUREDELAY)
minimum password length .			6	characters	(MINPWDLEN)
TACACS retries			3		(TACRETRIES)
TACACS timeout period			5	seconds	(TACTIMEOUT)
minimum password categori	les to match		1		(PWDMINCAT)
previous passwords to mat	ch		15		(PWDHISTORY)
password lifetime			38	days	(PWDLIFETIME)
force password change at	logon	en	able	ed	(PWDFORCE)
semi-permanent manager po	ort	no	ne		
Security counters					
logins	7	authent	icat	tions	23
managerPwdChanges	0	default	Acct	tRecoveries	0
unknownLoginNames	1	tacacsL	ogir	nReqs	1
totalPwdFails	5	tacacsL	ogir	nRejs	1
	3	tacacsR	eqT	imeouts	0
managerPwdFails					_
managerPwdFails securityCmdLogoffs	1	tacacsR	eqFa	ails	0

Table 7: New parameters in output of the **show user configuration** command

Parameter	Meaning
minimum password categories to match	The minimum number of character categories that must be present in passwords for users with manager or security officer privilege.
previous passwords to match	The number of passwords to save in a password history for each user with manager or security officer privilege, or "disabled" if password histories are disabled.

Table 7: New parameters in output of the show user configuration command

Parameter	Meaning
password lifetime	The lifetime, in days, of passwords for users with manager or security officer privilege, or "disabled" if passwords do not expire.
force password change at logon	Whether users with manager or security officer privilege logging in using an expired password are forced to change their password immediately; either "enabled" or "disabled".

Enhancements (CR00020478)

Some enhancements have been made to the reporting of statistics and status information relating to triggers. In addition, functionality has been added, to enable SNMP traps to be sent when triggers are activated.

The enhancements are:

- 1. The configuration and status of all defined triggers can now be obtained by SNMP. To support this, a Trigger Configuration Info table has been added to the Allied Telesis trigger MIB.
- 2. Detailed statistics relating to the trigger module as a whole can now be obtained by SNMP. To support this, a number of objects have been added under the triggerCounters branch of the Allied Telesis trigger MIB.
- 3. Triggers can now be configured to send SNMP traps when they are activated.

Two new commands are available in trigger configuration mode:

"trap" is to enable this option

"no trap is to diable this option.

By default the option is disabled

4. A new row has been inserted into the output of the "show trigger counters" command. This row appears after "Trigger activations". This item is to display the identity of the most recently activated trigger. The new output of this command will appear as follows:

Trigger activations 5

Trigger last activated...... 20

Time triggers activated today2

••••

5. A new column, labelled "TR", has been added to the output of "show trigger". This column indicates whether or not the trigger is configured to send an SNMP trap when it is activated.

The new output of this command will appear as follows:

awplus#show trigger TR# Type & Details Description Ac Te TR Repeat #Scr Days/Date ------

001 CPU (80% up) dispaly cpu usage... Y N Y 123 0 26-nov-2007

004 Memory (80% up) dispaly mem usage... Y Y Y Continuous 0 -mt---s

•••

6. A new row has been inserted into the output of the command "SHOW TRIGGER trigger-id" This row is to indicate whether or not an snmp trap is sent when the trigger is activated. The new output of this command appears as follows:

awplus#sho trigger 1

Trigger Configuration Details

Trigger 1

:

Test No

Trap Yes

:

External Loop Detection and Termination Mechanism (CR00026527)

The purpose of this feature is to detect whether the device is forming part of a network loop. That is, whether its external ports are receiving and transmitting packets that are contributing to a packet storm caused by a loop existing somewhere in its external network.

Operation

If this condition is detected, the switch will disable one or more of its ports in an attempt to terminate the storm by breaking the loop. The mechanism used in these checks operates independently and alongside conventional Ethernet loop spanning tree protocols that may be used to avoid data loops.

Methods employed

Two methods are employed to detect data loops:

- LDF Detection
- Receive Broadcast Counter Method

LDF detection

This method operates by transmitting Loop Detection Frames (LDF) from the external switch ports. An LDF is a VLAN tagged or untagged frame that contains the following:

- a unique and unregistered destination MAC address of a non-existent station. For example: FE-FF-FF-xx-xx where the last 3 bytes used are the last 3 bytes of the source MAC address of the device.
- the sending MAC address of the initiating device
- an LDF data field comprising a unique test pattern

Because their destination MAC addresses will always be unknown, LDF frames will flood the network. If the device then receives an LDF on the same VLAN as that used when originally transmitted, a loop is assumed to exist somewhere downstream of the device's external ports. When a loop is detected the switch will apply the process that is specified by the action parameter of the **set switch loopdetection** command.

Receive broadcast counter method

If the device is part of a broadcast packet storm, one or more of the external ports will be receiving broadcast frames at, or close to, line rate. These frames will then flood the ingress VLAN of the device, and the transmit broadcast packet counters of the other external ports of this VLAN will increase to near line rate.

This method detects loops by monitoring the rate at which broadcast frames are received on the device's external ports, as recorded by the broadcast packet counter. If this rate exceeds that set by the BCthreshold parameter of the **set switch loopdetection** command, then an external loop is assumed to exist

somewhere the device's external network. When a loop is detected the switch will apply the process that is specified by the action parameter of the **set switch loopdetection** command.

Actions if a loop is detected

If a loop is detected, a log message will be generated. Users are also able to configure whether the ports that participate in the loop will be disabled. A port disabled by this feature will remain disabled until it is either manually re-enabled, or a configurable timeout period elapses whereupon the CPU will re-enable the port. The **default** value of the configurable timeout period is **5 minutes**.

Commands

The following commands will be available on ALL devices:

- SET SWITCH LOOPDETECTION
- ENABLE SWITCH LOOPDETECTION
- SHOW SWITCH LOOPDETECTION
- SHOW SWITCH LOOPDETECTION COUNTER
- DISABLE SWITCH LOOPDETECTION
- ENABLE SWITCH LOOPDETECTION DEBUG
- DISABLE SWITCH LOOPDETECTION DEBUG

SET SWITCH LOOPDETECTION

Syntax

SET SWItch LOOPdetection=LDF [ACtion={NONE|DISableport}] [LDFinterval=10..1000000] [PDTO={1.. 86400|NONE}] [SECure={ON|OFF}]

Syntax

SET SWItch LOOPdetection=BCcounter [ACtion={NONE|DISableport}] [BCthreshold=1..20000000][PDTO={1..86400|NONE}]

Description

This command sets an operational parameter on a method of loop detection.

Table 8: This command displays the counters of a health check.

Parameter	Description
ACtion	Specifies the action to be taken when a port is deemed to be in a loop. If DISableport is specified, the port will be disabled, and will remain disabled for the time specified by the PDTO parameter of the set switch loopdetection command. However, once disabled, the user can re-enable the port at any time. If NONE is specified, no action will be taken. The default value is NONE.
BCthreshold	Specifies the receive broadcast packet port counter threshold, the units of which are frames per second. There is no default value for the BCTHRESHOLD parameter and as a result, this value must be specified before the BCCOUNTER method of loop detection can be enabled.
LDFinterval	Specifies the time interval in seconds between when a Loop Detection Frame (LDF) is sent out a port. A staggered start is used so that LDFs are not sent out all ports at the same time. The default is 120 seconds.
LOOPdetection	Specifies which method of loop detection will be set.
PDTO	The Port Disabled Time Out parameter specifies the length of time in seconds that a port remains in the disabled state after the port has been disabled by loop detection. If NONE is specified, the port will not be re-enabled by loop detection. Once a port has been disabled by loop detection, the port can be re-enabled at any time using the enable switch port command. Re-enabling a port will stop the timeout period. This parameter is only used if the DISABLEPORT action is specified. The default is 300 seconds.
SECure	Whether discard LDFs that are received out of sequence.

Example

To set the port disabled timeout to 60 seconds and to specify the disable port action on the LDF method of loop detection, use the command:

set swi loop=ldf ac=dis pdto=60

To set the port disabled timeout to the default 300 seconds and to specify the disable port action on the BCC method of loop detection, use the command:

set swi loop=bcc ac=dis pdto=none

Related commands

disable switch loopdetection enable switch loopdetection show switch loopdetection

ENABLE SWITCH LOOPDETECTION

Syntax

ENable SWItch LOOPdetection={BOTH|LDF|BCcounter} [ACtion={NONE|DISableport}] [POrt={port-list|ALL}]

Description

This command enables loop detection on the specified ports, or all ports if the PORT parameter is not specified.

Table 9: This command displays the counters of a health check.

Parameter	Description
ACtion	Specifies the action to be taken when a port is deemed to be in a loop. If DISableport is specified, the port will be disabled, and will remain disabled for the time specified by the PDTO parameter of the set switch loopdetection command. However, once disabled, the user can re-enable the port at any time. If NONE is specified, no action will be taken. The default value is NONE.
LOOPdetection	Specifies which method of loop detection will be enabled. If LDF is specified, Loop Detection Frames (LDF) will be periodically sent out the ports that loop detection is enabled on. If the switch receives these LDFs, then a loop has been formed. If BCCOUNTER is specified, the receive broadcast packet port counter will be checked against a user configurable threshold each second. If the rate equals or exceeds the threshold, the port will be deemed to be in a loop. The two methods operate independently of one another, and can be enabled simultaneously by specifying BOTH.

Parameter	Description
POrt	The list of ports that loop detection will be enabled on. If ALL is specified, then loop detection will be enabled on all the ports that loop detection is currently enabled on. The default value is ALL. Port numbers start at 1 and end at m, where m is the highest numbered Ethernet switch port, including uplink ports. Ports are identified by a port number.

Example

To enable loop detection using the bccounter method on ports 1 - 24, use the command:

ena swi loop=bcc port=1-24

Related commands

disable switch loopdetection set switch loopdetection

SHOW SWITCH LOOPDETECTION

Syntax

SHow SWItch LOOPdetection[={LDF|Bccounter}] [Port={port-list|ALL}]

Description

This command displays loop detection information about one or more ports.

Figure 2: Example output from the SHOW SWITCH LOOPDETECTION=LDF command

LDF Acti Secu LDF Port	Method on re interval disabled tin	 neout	Disable p OFF 120 sec 300 sec	oort	
Rx p	ort In loop	Disabl	ed Re-enabling in	Tx port	Debug mode
1	Yes	Yes	30	1	None
2	No	No	-	-	None
3	No	No	-	-	None
4	No	No	-	-	None
5	No	No	-	-	None
6	No	No	-	-	None
7	No	No	-	-	None
8	No	No	-	-	None
9	No	No	-	-	None
• • •					

Figure 3: Example output from the SHOW SWITCH LOOPDETECTION=BCCOUNTER command

BCCO Acti Broa	UNTER Method on dcast thresh disablod ti	l lold	Disab	le port 0 frames/sec	
Rx p	ort In loop	Disabled	Rate detecte	ed Re-enabling in	Debug mode
1	No	No	_	-	None
2	No	No	-	-	None
3	No	No	-	-	None
4	No	No	-	-	None
5	No	No	-	-	None
6	No	No	-	-	None
7	No	No	-	-	None
8	No	No	-	-	None
9	Yes	Yes	149764	288	None
10	No	No	-	-	None
11	No	No	-	-	None
12	No	No	-	-	None
13	No	No	-	-	None
14	No	No	-	-	None
15	Yes	Yes	149888	288	None
•••					
52	No	No	-	-	None

Table 10: Parameters displayed in the output of the SHOW SWITCH LOOPDETECTION

Parameter	Description
ACtion	The action the switch will take when the LDF method indicates that the port is in a loop. One of: Disable port or None.
Secure	Indicates whether an out of sequence LDF is discarded by the switch. One of: ON or OFF.
LDF interval	The interval between the transmissions of LDFs in seconds.

Parameter	Description
Port disabled timeout	The duration that a port that is disabled by LDF method, remains disabled. Either a time in seconds or None.
Rx Port	A list of ports on which the LDF method is enabled.
In Loop	Whether the LDF healthcheck has detected a loop on the port; one of Yes or No.
Disabled	The time in seconds before the port is automatically re-enabled.
Re-enabling in	The time in seconds before the port is automatically re-enabled.
Tx Port	The switch has received an LDF that it transmitted. The LDF contains information regarding the port that the LDF was sent out of on the switch; this port number is displayed in this field.
Debug mode	The debug mode that is currently turned on for the port; one of LDFTxRx or None.
BCCOUNTER METHOD)
Action	The action the switch will take when the BCCounter method indicates that the port is in a loop; one of Disable port or None.
Broadcast threshold	The broadcast threshold in frames per second.
Port disabled timeout	The duration that a port disabled by loop detection remains disabled. Can be specified by either a time in seconds, or continuous. In the continuous mode the port will remain disabled until it is manually enabled by using the enable switch port command.
Rx Port	A list of ports.
In Loop	A loop has been detected on the port by the BCCounter method; one of Yes or No.
Disabled	Whether port is currently disabled by the BCCounter method; one of Yes or No.
Rate detected	The number of the increase of the broadcast packets when the BCCOUNTER method determined that a port was in a broadcast storm.
Rate-enabling in	The time in seconds before the port is automatically re-enabled.
Debug mode	The debug mode currently turned on for the port: one of BCRate or None.

Examples

To display the status of loop detection, use the command:

sh swi loop

Related commands

disable switch loopdetection enable switch loopdetection set switch loopdetection show switch loopdetection counter

SHOW SWITCH LOOPDETECTION COUNTER

Syntax

SHow SWItch LOOPdetection COUnter[Port={port-list|ALL}]

Description

This command displays counter information about loop detection.

Figure 4: Example output from the SHOW SWITCH LOOPDETECTION COUNTER PO=1-52 command.

DF M	lethod			
ort	Date/Time	Tx	Rx	Status
		14	0	Disabled
		0	0	Disabled
		0	0	Disabled
		0	0	Disabled
		0	0	Disabled
		0	0	Disabled
		0	0	Disabled
		0	0	Disabled
		0	0	Disabled
		14	0	Disabled
		0	0	Disabled
		0	0	Disabled
		0	0	Disabled
		0	0	Disabled
		0	0	Disabled
		0	1	Disabled
		0	0	Disabled
		0	0	Dibubica
		0	0	Disabled
cot	NTER Method			
rt	Date/Time	Threshold	Rate detected	Status
				Enabled
				Fnablod
	04-2009 13.53.42	100000	70644581	Enabled
		-		Fnablod
		—	-	Enabled
		-	-	Enabled
		-	-	Enabled
		-	-	Enable ⁷
		-	-	Enabled
	04-Aug-2009 13:59:42	1000000	/064///4	Enabled
		U	0	Enabled
•		0	0	Dochlad

Parameter	Meaning	
LDF METHOD		
Port	A list of ports.	
Date/Time	The date and time when the LDF healthcheck last detected a loop was detected on the port.	
Tx	The number of LDFs transmitted out of the port.	
Rx	The number of LDFs received on the port.	
Status	The current status of LDF method on the port; one of <i>Enabled</i> or <i>Disabled</i> .	
BCCOUNTER METHOD		
Port	A list of ports.	
Date/Time	The date and time when BCCountercheck last detected a loop on the port.	
Threshold	The broadcast threshold in frames per second was set when the loop was detected.	
Rate detected	The number of the increase of the broadcast packets when the BCCOUNTER method determined that a port was in a broadcast storm.	
Status	The current status of BCCOUNTER method on the port; one of <i>Enabled</i> or <i>Disable</i> .	

Table 11: Parameters displayed in the output of the SHOW SWITCH LOOPDETECTION COUNTER

Examples

To display the status of loop detection, use the command:

show swi loop=bc cou port=5

Related commands

disable switch loopdetection enable switch loopdetection set switch loopdetection show switch loopdetection

DISABLE SWITCH LOOPDETECTION

Syntax

DISable SWItch LOOPdetection={LDF|BCcounter|BOTH}[POrt={port-list|ALL}]

Description

This command disables loop detection on the specified ports, or all ports if the PORT parameter is not specified.

Table 12: This command displays the counters of a health check.

Parameter	Description Specifies which method of loop detection will be disabled.		
LOOPdetection			
	LDF	Loop Detection Frames (LDF) will not be sent from ports with loop detection disabled.	
	BCcounter	The broadcast packet port counter will not be monitored	
	BOTH	Both LDF and BCcounter disabling will be disabled.	
POrt	The ports that loop detection will be disabled on.		
	Default: ALL		
	Port-list	Selects a list of port numbers in the range 1 to m, where m is the highest numbered Ethernet switch port, including uplink ports. Ports are identified either by a port number or a line card.port number.	
	ALL	Selects all the ports.	

Examples

To enable loop detection using the bccounter method on the BCCOUNTER ports 1 - 24, use the command:

ena swi loop=bcc port=1-24
Related Commands

enable switch loopdetection show switch loopdetection set switch loopdetection enable switch loopdetection

ENABLE SWITCH LOOPDETECTION DEBUG

Syntax

ENable SWItch LOOPdetection DEBug={ BCRate | LDFtxrx | ALL}] [POrt={port-list | ALL}] [TIMEOut={1..10000 | NONE}]

Description

This command enables loop detection debugging on the specified ports, or all ports if the port parameter is not specified. Be aware that enabling debug could flood the receiving Telnet session or asynchronous port with raw data. The default value is for debug to be disabled on loop detection.

Table 13: This command displays the counters of a health check.

Parameter	Description
ALL	All loopdetection debug options.
BCRate	The rate of broadcast frames received over a fixed 1 second time interval. The number of broadcast frames that arrive during a 1second time period are compared with the number recorded for the previous period. If this count exceeds the value set by the BCthreshold parameter of the set switch loopdetection command, then the bcrate will be displayed in debug information.
DEBug	Specifies the loop detection debug mode to be enabled. The values for the debug parameter will be determined during implementation. If all is specified then all debug modes will be disabled.
LDFtxrx	Debug information will be displayed whenever an LDF frame is transmitted or received.
LOOPdetection	The loopdetection parameter specifies which method of loop detection will not have debugging. If both is specified, then both methods of loop detection will not have debugging.

Table 13: This command displays the counters of a health check.

Parameter	Description
POrt	Specifies the list of ports that loop detection debugging will be enabled on. If ALL is specified, then loop detection debugging will be enabled on all ports. The default value is all. Port numbers start at 1 and end at m, where m is the highest numbered Ethernet switch port, including uplink ports. Ports are identified by a port number.
TIMEout	The timeout parameter specifies the time in seconds for which any switch health check debugging is enabled. This reduces the risk of the switch and the display being overloaded with too much debugging information.

Examples

To enable loop detection debug modes via BC rate method on port 1-24, use the command:

ena swi loop deb=bcr port=1-24

Related Commands set switch loopdetection show switch loopdetection

DISABLE SWITCH LOOPDETECTION DEBUG

Syntax

DISable SWItch LOOPdetection={BOTH | LDF | BCcounter} DEBug={BCRate | LDFtxrx | ALL} [POrt={port-list | ALL}]

Description

This command disables loop detection debugging on the specified ports, or all ports if the PORT parameter is not specified. The default value is for debug to be disabled on loop detection.

Table 14: This command displays the counters of a health check.

Parameter	Description
BCRate	The rate of broadcast frames received over a fixed 1 second time interval. The number of broadcast frames that arrive during a 1 second time period are compared with the number recorded for the previous period. If this count exceeds the value set by the BCthreshold parameter of the set switch loopdetection command, then the BCRate will be displayed in debug information.
DEBug	Specifies the loop detection debug mode to be disabled. The values for the DEBUG parameter will be determined during implementation. If ALL is specified then all debug modes will be disabled.
LDFTxRx	Display of information whenever a LDF is transmitted or received.
LOOPdetection	The LOOPDETECTION parameter specifies which method of loop detection will not have debugging. If BOTH is specified, then both methods of loop detection will not have debugging.
POrt	Specifies the list of ports that loop detection debugging will be disabled on. If ALL is specified, then loop detection debugging will be disabled on all ports. The default value is all. Port numbers start at 1 and end at m, where m is the highest numbered Ethernet switch port, including uplink ports. Ports are identified by a port number.
ALL	All loopdetection debug options.

Examples

To disable loop detection debug modes via BC rate method on ports 1-24, use the command:

dis swi loop=bcc deb=bcr port=1-24

Related Commands

enable switch loopdetection set switch loopdetection show switch loopdetection

Software Maintenance Version 291-19 includes the resolved issues in the following tables. In the tables, for each product series:

- "Y" indicates that the resolution is available in Version 291-19 for that product series.
- "-" indicates that the issue did not apply to that product series.

Level 1

No level 1 issues.

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00023546	Spanning Tree Protocols	2	STP forwarding did not operate correctly between switches connected with an aggregated link. This could have caused ports in the link to be in the discarding state, rather than the forwarding state. This issue has been resolved.	-	_	_	Y	Y	Y	Y	Y	Y	Y	Y
CR00023702	Firewall	2	The add firewall policy httpfilter command allows you to specify a file containing a list of commands to control web access. However, the keyword aspect of this control file was not filtering web access correctly. This has been corrected. Note that you must add keywords to the top of the file under "keywords:" before any other filtering type, such as "urls:". See the Firewall chapter in the Software Reference for your router or switch for more information about creating these files.	Y	Y	Y	Υ	Y	Y	_	_	_	_	Y

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	АТ-9900	АТ-9800
CR00024044	Tost	2	The router or switch could become upresponsive, or report, during a full		~ ~	~ ~				~ ~	~ ~	~		
CR00024044	lest	2	interface test on all interfaces that lasted for a period of over 40 minutes. This only occurred when ethernet crossover cables were used as loop back cables for the interface tests. This issue has been resolved.	T	T	T	I	T	T	T	I	Ι	T	
CR00024282	OSPF	2	In some uncommon network configurations, it was possible that some summary LSAs may not have been propagated to all areas in the AS. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00024305	Switching	2	Previously on a 9924T switch, if you tried to create a new hardware filter when the filter database was full, the database could become corrupted until the next reboot. As well, deleting filters while the database was corrupted could result in the wrong filters being removed. This issue has been resolved. Now, if the maximum number of hardware filters is reached, any attempt to add new hardware filters will not affect the hardware filter database.	_	_	_	_	_	_	_	_	_	Υ	
CR00024695	OSPF	2	When flushing a very large amount of LSAs (4000 or more), the OSPF network neighbour relationship would become unstable, as the router or switch was not transmitting and receiving OSPF hello messages efficiently. This issue has been resolved. The ability of the router or switch to handle OSPF traffic has increased significantly.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00024758	PRI	2	The router could reset PRI interfaces more often than was necessary in the presence of line noise. This issue has been resolved.	Y	Y	Y	_	_	_	_	-	_	_	-
CR00024840	ADSL	2	Previously, line degradation on an ADSL2 or ADSL2+ connection would cause failures in the link as the router attempted to adapt to the changes in the line condition. This issue has been resolved.	Y	_	_	_	_	_	_	-	-	—	-
CR00025019	SFP	2	Previously, an x900-48FS switch would not recognise an inserted Coretek SFP after a restart. This issue has been resolved.	-	-	_	_	_	_	_	-	Y	_	_

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR7505 / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00025177	OSPF	2	Previously, when multihomed links were used between OSPF neighbours and all were active (that is, the secondary links were not added with passive=on), then it was possible that the show opsf neighbour command would not display some neighbours. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00025186	РРР	2	If a router or switch was configured for both PPPoE client and Access Concentrator modes, then after a restart when the router or switch received a PPP LC Echo Request for a session that no longer existed (due to the restart) it would send an invalid PADT for that session. As a result the session would take much longer to be removed by the peer and a new session would not be established as quickly as possible. This issue has been resolved. After a restart, the router or switch will ensure that a valid PADT is sent and re-establishment of the PPPoE session happens as quickly as possible.	Y	Y	Y	Y	Y	Y	_	_	Y	_	Y

No level 3 issues.

Level 4

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00024786	OSPF	4	Previously, when an OSPF neighbour was removed, the neighbour entry remained in the show ospf neighbour output, even after the LSA had timed out. This issue has been resolved. After an LSA times out for a removed neighbour, the entry is no longer shown, unless specifically requested by using the full parameter in the show ospf neighbour command.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

Enhancements

No enhancements.

Software Maintenance Version 291-18 includes the resolved issues and enhancements in the following table. In the tables, for each product series:

- "Y" in a white column indicates that the resolution is available in Version 291-18 for that product series.
- "-" in a white column indicates that the issue did not apply to that product series.
- a grey-shaded column indicates that Version 291-18 was not released on that product series.

"Y" in a grey column indicates that the issue applied to that product series. These issues are resolved in the next Version (291-19).

"-" in a grey column indicates that the issue did not apply to that product series.

Level 1

No level 1 issues.

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00024484 CR00024714	Switching	2	On AT-8948 and AT-9900 series switches, the forwarding database (FDB) on the switch could lock-up when a large numbers of MAC addresses were learnt or aged on the system at a high rate (for instance, during a broadcast storm). This issue has been resolved.	-	-	-	-	_	-	_	-	Y	Y	-
CR00024732	EPSR	2	The switch could restart if its EPSR process requested the switch to flush its forwarding database (FDB). This could only occur on an EPSR network that contained a large numbers of VLANs and required the switch to store a large numbers of MAC addresses in its FDB. This issue has been resolved.	_	-	-	-	_	-	-	-	Y	Y	-

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR7505 / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00024760	Switching	2	Previously on AT-8948 and AT-9900 series switches, the switch could stop learning new MAC addresses during broadcast storm conditions that occurred for a long period of time. This issue has been resolved.		-		_	_	1	_	_	Y	Y	_
CR00024889	Switching	2	MAC thrash limiting did not work in software release 291-17. This has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

Levels 3 and 4

No level 3 or 4 issues.

Enhancements

No enhancements.

Software Maintenance Version 291-17 includes the resolved issues and enhancements in the following tables. In the tables, for each product series:

- "Y" indicates that the resolution is available in Version 291-17 for that product series.
- "-" indicates that the issue did not apply to that product series.

Level 1

No level 1 issues.

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00020173	X.25	2	The router or switch could restart unexpectedly when three or more X.25T circuits were all transmitting. This issue has been resolved. As well, the router or switch will now ensure that X.25 calls are cleared when installed in a X.25 network that sends Reset Indications in response to Reset Confirmation messages. Sometimes when an X25 network resets a circuit with a Reset Indication the network is not satisfied by a Reset Confirmation reply and continues to send a Reset Indication for every Reset Confirmation. The router or switch now counts the Reset Indications received and clears the call if more than 3 Reset Indications are received with no data transferred between them.	Y	Y	Y	Y	Y	_	_	_	_	_	

CR	Module	Level	Description	AR44x / AR450	AR7×5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00021338	РРР	2	Previously, PPP could unneccessarily reduce the memory available on the device for other services when configured as a PPPoE access concentrator. This occurred when a client repeatedly attempted to connect and failed (for example because of authentication failure). When the session was terminated, buffers were left allocated to the session, causing the amount of memory available to steadily reduce. This issue has been resolved.	Y	Y	Y	Y	Y	Y		_	Y	Y	Y
CR00021633	Firewall	2	When the firewall received an 500-level error from FTP, it did not always clean up the firewall sessions associated with the FTP connection. This issue has been resolved.	Y	Y	Y	Y	Y	Y	_	_	_	_	Y
CR00021772	IGMP snooping	2	Previously IGMP Snooping caused a memory leak when a host joined or left a multicast group. This was because memory allocated when the host joined the group was not returned to the memory pool when the host left the group. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00022084	Bridging	2	Previously, if a bridge filter was configured with port=none the running configuration on the router or switch would actually be set to port=all . This issue has been resolved.	Y	Y	Y	_	_	_	_	_	_	_	-
CR00022092	UPnP	2	Over a long period of time UPnP would exhaust the number of available TCP connections on the device and not release them. This has been resolved.	Y	Y	Y	_		_	Ι	_	-	-	_
CR00022692	Port Authentication	2	In certain network configurations, when an AR770S required authorisation from a Port Authentication device, the AR770S would fail to respond to the request packet sent from the Authenticator. This occurred only if the Authenticator was in multiple-supplicant mode (enabled using mode=multi in the enable portauth port command). This issue has been resolved.	_	_	Y	_	_	_	_		_		_

CR	Module	Level	Description	AR44x / AR450	AR7×5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00022732	PIMv4	2	In normal PIM operation, assert messages are used between PIM neighbours to determine which neighbour has the better route between a multicast client and source. Once the exchange has occurred, the losing neighbour informs the winning neighbour to remove its route from the neighbour's PIM routing table. The winning neighbour forwards the multicast traffic and starts an assert timer that, when it expires, causes a new assert exchange. However, when the router or switch was the losing PIM neighbour, it would not correctly respond to the new assert exchange, and it would fail to tell the winning neighbour to prune its route from the neighbour's routing table. This meant that the winning neighbour, would incorrectly transmit multicast traffic to the losing neighbour. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	-	Y	Y	Y
CR00022932	IPsec	2	Previously, the router or switch could fail to create some IPsec tunnels if the IPsec peer was specified using a DNS name (peeraddress=domainname) in the create ipsec policy or set ipsec policy commands. This occurred only when an ISAKMP policy was attached to the IPsec policy (with the isakmppolicy parameter), and the ISAKMP policy also used the peer's DNS name to identify the peer. This issue has been resolved.	Y	Y	Y	Y	Y	Y	1	_	-	1	1

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00022946	DHCP	2	 Previously, when you created a DHCP user-defined option, a null byte was attached to the end of any defined string. For example, if this option was specified: add dhcp option=99 policy=name type=string value=acme then when this option was included in a DHCP message, a null byte was added to "acme", making the string 5 bytes long. This behaviour has changed based on the option number. For options numbered between 0 and 86, the null byte is still added to the end of the string. For options numbered 87 and higher, the null byte is not added. If you override a predefined option in the range of 0 to 86 with a user-defined option, it will continue to append the string with a null byte for backwards compatibility. This is to meet the requirements of both RFC 2131 and 2132. RFC 2131, which defines the DHCP protocol, explicitly states that certain string fields should be null terminated (specifically options 12 and 67). This RFC and others before it have led Allied Telesis routers and switches to null terminate string-based options from 0 to 86. However, RFC 2132, which defines further DHCP and BOOTP vender extensions, clarifies that string fields should not be null terminated. Note that you can use the hexstring parameter if you want to have a value that does not have the null byte appended for DHCP options between 0 and 86. 	Y	Υ	Y	Υ	Y	Y	Y	Y	Y	Y	Y
CR00023047	IPsec	2	Under certain IPSec policy configurations with multiple policies numbering above 24, the throughput performance of IPSec was not linear across the increasing number of policies. This issue has been resolved.	Y	Y	Y	Y	Y	Y	_	_	_	_	_
CR00023261	STP, EPSR	2	Sometimes, under sustained broadcast storm conditions and following an STP topology change or an EPSR ring state change, the switch would restart. This issue has been resolved.	_	-	_	-	-	_	_	_	Y	Y	_

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00023554	PRI	2	Previously, a PRI interface could lock up in the presence of line noise. This has now been fixed.	Y	Y	Y	Y	Y	-		_	_	_	_
CR00023842	DHCP	2	Previously, on a router or switch using multihoming, the DHCP server on the router or switch could sometimes assign multiple IP address to the same client. This occurred for clients attached to an interface configured with more than one IP address. Some improvements to this issue were made in software version 2.9.1-16. This software release resolves this issue. It ensures that DHCP release, renew, and discover messages are correctly processed on interfaces with multiple IP addresses, so that the DHCP server can identify when it has already assigned a client an IP address.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00023921	RIP	2	Previously, RIP would not advertise the default route if a blackhole route had been entered into the routing table. This was caused by RIP suppressing the advertised routes based on the routes' netmask lengths instead of their preference values. This has been fixed. Please note that if your configuration relied solely on the netmask to determine if a black hole route suppressed a route advertised by RIP, you may need to have the routes' preference values adjusted so that it continues to be suppressed.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00024189	PIM	2	Previously the router or switch may have restarted if a change in unicast routing information led to a PIM Source, Group entry to no longer have an RPF interface to a source. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y		Y	Y	Y

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00024244	РРР	2	The router or switch would silently discard echo-requests from a PPP peer after the peer had negotiated with it not to use the LCP magic number option. This was because the router or switch would discard echo-requests with a magic number set to 0 regardless of whether the magic number was required for the link. The magic number option is used to check that the link is not in loopback mode. This issue has been resolved. Echo-Requests with a magic number of 0 are now replied to if the PPP peers have negotiated not to use the LCP magic number option.	Y	Y	Y	Y	Y	Y	_	_	Y	Y	Y

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00020319	SNMP	3	ASN.01 BER padding is now enabled by default. This means that SNMP adds 0x00 padding when the most significant 9 bits of an object's value are all 1. Padding enables legacy SNMP NMS systems to correctly decode this value, and provide correct readings. Previously the default was for the encoding to follow the ASN.01 BER rule, which cuts off the most significant byte of 0xff. This setting has an impact on all integer type MIB objects, including 32 bit and 64 bit counter objects. To remove the padding, and return to using the ASN.01 BER encoding rule, use the command: set snmp asnberpadding={off no false}	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00020833	IP	3	When using IP NAT, TCP connections would have the sequence and/or acknowledgement numbers incorrectly altered by the router, which prevented the TCP connections from being properly set up. This issue has been fixed. Please note that NAT configured using the Firewall was unaffected by this issue.	Y	Y	Y	_		1	1	_	1		
CR00021128	Firewall, VRRP	3	Previously, when VRRP was configured on a router or switch that also had a Firewall NAT rule involving the same VRRP IP address, when the router or switch was in the Backup VRRP state it would reply to any incoming ARPs for the VRRP IP address with its own MAC address. This issue has been resolved. When VRRP is in the backup state, it will never reply to ARP requests for the VRRP IP address under any circumstances.	Y	Y	Y	Y	Y	Υ	_	_	_	-	Y

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00023040	GUI, Firewall	3	When configuring LAN to WAN Firewall rules via the GUI, the "Action" drop-down box was missing the "No NAT" option. This issue has been resolved.	Y	Y	Y	Y	_	Y	_	_	_	_	Y
CR00023083	IPsec	3	Previously, if the router or switch had IPsec policies create on multiple interfaces, it would sometimes fail to create a connection when it received a connection request from a valid peer. This was because the router or switch would sometimes use the wrong IPsec policy for the interface. This issue has been resolved.	Y	Y	Y	Y	Y	Y	_	_	_	_	_
CR00023393	PPP	3	If the router or switch was acting as a PPPoE Access Concentrator, and it was power-cycled or restarted, then re-establishing any existing PPPoE sessions could take longer than necessary. This was because the router or switch would send the incorrect PADT in response to PPPoE session packets sent from the existing PPPoE session (EtherType of 0x8664, the PPPoE Session Protocol). Some PPPoE clients would ignore this PADT, causing a delay before the PPPoE session was re-established. This issue has been resolved. The router or switch now send the correct PADT in response to any existing sessions after restarting (EtherType of 0x8663, the PPPoE Discovery Protocol).	Y	Y	Y	Y	Y	Y	_	_	Y	Y	Y

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00024495	OSPF	3	 Previously, if a new OSPF router ID was learned via an OSPF point-to-point (PTP) link, the original OSPF router ID was not removed from the show ospf neighbour command output. For PTP networks, incoming OSPF hello packets are used to update neighbour information. On an PTP interface, existing neighbours are matched by the router ID in the hello packet, whereas on other types of interfaces the neighbours are matched by source address. In the case of a PTP network, however, there are only ever 2 ends to the network and so there should only be one existing neighbour for the interface. This issue has been resolved. Now, if a new OSPF Router ID is learned via an OSPF PTP link, the original OSPF Router ID is removed from the show ospf neighbour command output. 	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00023042	VRRP	4	When a DNS query was sent to the VRRP-adopted virtual IP address on a router or switch, the relayed-response would have a source IP address of the interface it was sent from, instead of the virtual IP address. This issue has been fixed. DNS relay replies will now use the VRRP virtual IP address as their source address if the original query was sent to the VRRP virtual IP address.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

Enhancements

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00019005	DHCP snooping	-	The restriction on classifiers for DHCP snooping has been removed. This means that you can now specify a classifier number from 1 to 9999 when creating a DHCP snooping classifier. Previously, the range was restricted to classifiers numbered 1 to 100. The maximum number of DHCP snooping classifiers you can create has also increased to 520.	_	_	_	_	_	_	_	_	Y	Y	_

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00020057	DoS Attack Prevention	-	The AlliedWare TM Operating System now includes a Denial of Service Attack Protection feature for AT-8600 Series switches. This enhancement allows you to configure specific defences against the following types of DoS attacks: IP Options LAND Attack Ping of Death Attack Smurf Attack SYN Flood Attack Teardrop Attack For more information about configuring DoS Attack Prevention, see the <i>AlliedWare™ Operating System Software Reference for Version 2.9.1 DoS</i> <i>Attack Prevention Edition</i> available for AT-8600 Series switches. You can download this software reference from: www.alliedtelesis.co.nz/documentation/	_		1			-	Y		_		
CR00020882	Firewall	-	A new compatibility mode allows the firewall to interoperate with the SAMSUNG SmartViewer 2.0 for ProDVR application. This application uses RSTP over TCP to communicate with SAMSUNG IP security cameras. To use this application on a router or switch with a firewall configured, you must add a new application rule for RTSP to your firewall policy: add firewall policy=[policy-name] apprule=app-rule-id action=allow interface=[interface] application=rtsp compatibility=smartviewer	Y	Y	Y	Y	Y	Y	_	_	_	_	Y

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR7505 / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00021615	ADSL, Core	-	With this software version, AR441S routers with a hardware revision of M1-2 (or later) will support ADSL2 and ADSL2+ connections. You can see the hardware revision of a router by entering the command show system and checking the "Rev" column for the "Base" board.	Y	_		_	_	_	_	_	-	_	
			 When running this software version, AR441S routers with rev M1-2: have the following new options for the command set adsl standard: adsl2 adsl2plus auto2plus connect only to devices offering ADSL2+ connect at ADSL2+ if this is offered by the other end device (CO), or otherwise automatically fall back to what is offered 											
			have a default ADSL standard setting of auto2plus											
			 behave as they currently do for other ADSL standard settings When running this software version, existing AR441S routers with a hardware revision of M1-1 or earlier: do not have the new options adsl2, adsl2plus, or auto2plus for the command set adsl standard 											
			still use the existing default ADSL standard setting of auto , which allows automatic fallback connection for ADSL standards only.											
CR00023867	Switching	-	The maximum number of uplink ports available for private VLANS has increased from 50 to 150.	_	_	_	Y	Y	Y	Y	Y	_	-	_

CR	Module	Level	Description	AR44x / AR450	AR7×5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	АТ-9900	AT-9800
CR00023990	РРР	-	Two new parameters, ipfilter and ipfragment , are now available for the create ppp template and set ppp template commands: create ppp template=ppp-template [ipfilter=NONE 0999] [ipfragment=ON OFf True False Yes No] set ppp template=ppp-template [ipfilter=NONE 0999] [ipfragment=ON OFf True False Yes No] These parameters are useful when a dynamic IP interface is created over the dynamic PPP interface. The shortest valid strings are ipfi for ipfilter and ipfr for ipfragment . The ipfilter parameter specifies the traffic filter to apply to IP packets transmitted or received over the dynamic IP interface. The filter must already have been defined with the add ip filter command. The dynamic IP interface may have a maximum of one traffic filter but the same traffic filter can be assigned to more than one interface. Traffic filters are applied to packets received via the dynamic IP interface. The default is to not apply a filter. The ipfragment parameter specifies whether the "Do not fragment" bit is obeyed for outgoing IP packets that are larger than the MTU of the interface. If yes , the "Do not fragment" bit is ignored and outgoing IP packets larger than the MTU of the interface are fragmented. This is particularly useful for interfaces configured with GRE, SA, or IPsec encapsulation, which can potentially increase packet sizes beyond the MTU of the interface. If no , the "Do not fragment" bit is obeyed and IP packets larger than the MTU are discarded. This is normal behaviour for IP. The fragment parameter has no effect on packets smaller than the interface MTU. The default is no .	Y	Υ	Y	Y	Y	Y			Y	Υ	Y

Software Maintenance Version 291-16 includes the resolved issues and enhancements in the following tables. In the tables, for each product series:

- "Y" indicates that the resolution is available in Version 291-16 for that product series.
- "-" indicates that the issue did not apply to that product series.

Level 1

No level 1 issues.

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00017581	Firewall	2	Sometimes in congested networks, when processing certain out-of-order FTP or RSTP TCP packets the firewall could leak some memory. This issue has been resolved.	Y	Y	Y	Y	_	Y	-	_	_	_	Y
CR00019431	Bridge, L2TP, PPP	2	With some L2TP/PPP configurations, disabling the port or removing the cable from the port caused the router to reboot. Improvements related to this issue were made in software version 291-12. This version contains further improvements to prevent the issue occurring.	Y	Y	Y	Y	Y	Y	_	_	_	_	_
CR00020257	АТМ	2	With M3 versions of the AR441S, sometimes when the router was restarted the ADSL link would come up, but packets larger than two cells would often be received with CRC errors and discarded. This issue has been resolved.	Y	_	_	_	_	_	_	_	_	_	_

CR	Module	Level	Description	AR44x / AR450	AR7×5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00020937	QoS	2	 Under some configurations, the switch could reboot when: applying a QoS policy to the same port twice (by using the command set qos port=x policy=x). adding classifiers to a QoS flowgroup that has not been associated with a policy or traffic classifier. These issues have been resolved. 	_	_	_	Y	Y	Y	Y	Y	Y	Y	Y
CR00021623	Switching	2	Previously when a MAC learning limit was enabled along with MAC re- learning for a switch port, if the same MAC addresses were learnt by another port in the same vlan (a 'station move' event), the learn limit on the first port was not decremented even though the MAC addresses were no longer tied to it. This would mean that after the port reached its learn limit, it would stop learning any new MAC addresses even if all of the previously learnt addresses were then moved to different ports. This issue has been resolved. Now when a MAC address undergoes a 'station move' event, the learn counter of the first switch port will be decremented when the MAC is removed, so the port can no longer get into a state where it will refuse to learn more MAC addresses.	_		_	_	_	_	_	_	Y	Y	-
CR00021993	EPSR	2	Previously when an EPSR+ ring was recovering from multiple link failure, IP connectivity could be lost for longer than necessary. This issue has been resolved.	-	_	_	_	_	_	_	_	Y	Y	-
CR00022057	IPv6	2	Previously, if a router or switch received a neighbour discovery advertisement with a target link-layer address option of 00-00-00-00- 00, the device may have restarted. This issue has been resolved.	Y	Y	Y	Y	Y	Y	-	-	Y	Y	Y

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00022153	DHCP	2	Previously, on a router or switch using multihoming, the DHCP server on the router or switch could sometimes assign multiple IP address to the same client. This occurred when a client's DHCP Discover message was received through more than one logical interface on the router or switch. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00022292	Switching	2	On some occasions, inserting an Allied Telesis AT-G8T copper GBIC stopped the GBIC ports from operating correctly. The GBIC LEDs would also display the wrong state (lit when the GBIC was removed or off when the GBIC was inserted). This issue has been resolved.	_	_	_	_	_	Y	_	_	-	_	Y
CR00022437	IPsec, LT2P	2	Previously some specific network configurations would not work when L2TP was secured with IPsec transport mode through NAT. This issue has been resolved.	Y	Y	Y	Y	Y	Y	_	_	_	-	_
CR00022482	LLDP	2	Previously a downstream device could learn the router or switch's MAC address when it received an LLDP DU. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00022545	L2TP	2	Previously, when a router or switch at one end of an L2TP tunnel rebooted, it would have to wait for the tunnel on the other end to timeout before it could recreate the tunnel. This caused a delay in recreating the tunnels after a restart. This issue has been resolved. Also, under some situations, when an L2TP tunnel was destroyed the router or switch would crash. This issue has been resolved.	Y	Y	Y	Y	Y	Y	_	_	Y	Y	Y

				44x / AR450	7x5	750S / AR770S	pier i	pier w	8800	8600	8700XL	8948 / x900-48	0066	9800
CR	Module	Level	Description	AR	AR	AR	Ra	Raj	AT	AT	AT	AF	ΑŢ	АŢ
CR00022596	Port Authentication	2	 Previously on an AR-770s, the command: enable portauth=8021x port=<i>portid</i> type=authenticator guestvlan=<i>vlanid</i> would not add the specified port to the specified guest VLAN if executed from the device boot configuration script. This issue has been resolved. 	-	_	Y	_	_	_	_	_	-	-	_
CR00022647	ΒΟΟΤΡ	2	Previously if a router or switch acting as a BOOTP relay had two subnets, and one was a super net of the other, the router or switch could forward DHCP messages with the broadcast flag set to the wrong interface. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00022985	L2TP	2	Previously, under some heavy load traffic conditions, L2TP tunnels would experience a periodic latency or sometimes no longer function. This issue has been resolved.	Y	Y	Y	Y	Y	Y	_	_	Y	Y	Y
CR00022993	PIMv4	2	Previously on specific network configurations, using PIM Sparse Mode could cause a memory leak. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	_	Y	Y	Y
CR00023012	IP	2	A security vulnerability was found in the design of the DNS protocol. This vulnerability has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00023053	BGP	2	A security vulnerability was found in the implementation of BGP. This vulnerability has been resolved.	Y	Y	Y	Y	Y	Y	-	_	Y	Y	Y
CR00023082	RADIUS	2	RADIUS servers can specify multiple dynamic routes to a user, in addition to the normal host specific route to the allocated address. These additional routes are called framed-routes in RADIUS configuration definition. Previously, the maximum number of framed-routes that could be created by the RADIUS server on the router or switch were limited to 2 per client. This limit has increased to 32 routes.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00023347	LT2P, IPsec	2	Previously, the router or switch could reboot while a L2TP tunnel was being established over an IPsec connection. This occurred only when the device received either:	Y	Y	Y	Y	Y	Y	_	_	_	_	_
			 a request to establish a secure channel from a source that does not match an IPsec policy, or 											
			 a L2TP call disconnection notification (CDN) or a Stop Connection (StopCCN) with values outside of those specified by the L2TP RFC. 											
			This issue has been resolved.											

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00021620	STP	3	Previously the set mstp cist port command parameters intpathcost and extpathcost could not have the value default set. This issue has been resolved.	-	_	_	Y	Y	Y	Y	Y	Y	Y	-
CR00021821	IPsec	3	In certain situations on an IPsec network, queued packets were not discarded despite reaching their retry timeout period. While a router or switch is establishing a Security Authorisation with its peer, it keeps a queue of the packets waiting to be sent across the network. These packets have a retry timeout period and if this period is reached, the packets should be discarded. This issue has been resolved. Packets that reach their retry period are now discarded from the queue.	Y	Y	Y	Y	Y	Y	-	_	-	_	_
CR00022301	Bridging	3	Previously if ATM was used as the WAN interface in a remote bridge and the bridge had more than 1 VLAN, then the VLAN module would drop the bridged frames. This issue has been resolved.	Y	-	_	_	_	_	_	_	_	_	-
CR00023011	LT2P, Firewall	3	Previously, the firewall on the router or switch would block some L2TP control messages during a route change (for example, when a PPP connection was coming up). This issue has been resolved.	Y	Y	Y	Y	Y	Y	_	-	_	_	Y

Level 4

No level 4 issues.

Enhancements

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR7505 / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00019706	РРР	-	A new parameter ipborrow has been added to the create and set ppp interface commands. You can set the ipborrow parameter to the values: yes on true no off false . This parameter is required in the following situation: the PPP interface has been configured as an unnumbered IP interface (i.e. configured with IP address 0.0.0.0), but you do not want the PPP peer to allocate an IP address to be used on the local PPP interface (i.e. iprequest=no). In this case, the router or switch needs to present a non-zero IP address to the peer during IPCP negotiation. The solution to this problem is to use another IP address that has been configured on the router or switch (invariably another interface on the device will have been configured with a non-zero IP address). With the ipborrow parameter, you can configure the unnumbered PPP interface to 'borrow' this other interface's IP address to use as the IP address it presents to the peer during IPCP negotiation. If there are multiple non-zero IP interfaces on the router or switch, you cannot specify which interface's IP address the unnumbered PPP will borrow; it will simply borrow the IP address from the interface with the	Y	Y	Y	Y	Y	Y		_	Y	Y	Y
CR00021106	IPsec, ISAKMP	-	lowest ifindex. You can now specify peers in ISAKMP and IPsec policies using a DNS name. Previously, you could only specify the peers using an IP address.	Y	Y	Y	Y	_	Y	_	-		_	_

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00021262	IPsec	-	 This enhancement has improved router or switch performance when: multiple IPsec policies exist. In particular, having two policies causes much less of a reduction in performance. a single channel exists with bidirectional traffic (i.e. the single channel is both encoding and decoding packets). Some improvements for this situation were made in 291-15. This version contains further improvements. 	Y	Y	Y	Y	_	Y	_	_	_	_	_
CR00021769	SNMP	-	A new command set snmp trapdelay has been added to allow SNMP traps to be queued for a specified time at start up. By default, all SNMP traps are queued for 10 seconds following startup. This allows time for links to come up on the router or switch. However sometimes this is not enough time for other network protocols to converge and open up transmission paths to the SNMP management station. The set snmp trapdelay command allows you configure a longer delay of up to 10 minutes on an SNMP trap. To change the delay, use the command: SET SNMP TRapdelay=10600 The default is 10 seconds.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00021852	EPSR	-	An enhancement has been made to EPSR to speed up recovery time in situations where the Master switch is isolated or down. In these situations, if any links between transit nodes go down and are restored, the transit nodes are now able to put the recovered ports back into a forwarding state even without messaging from the Master switch. This means that connectivity around the ring can be partially restored before communication with the Master has been restored. The mechanism by which the transit nodes make this decision operates in a way that prevents the possibility of the ring ever becoming unprotected.	-	_	_	_	_	_	_	_	Y	Y	

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00022331	SHDSL	-	Previously on AR442S routers, SHDSL train up times were variable and frequently longer than one minute. This enhancement reduces this variability and minimises the train up time required.	Y	_	_	_	-	_	-	-	-	-	-
CR00022832	SNMP	-	The set interface command now has the parameter trapdelay , which allows you to delay the transmission of SNMP link status traps from 0 to 60 seconds. This is useful for situations where the SNMP link status traps need to wait for route tables to be updated or other protocols to process the link change event before being transmitted. The new command is: set Interface={ <i>iflndex</i> <i>interface</i> } trapdelay=060 Note that you cannot set a delay on a dynamic interface. The default is 0 . The output of the show interface = <i>interface</i> command now displays the value for this parameter. Note that this changes the behaviour set by CR00021581 in software version 2.9.1-15, which introduced a fixed 5 second delay for link status traps.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

Software Maintenance Version 291-15 includes the resolved issues and enhancements in the following tables. In the tables, for each product series:

- "Y" indicates that the resolution is available in Version 291-15 for that product series.
- "-" indicates that the issue did not apply to that product series.

Level 1

No level 1 issues.

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00020914	DVMRP	2	When using DVMRP for multicast traffic, if the router or switch received a leave request from the last remaining client in a multicast group before it could fully establish the DVMRP session for that group, the router or switch would not send a prune message to the upstream router and would continue to receive multicast traffic for that group. This issue has been resolved.	Y	\prec	Y	Y	Y	Y			Y	Y	Y
CR00021146	EPSR	2	Previously, it was possible for non-EPSR messages such as IGMP snooping query solicitation messages to be sent on the EPSR control VLAN if the control VLAN was part of an STP topology. Since the control VLAN is designed as an intentional loop so that the master node can monitor the integrity of the loop, other messages on the control VLAN can form a packet storm. This issue has been resolved. All switches in an EPSR ring now discard all non-EPSR messages on the control VLAN.	_	-	-	-	-	-	_	_	Y	Y	_

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	АТ-9900	AT-9800
CR00021342	BGP	2	A small memory leak was occurring when receiving BGP update messages. This issue has been resolved.	Y	Y	Y	Y	Y	Y	_	_	Y	Y	Y
CR00021491	DVMRP	2	When DVMRP had pruned an incoming multicast stream, if that stream continued to be transmitted and pruned correctly, after 24 hours the downstream DVMRP neighbour could stop successfully pruning that stream. At this point the downstream neighbour would be receiving the traffic on the interface even though it had no downstream receivers. This issue has been resolved.	Y	Y	Y	Y	Y	Y			Y	Y	Y
CR00020593	Firewall	2	When using multiple firewall policies, TCP connections created across the policies would have any TCP options (such as timestamps or window scaling) stripped out of the SYN packets. This could cause slow downs or other problems for programs that rely on those TCP options being present. This has been resolved—the TCP options will no longer be stripped from the SYN packets in this case. Also, the RFC 1323 TCP window scaling option, if present, would not be correctly applied to FTP data connections (FTP connections on port 20), resulting in low throughput for FTP file transfers. This issue has been resolved.	Y	Y	Y	Y	_	Y	_	_	_	_	Y
CR00020643	Flash file system	2	An error in the flash file rename code could occasionally result in flash file system header corruption, leading to flash file system inconsistencies. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00020677	IPsec	2	Previously, one of the memory buffers displayed in output of the command show buffer scan was periodically increasing, because of an IPsec issue. This issue has been resolved.	Y	Y	Y	Y	_	Y	_	_	_	_	_
CR00020700	WAN load balancing	2	Previously, AR750S and AR770S routers required a special feature license for WAN load balancer. This issue has been resolved. A license is no longer required for these routers.	-	-	Y	-	-	-	-	-	_	-	_

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00021006	Switching	2	When ingress filtering was enabled on a port and a packet arrived on that port with a VLAN identifier that the port was not a member of, the source MAC address would be incorrectly learnt. This issue has been resolved and in this situation the MAC address is no longer added to the forwarding database.	_	_	_	_	_	_	_	_	Y	Y	_
CR00021259	Switching, VLAN	2	If a VLAN-tagged ARP request was received with a VLAN ID of a VLAN that had previously existed but had been destroyed, the switch could reboot. This issue has been resolved.	_	_	_	_	_	_	_	_	Y	Y	_
CR00021308	OSPF	2	In a configuration where two otherwise identical external OSPF routes had been learnt to a particular destination over two different interfaces, when one of the interfaces went down both routes would be permanently removed from the routing table and would not be added until OSPF was reset. This issue has been resolved. Only the route belonging to the downed interface will be removed.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00021978	Switching	2	If an ARP was received on a port and the MAC associated with that ARP subsequently moved to another port and had a new IP associated with it, and the new port was on a different switch instance, then when the original ARP timed out, the MAC would be removed from the switch's forwarding database. This only happened if the ARP moved across switch instances. This issue has been resolved.	_	_	_	_	_	_	_	_	Y	Y	-

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR7505 / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00020551	DHCP	3	Previously, when an AT-8600 series switch was acting as a DHCP server with a range defined, frequent Flash memory compactions would occur. This issue has been resolved.	_	_	_	-	Ι	_	Y	_	_	_	_
CR00020710	Switching	3	The show switch fdb port= < <i>number></i> command was displaying FDB information on incorrect ports. This issue has been resolved. Also, if the show switch fdb port= < <i>number></i> command is run where the port specified is in a trunk, all FDB entries for that trunk will be displayed, irrespective of which actual port the source MAC ingressed.	_	_	_	_	_	_		_	Y	Y	
CR00020794	Switching	3	If a user set a description on an AT-9924 switch port and then used the command show int counter or show int= < <i>id></i> to display interface counters, the command output would include counters called ifInDiscards and ifOutDiscards. However, these counters do not apply to these switches. This issue has been resolved, so these counters no longer display.	_	_	_			_		_	_	Y	
CR00020795	Switching	3	Previously, conditions existed where it was possible to remove a GBIC from a AT-8800 or AT-8600 series switch, but have the GBIC LED stay on. This could occur if a GBIC had been inserted into the switch in such a way that the GBIC pins did not all make electrical connection at the same time. This issue has been resolved. Removing a GBIC now always results in the LED being turned off.	_	_	_	_	_	Y	Y	_	_	_	
CR00021265	IP gateway	3	If the traceroute command was used from a Windows-based device to trace the path to a destination through a switch which had two potential return paths, then the traceroute command did not always produce the correct results. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR7505 / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00021267	Bridging	3	If the router received a CDP packet, and CDP was disabled (the default state), and bridging was configured, then the packet would not be bridged. This issue has been resolved.	Y	Y	Y		_	_	_	_	Ι	_	_
CR00021581	SNMP	3	Previously, the switch did not always successfully transmit SNMP link status traps. This issue has been resolved. SNMP link status traps are now delayed for 5 seconds to allow lower layer interfaces to come up.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00021766	Switching	4	If a port was set as a loopback on an AT-8948 or x900-48FE series switch, and was configured with a speed of 10mhauto , the LEDs did not display correctly. This issue has been resolved.	-	_	_	-	-	-	_	-	Y	-	-
CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
--------------------------	--------	-------	--	---------------	-------	-----------------	----------	----------	---------	---------	-----------	-------------------	---------	---------
CR00018895	SSH	-	Secure Shell (SSH) no longer requires a feature licence. SSH server and client functionality now works when no feature licence is present.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00020566 CR00021186	EPSR	-	This software version includes support for EPSR+ with enhanced multiple link recovery. This enhancement enables an EPSR ring to recover from simultaneous failure of multiple links or units, no matter where in the ring these failures occur. With enhanced recovery, if a ring has multiple points of failure, and then one point recovers, the recovered point will start processing traffic even if other points are still down. This keeps as much of the ring available as possible. To enable enhanced recovery, use one of the commands: create epsr= $$ enhance=on set epsr= $$ enhance=on Note that you must enable enhanced recovery on the master node and every transit node within the EPSR domain. Enhanced recovery is disabled by default, to allow interoperation with other implementations that are based on RFC 3619. To disable enhanced recovery, use one of the commands: create epsr= $$ enhance=off set epsr= $$ enhance=off set epsr= $$ enhance=off To see whether it is enabled or disabled, use the command: show epsr and check the "Enhanced Recovery" field.		_				-			Y	Y	

CR	Module	Level		Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	АТ-9900	AT-9800
CR00021061	NSM	-	This software and Rapier 4 identify the r	e version includes support for new variants of the Rapier 24i 8w switches, which have new NSM bay connectors. You can new switch variants by the following board IDs:	-	_	_	Y	Y	_	_	_	_	_	_
			Board ID	Name (as displayed by show system)											
			311	AT-RP24i-B Rapier 24i NEBS											
			312	AT-RP24i-B Rapier 24i DC NEBS											
			302	AT-RP48w-B-15 Rapier 48w-AC											
			300	AT-RP48w-B-85 Rapier 48w											
			The new con	nectors are compatible with the following new NSM variants:											
			Board ID	Name											
			212												
			217												
			514												
			Only the new Rapier 48w s IDs of 87 and	v switch variants can use the new NSMs. Other Rapier 24i and witches continue to use the original NSMs (which have board 187).											
CR00021262	IPsec	-	This enhance	ment has improved router or switch performance when:	Υ	Y	Y	Y	-	Y	-	-	-	_	-
			multiple II much less	Psec policies exist. In particular, having two policies causes of a reduction in performance.											
			■ a single ch both enco	nannel exists with bidirectional traffic (i.e. the single channel is oding and decoding packets).											

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00021304	IPsec	-	 Changes have been made to reduce the risk of packet loss over a VPN under very high traffic levels and corresponding high-to-overload CPU conditions. The number of input buffers allowed for IPsec message processing has been increased, to mitigate brief (<50ms) periods of CPU overload where the arrival of IPsec packets can exceed the router or switch's ability to process them in real time. This prevents packet loss. Processing of the ISAKMP heartbeat between two peer routers or switches has been given the highest priority over packet stream encryption, to ensure that the security authorisation synchronisation is not lost during high traffic rates. Loss of synchronisation results in packet loss until a resynchronisation completes. 	Y	Y	Y	Y		Y	_	_		_	_
CR00021752	SHDSL, GUI	-	It is now possible to use the web-based GUI to display SHDSL counters and statistics on AR442S routers. The new pages are available from the left- hand menu under: Diagnostics > Layer 1 Counters > SHDSL Counters Diagnostics > SHDSL Statistics.	Y	_	_	_	_	_	_	_	_	_	_

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00021896	VLAN	-	This enhancement enables administrative (virtual) activation of VLANs. When a VLAN is activated virtually, its IP interface is active (and therefore usable) even if all its ports are physically disconnected. The IP interface associated with the virtually activated VLAN can be operated by protocols such as OSPF, BGP, and RIP. VLAN activation is useful for VLANs that are reached through L2TP tunnels	Y	_	Y	Y	Y	Y	Y	Y	Y	Y	Y
			 instead of through switch ports. To turn virtual activation on or off, use the command: SET VLAN={vlan-name 14094 ALL} VIRTActivation ={Yes No} The default is no. To see whether the VLAN has been activated virtually, use the command show vlan and check the new "Admin Active" field. This enhancement was previously only available on Rapier, AT-8800, 											
			AT-8600 and AT-8700XL switches. Now it is available on all devices that support VLANs.											

Features in 291-14

Software Maintenance Version 291-14 includes the resolved issues and enhancements in the following tables. In the tables, for each product series:

- "Y" in a white column indicates that the resolution is available in Version 291-14 for that product series.
- "-" in a white column indicates that the issue did not apply to that product series.
- a grey-shaded column indicates that Version 291-14 was not released on that product series.

"-" in a grey column indicates that the issue did not apply to that product series.

"Y" in a grey column indicates that the issue applied to that product series. These issues are resolved in the next Version (291-15).

Level 1

No level 1 issues.

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00019178	VRRP	2	When using monitored interfaces in conjunction with VRRP, if a primary master device was brought into the backup state by the monitored interface going down, it would continue to reply to ARP requests for the virtual IP address with its own MAC address. This issue has been resolved. The device will now ignore ARP requests in this situation.	Y	Y	Y	Υ	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR7505 / AR7705	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00020266	Switching	2	If a network event caused the switch to flush its layer 2 forwarding database (FDB) for a port, in some circumstances the switch also flushed hardware ARP entries that hardware layer 3 routes were still using. Possible triggers included an STP topology change somewhere else in the network, or a link flap on a port. Depending on the network configuration and/or network traffic, this issue could result in incorrectly layer 3 switched traffic. This issue has been resolved.	_		_	_	_	_	_		Υ	Υ	_
CR00020413	DHCP snooping, IGMP snooping	2	 IGMP snooping did not correctly snoop IGMP traffic that arrived on an untrusted DHCP snooping port. This issue has been resolved. IGMP packets are processed now, unless IP filtering is enabled in DHCP snooping. Note that IP filtering is enabled by default, so the switch will drop IGMP packets by default if DHCP snooping does not have the source host as a current valid entry in the DHCP snooping database. To disable or enable IP filtering in DHCP snooping, use the commands: disable dhcpsnooping ipfiltering enable dhcpsnooping ipfiltering DHCP snooping must be enabled for IP filtering to take affect, but IP filtering cannot be disabled or enabled while DHCP snooping is enabled. 	_	_	_	Y	Y	Y	Y	Y	Y	Y	_
CR00020759	Switching	2	On AT-8948 switches running version 291-13, SFPs did not work—the link did not come up. This issue has been resolved.	-	_	_	-	-	-	_	_	Y	_	-

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR7505 / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00015046	L2TP	3	When the L2TP speed was changed, output of the command show ppp util still showed the old speed. This issue has been resolved. The previous behaviour was not incorrect, because the new speed only takes effect when the L2TP tunnel is restarted by deactivating and reactivating the call. The router or switch now displays a message to indicate this.	Y	Y	Y	Y	Y	Y	_	_	Y	Y	Y
CR00019267	Hotswapping	3	Occasionally, AT-8948 and x900-48 series switches rebooted or gave an invalid error message when hotswapping a PSU or FOM unit in. The invalid error message was about an airflow direction mismatch. The PSU or FOM would function correctly, but the switch would display incorrect information in output of the show system command. This issue has been resolved so that the switch does not reboot. If the error occurs, the switch displays a console message to indicate that a failure occurred when hotswapping in, and a log message will record the failure. If there was a failure when hotswapping the PSU or FOM in, the switch will display a console message when the PSU or FOM is swapped out.	_	_	_	_	_	_	_	_	Y	_	
CR00020168	L2TP	3	If the router or switch attempted to establish an L2TP tunnel over a link that was down, multiple tunnels were created when the link was re-established. This issue has been resolved.	Y	Y	Y	Y	Y	Y	_	_	Y	Y	Y

Level 4

No level 4 issues.

Enhancements

No enhancements.

Features in 291-13

Software Maintenance Version 291-13 includes the resolved issues and enhancements in the following tables. In the tables, for each product series:

- "Y" indicates that the resolution is available in Version 291-13 for that product series.
- "-" indicates that the issue did not apply to that product series.

Level 1

No level 1 issues.

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00018575	L2TP	2	If an L2TP tunnel had a large number of PPP interfaces over it, and the link that the L2TP tunnel was over went down, the router or switch might restart. This issue has been resolved.	Y	Y	Y	Y	Y	Y	_	_	Y	Y	Y
CR00019285	SHDSL	2	The AR442S router's SHDSL interface would not "train up" with some Alcatel DSLAMs, because of an EOC message exchange issue. This issue has been resolved. Some other issues with EOC message reception were also resolved.	Y	_	-		_	_	_	_	_	_	_
CR00020240	ΡΙΜ	2	In PIM, if the RPF neighbour to the source or the RP changed as a result of a unicast route change, and there were slow route updates, and that meant a new route to the RPF could not be found within 5 seconds, then multicast traffic would not resume correctly once the new routing information was learned. This issue has been resolved.	Y	Y	Y	Y	Y	Y	_	_	Y	Y	Y

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00020253	IP gateway	2	If multicast traffic was being forwarded to a PPP interface and that PPP interface went down, the router or switch would restart. This issue has been resolved.	Y	Y	Y	Y	Y	Y	1		Y	Y	Y
CR00020436	DHCP snooping	2	DHCP Snooping did not correctly block traffic from untrusted IP addresses, because it did not correctly create the required filters. This issue has been resolved. Note that this issue did not apply on x900-48, AT-8948, or AT-9900 series switches, because you create the filters manually on those switches.	_	_	_	Y	Y	Y	Y	Y	_	_	_
CR00020522	DHCP snooping	2	If a client sent an ARP request to a DHCP Snooping switch, the DHCP Snooping switch would drop the ARP packet at its CPU. This issue has been resolved. Note that this issue did not apply on x900-48, AT-8948, or AT-9900 series switches.	-	_	_	Y	Y	Y	Y	Y	_	_	_

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00010538	Firewall	3	When firewall events were recorded in the Notify queue (displayed in output of the command show firewall event=notify), the IP address shown would be the address of the very first packet that belonged to that event flow. For example, if 64 host scan packets were required to trigger a host scan event and the first packet had a target IP of 1.1.1.1 and the 64th had an IP of 1.1.1.64, then the IP address recorded would be 1.1.1.1, even though the event was not actually recorded until the 64th packet arrived. Additionally, the source and destination ports in this display would always show as 0. These issues have been resolved. The IP addresses shown are now those of the particular packet that triggered the event notification, and the source and destination ports used by that packet. These issues were partially resolved in an earlier version—this version contains an improved resolution.	Y	Y	Y	Y	Y	Y	_		-	_	Y
CR00019207	Switching	3	A small number of x900-48 series switches were experiencing link problems for some ports with some SFPs. This issue has been resolved.		I	-	_	Ι	_	_		Y	Ι	Ι
CR00020023	RSTP, SNMP	3	If the STP state of a switch port in a Rapid Spanning Tree was monitored via SNMP using the BRIDGE-MIB, the value reported for a port in the Alternate role was Listening when it should have been Blocking. Similarly, Blocking was reported for a port in the Disabled role when it should have been Disabled. This issue has been resolved.	_	-	_	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00020243	SNMP, IP gateway	3	Previously, the router or switch would respond to SNMP requests destined for broadcast addresses. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00020320	IPsec, IP gateway	3	In some configurations using PPPoE and IPsec, inappropriate ICMP redirect messages would be generated. This issue has been resolved.	Y	Y	Y	Y	_	Y	_	_	_	_	_
CR00020354	Switching	3	AT-8848 switches would drop DHCP packets if they ingressed at a port on one switch instance and should have egressed out a port in the other switch instance. Ports 1 to 24 and the uplink port 50 are on instance 0. Ports 25 to 48 and the uplink port 49 are on instance 1. This issue has been resolved.	_	_	_	_	_	Y	_		_	_	
CR00020376	SNMP, IGMP	3	SNMP could not always access all the group members in the IGMP interface group table. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

Level 4

No level 4 issues.

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00017819	MACFF	-	MAC-forced forwarding static server entries and debugging has been improved. For details, see "MAC-forced forwarding enhancements (CR00017819)" on page 235.	_	_	_	Y	Y	Y	Y	Y	Y	Y	-
CR00019547	VLAN	-	This enhancement enables administrative (virtual) activation of VLANs. When a VLAN is activated virtually, its IP interface is active (and therefore usable) even if all its ports are physically disconnected. The IP interface associated with the virtually activated VLAN can be operated by protocols such as OSPF, BGP, and RIP. VLAN activation is useful for VLANs that are reached through L2TP tunnels instead of through switch ports. To turn virtual activation on or off, use the command:	-	_	_	Y	Y	Y	Y	Y	_	_	_
			SET VLAN={vlan-name 14094 ALL} VIRTActivation ={Yes No} The default is no . To see whether the VLAN has been activated virtually, use the command show vlan and check the new "Admin Active" field.											

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00020309 CR00020326	BRI	-	This release adds support for the V3 hardware revision of the AT-AR021 BRI-S/T Port Interface Card (PIC). The AT-AR021 V3 hardware revision is a plug-in replacement for the V2 hardware revision, which is no longer available. The AR021v3 has the same feature set and command set as the AR021v2, except that it does not support NT mode operation. Existing configurations for normal TE mode operation will run unchanged on the AR021v3. The AR021v3 PIC can be installed in the following expansion bays:	Y	Y	Y	Y	Y	_	_	_	_	_	_
			 PIC bays on the AR415S, AR440S, AR441S, AR442S, AR725, AR745, AR750S, AR750S-DP, and AR770S routers AT-AR040 NSM installed in the AR745 router, Rapier 16fi, Rapier 24i, and Rapier 48w switches. 											
CR00020370	Switching	-	Support for the RoHS-compliant AT-G8T GBIC was added for AT-9800 series switches. Before this, the GBIC would fail to link up with the slide switch set to auto (its default position).	_	_	_	_	_	_	_	_	_	_	Y

Features in 291-12

Software Maintenance Version 291-12 includes the resolved issues and enhancements in the following tables. In the tables, for each product series:

- "Y" indicates that the resolution is available in Version 291-12 for that product series.
- "-" indicates that the issue did not apply to that product series.

Level 1

No level 1 issues.

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00019066	L2TP	2	Under certain conditions, entering the show l2tp tun call command would cause the router or switch to reboot. This issue has been resolved.	Y	Y	Y	Y	Y	Y	_	_	Y	Y	Y
CR00019431	Bridge, L2TP, PPP	2	With some L2TP/PPP configurations, disabling the port or removing the cable from the port caused the router to reboot. This issue has been resolved.	Y	Y	Y	Y	Y	Y	_	_	-	-	_
CR00019923	LACP, VLAN	2	The switch sometimes rebooted if a port was added to a private or nested VLAN when LACP was enabled. This issue has been resolved.	_	_	_	_	_	_	_	-	Y	Y	_
CR00020051	Switching	2	If trunked ports were quickly removed from a device (for example, by powering off the device that the trunked ports were connected to), it was possible for the trunk's master port to become a port that was not a member of the trunk. This issue has been resolved.	_	_	_	Y	Y	Y	Y	Y	_	_	_

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00018949	Core	3	When a PSU or FOM was hotswapped and replaced with a new unit of the same type, the switch did not update the serial number of the hotswapped unit. Output of the commands show system and show log displayed the serial number of the previous unit. The same issue occurred with PICs in NSM units. For example, if you hot swapped out an NSM with a BRI PIC and then replaced that PIC with another identical PIC, and then hot swapped the NSM back into the bay, the new PIC's serial number was not displayed. This issue has been resolved.	Y	Y	Y	Y	×	-	_	_	Y	Y	
CR00019557	IPsec	3	Previously, if the router was trying to establish a VPN and the peer sent a proposal that had more than 4 transforms in it, the router did not establish the VPN, and could reboot. In IPsec, each transform specifies a possible set of security parameters for the proposed tunnel. You can see the number of transforms in a VPN proposal by entering the command enable isakmp debug , attempting to establish the tunnel, and looking for messages with text like: Proposal#: 1 Protocol: ESP(3) #Trans: 8 SPI: 9624fe10 Transform#: 1 This issue has been resolved. The router now accepts and can send proposals with up to 10 transforms, although it is unusual to need more than 4. Also, if the router receives a proposal with too many transforms, it sends an error message in response instead of rebooting.	Y	Y	Y	Y		Υ				_	

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00019870	Firewall	3	The firewall's TCP Setup Proxy did not always calculate the MSS value correctly. Instead, it would sometimes set the MSS value to 536 bytes, regardless of the MSS value in the incoming SYN packet. This issue has been resolved.	Y	Y	Y	Y	_	Y	_	_	_	Η	Y
CR00020045	SNMP	3	When using an SNMP browser to manager the Rapier 16fi, a user may have seen an incorrect System Identity reported for variants with MT-RJ fibre ports. This issue has been resolved.	_	_	_	Y	_	_	_	_	_	_	_
CR00005048	GUI	3	When using the web-based GUI to add an IP Interface to a PPP connection, not all the available PPP instances were selectable. This issue has been resolved. Additionally, you can now use the GUI to give an ethernet interface a DHCP-assigned IP address, and to enable or disable the IP request option for PPP dynamic assignment.	Y	_	Y	_	_	_	_	-	-	_	_

Level 4

No level 4 issues.

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00018418	igmp, mib	-	AlliedWare now includes an IGMP Group MIB. This MIB is available in the file at-igmp.mib. It has the object identifier prefix igmp ({ modules 139 }), and contains a collection of objects and traps for monitoring IGMP group membership. For more information, see "IGMP Group MIB (CR00018418)" on page 236.	Y	Y	Y	Y	Y	Y	Y	Y	Υ	Y	Y
CR00019548	PRI	-	With this enhancement, the show pri state command now displays any current loopback configuration and lists any running tests on PRI ports.	Y	Y	Y	Y	Y	-	_	_	_	_	

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00019989	Switching		A new command has been added to modify the operation of the switch when a packet uses the default hardware multicast route. This usually happens when the switch receives new unregistered multicast traffic. The command syntax is: SET SWItch DEFAultmrouteoperation={TRap ROUte DEFault} The defaultmrouteoperation parameter specifies the operation to perform on the first packet received for a multicast stream. If you specify trap or default , the packet is copied to the CPU for processing, and is also flooded to other ports in the VLAN. Under some circumstances, especially when an L3 multicast routing protocol such as PIM is configured, the packet may not be flooded correctly to other ports on the receiving upstream VLAN. If you specify route , the packet is copied to the CPU and also routed on the receiving upstream VLAN. In some circumstances this may change the packet's VLAN tag. The default is trap . Important: Setting this command to route changes the default behaviour of the switch hardware, may change the VLAN tag, and may cause issues in private VLAN configurations. We recommend that you only change this setting if clients on the receiving VLAN are not receiving the first packet of a new multicast stream and this is affecting the multicast service. To see the current setting, use the command show switch and check the entry called "Def. Multicast Route Op".			-		_	_	-		Y	Y	
CR00020024	Bridging	-	In Software Version 291-11, CR00019152 increased the maximum number of bridge ports supported, but with the trade-off of reduced bridging performance for small packets. This CR completes the enhancement by restoring bridging performance to its earlier level.	Y	Y	Y	Y	Y	-	-	-	-	-	-
CR00020146	IP gateway	-	The upper limit on the number of entries in an IP filter has been increased from 255 to 3072.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR44x / AR450	AR7x5	AR750S / AR770S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	AT-8948 / x900-48	AT-9900	AT-9800
CR00020171	Eth	-	Log entries are now generated when Ethernet port links are taken up or down. Typical log entries are: 26 11:37:18 6 ETH PINT DOWN ETH3: interface is DOWN 26 11:37:28 6 ETH PINT UP ETH3: interface is UP Note that AR022 PICs (ETH PICs) do not enter a log message after a restart if the link is up during that restart, but do enter a log message for each subsequent link transition.	Y	Y	Y	_	_	_	_	_	_	_	_

Features in 291-11

Software Maintenance Version 291-11 includes the resolved issues and enhancements in the following tables. In the tables, for each product series:

- "Y" indicates that the resolution is available in Version Version 291-20 for that product series.
- "-" indicates that the issue did not apply to that product series.

Level 1

No level 1 issues

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00000704	PPP, SYN	2	Previously when a SYN link failed and the link indication signal (e.g. Carrier Detect) was de-asserted, then output of show interface would show the SYN interface as down, but the PPP interface would remain up until PPP Link Quality Reporting (LQR) determined that the link was no longer operational. Depending on the LQR timer setting, this could take many seconds. This issue has been resolved. The PPP link now goes down within a few seconds of the SYN link going down.	Y	Y	Y	Y	Y	_	_	_	-		-
CR00007153	DHCPv6, IPv6, PIMv6, Software QoS	2	Previously, it was only possible to create 2048 IPv6 interfaces on switches with IPv6 support in hardware (x900-48 series switches and AT-8948 switches with an accelerator card installed). This issue has been resolved. You can now create up to 4096 IPv6 interfaces on these switches.	_	_	_	_	_	_	_	_	Y	-	_

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00007412	PIM, PIMv6	2	PIM Null-Register packets were being generated with incorrectly formatted dummy multicast data. This issue has been resolved, so that the packets conform to the formats specified in RFC 4601, Section 4.9.3. Register Message Format.	Y	Y	Y	Y	Y	Y	Y	_	Y	Y	Y
CR00008888	SYN	2	If a link-up SYN interface was disabled and then enabled again, or if the PPP link over that interface was reset, then the ifOperStatus would change to down and would not come back up again. This issue has been resolved.	Y	Y	Y	Y	Y	_	_	_	_	_	_
CR00010428	Switch	2	If 0.0.0.0 was specified as an IP address for a VLAN interface, the incorrect VLAN ID was written into the hardware routing table. This issue has been resolved.	_	_	_	_	_	_	_	_	_	-	Y
CR00013548	EPSR	2	Previously, if EPSR failed over, and some of the ports in the EPSR ring were trunked, and there were ARPs present on the non-master port, the ARPs would not be deleted. This meant that connectivity could be lost when the ring switched back. This issue has been resolved.	_	_	_	_	_	_	_	_	Y	Y	_
CR00016205	Firewall	2	The firewall did not allow any incoming traffic destined for a non-policy interface, including the local interface. This issue has been resolved. The firewall now allows traffic that comes from a private trusted interface and is destined for a local interface.	Y	Y	Y	Y	Y	Y	_	_	_	_	Y
CR00016331	Eth	2	With some link partners, an AR750S Ethernet port would stop receiving packets after some hours or days, and a link state cycle or interface reset was required to restore operation. This issue has been resolved.	_	_	Y	_	_	_	_	_	_		_
CR00017519	VLAN	2	ARP packets were not processed if they had been tagged with an 802.1p priority value. This issue has been resolved.	-	_	_	Y	Y	Y	Y	Y	Y	Y	-

CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00017540	Switch, Classifier	2	On AT-8948 and AT-9900 series switches, if a classifier matched on VLAN ID or interface, the switch did not correctly classify traffic. This stopped hardware filters or QoS policies from working if they used such classifiers. This issue has been resolved.	_	_	_	_	_	_	_	_	Y	Y	_
CR00017750	IP Gateway	2	When an IP interface went down, and the switch received traffic on another interface that was destined for the down interface's IP address, the switch no longer processed that traffic locally. Instead, it sent the traffic out its default route. For example, if vlan1 had an IP address of 192.168.1.1 and the switch received a ping on vlan2 for 192.168.1.1, then the switch would route the ping out its default route, instead of processing the ping packet and sending a ping reply message back. This issue has been resolved. Traffic that is directed at an IP interface will now be processed regardless of the link state of the interface itself.	_	_	_	_	_	_	_	_	Y	Y	_
CR00017751	IGMP	2	Previously, IGMP packets that had a source IP address of 0.0.0.0 were not accepted. This issue has been resolved. Such packets are now accepted and processed.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00017767	Switch	2	When the Ethernet interface of an AR770S router was under very heavy load it could, very occasionally, enter a mode which had a high latency for packets transmitted over the interface. This issue has been resolved.	_	-	Y	_	_	_	_	-	-	_	_
CR00018035	Log	2	After changing the destination of the permanent or temporary logs to syslog , the router or switch would sometimes reboot when displaying the dynamic configuration. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

							-							
CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00018137	Switch, VLAN	2	Previously, multicast limiting did not limit the number of destination look- up failure packets or multicast packets destined to reserved IP multicast addresses. In a correctly-functioning network, rates of these packets are very low, but in a network with a loop, rates can be very high. This issue has been resolved. Multicast limiting now includes such packets.	_	_	_	_	_	_	_	_	_	_	Y
CR00018141	Switch	2	CPU utilisation could become very high under circumstances in which the switch needed to learn a large number of entries. For example, this could occur during a reboot when large numbers of MAC entries require learning. This issue has been resolved.	_	_	_	_	_	_	_	_	_	_	Y
CR00018184	DHCP	2	Previously, the router or switch did not have a minimum length for the Options field of DHCP messages. This conformed to RFC 2131, which states that the length of the Options field is variable, but did not conform to RFC 1531, in which the field has a minimum length of 312 bytes. This issue has been resolved. To maintain interoperability with pre-RFC 2131 DHCP clients, the router or switch now pads the Options field to 312 bytes if it is less than this.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00018270	Switch	2	When aging out FDB MAC entries on x900-48 series switches, it was possible for the FDB entry to be erased while there were still references to it. This could result in L3 switched traffic with a destination MAC of 00-00-00-00-00. This issue has been resolved.	_	_	_	_	_	_	_	_	Y	-	
CR00018700	OSPF	2	When a physical IP interface had multiple logical interfaces running on it and the physical interface's status changed, OSPF only recorded the status change of the first logical interface. For example, if the physical interface was down and came back up, OSPF would only give the first logical interface a status of up; it would leave the other logical interfaces down. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Υ	Y	Y	Y	Y
CR00018751	Firewall	2	The firewall sometimes rebooted when using ENAPT, especially if FTP was being run though the firewall. This issue has been resolved.	Y	Y	Y	Y	Y	Y	-	_	_	_	Y

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00018752	Switch	2	An AR770S router could reboot when it was processing a very heavy traffic load in its CPU. This issue has been resolved.	_	-	Y	_	_	_	-	_	_	_	_
CR00018941	IP Gateway	2	When deleting an IP RIP interface or disabling an IP interface with RIP running on it, the router or switch would stop responding and reboot after 5 minutes. This issue has been resolved.	Y	Υ	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00018943	Switch	2	With 1000Base SFPs installed, the AR770S Eth ports failed to establish a link on restarting when receiving a moderate amount of traffic. This issue has been resolved.	_	_	Y	_	-	_	_	_	_	_	-
CR00019273	BGP	2	Once a BGP peer had received updates from another peer, it was not possible to use the commands delete bgp net or delete bgp import to remove a locally-imported route from the BGP RIB. This issue has been resolved. These commands will now work at all times.	Y	Y	Y	Y	Y	Y	Ι	_	Y	Y	Y
CR00019351	TPAD, X25T	2	Multiple concurrent TPAD transactions could cause the router or switch to reboot. This issue has been resolved.	Y	Y	Y	Y	Y	_	-	_	_	_	-
CR00019542	Eth	2	With some link partners, an AR415S Ethernet port would stop receiving packets after some hours or days, and a link state cycle or interface reset was required to restore operation. This issue has been resolved.	Y	_	-	_	-	-	-	_	_	_	-
CR00019713	OSPF	2	If two or more ECMP routes from Type-5 LSAs were learned by the router or switch, only the route from the LSA with the highest Router ID would be inserted into the IP route table. This issue has been resolved. All routes will now be inserted.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00007089	PRI	3	 The following issues occurred with testing PRI interfaces: When the commands enable pri=x test=y and disable pri=x test=y were entered, the router or switch did not display an "Operation Successful" message. This issue has been resolved. The output displayed by the "?" help for enable pri=x test=? incorrectly said that the maximum value was 11. This issue has been resolved. The "?" help now returns the following message: required - decimal in the range 1 to 7 (for E1) 1 to 9 (for T1) When show pri=x test was entered, the router or switch displayed an error message instead of the table of test switches. This issue has been resolved. When disable pri=x test was entered with no value on the test parameter, the router or switch displayed an error message instead of disabling all current tests. This issue has been resolved. 	Y	Y	Y	Y	Y	_					
CR00007499	VRRP	3	Previously, if a VRRP virtual router was enabled but not connected to anything (for example, no ports in the VRRP VLAN were connected), and the VR was disabled by using the command disable vrrp= <i>n</i> , the error message "Error (3088271): VR n is already disabled" was displayed. This issue has been resolved. This incorrect error message no longer displays.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00007870	IP Gateway	3	 The following issues occurred with ICMP Router Advertisement: When the feature was enabled, four initial advertisements were sent instead of three, as defined in RFC 1256. The advertisement counter was incremented incorrectly when advertisements were sent on a down interface. This resulted in no advertisements being sent at all. If an advertisement interface was added and then deleted, the interface could not be added again. These issues have been resolved. 	_	_	_	Y	Y	Y	Y	Y	_	_	Y
CR00007880	LAPB, MIOX, X25-T, Core	3	If the access link to an X.25 network was unstable and suffered outages frequently, it was possible for X.25 calls to become locked up so that data was not successfully transferred. When this happened, the call needed to be manually taken down before normal operation would resume. This issue has been resolved.	Y	Y	Y	Y	Y	_	_	_	_	_	_
CR00010517	Firewall	3	When the firewall deny event table filled up, the oldest deny event was pushed out by the next new one, even if the old event had not finished. This meant that the old attack was never recorded as having finished, and prevented the firewall from recording that attack again, even after the associated session had closed. This issue has been resolved. The firewall now ends the event as if the event had timed out and finished.	Y	Y	Y	Y	Y	Y	_	_	_	_	Y
CR00010575	Classifier	3	If the command create classifier=x innervlanid=y was entered, then the configuration from show config dynam or create config displayed the command as create classifier=x innervlanid=y innertpid=8100 , even though the entered command had not specified the innertpid value. This issue has been resolved. The command create classifier=x innervlanid=y no longer sets the innertpid value.		_	_	_	_	_	_		Y	Y	-

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00011170	STP, MSTP, Switch	3	Previously, a topology change could result in a mismatch between the switch's software and hardware forwarding database. This issue has been resolved.	_	_	_	Y	Y	Y	Y	Y	_	_	_
CR00012479	IPv6, TCP	3	Issues in the IPv6 implementation of TCP meant that routers or switches running SSH for IPv6 could reboot under unusual circumstances. These issues have been resolved.	Y	Y	Y	Y	Y	Y	_	_	Y	Y	Y
CR00013213	Triggers	3	The command create trigger time accepted invalid dates such as 00-dec-2000. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00013772	MSTP	3	If a switch was configured for MSTP with the protocol version set to RSTP, and the switch was connected to a switch that was configured for MSTP with the protocol version set to MSTP, then a loop could occur. This issue has been resolved.	_	_	_	Y	Y	Y	Y	Y	Y	Y	-
CR00013775	Firewall	3	When a host on a private firewall interface attempted to ping an unreachable host on a public firewall interface and received "destination unreachable" reply messages created by the firewall, the firewall would create firewall sessions for the packet flow that would time out after 600 seconds. This issue has been resolved. The firewall no longer creates sessions for locally generated "destination unreachable" reply messages.	Y	Y	Y	Y	Y	Y	_	_	_	_	Y
CR00014278	Firewall	3	When a private LAN interface was brought down then up again, the firewall did not apply NAT to locally generated packets, such as pings. This meant ping replies could not be returned. This issue has been resolved.	Y	Y	Y	Y	Y	Y	_	_	_	_	_
CR00015160	Core	3	It was not possible to enable link trapping on dynamic interfaces. The command to do so (enable interface=dynamic linktrap) returned an error. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	AT-9900	AT-9800
CR00015870	Firewall	3	It was possible to enter the same firewall rule multiple times. The duplicate entries would cause the firewall to renumber the rules, leaving multiple copies of the same rule in the configuration. This issue has been resolved. It is no longer possible to enter a rule that is identical to an existing rule.	Y	Y	Y	Y	Y	Y	_	_	_	_	Y
CR00015986	VRRP	3	The router or switch could reboot if it was configured with a very large number of VR instances, and each of these VR instances was configured to monitor an interface. In other words, this occurred when adding a large number of VRs by using commands like the following example: create vrrp=106 over=vlan1 ipaddress=192.168.1.109 priority=200 add vrrp=106 monitoredinterface=eth0 This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00016768	IPsec, Software QoS	3	If a Software QoS DAR was configured in a traffic class that was attached to an IPSec tunnel interface, the dynamic classifiers were not created or assigned to the traffic class correctly. This issue has been resolved.	Y	Y	Y	Y	_	_	_	_	_	_	_
CR00017240	Switch	3	If there were a large number of IGMP snooping groups and the switch received an IGMP query or other All Router traffic, then it could experience an STP topology change. This issue has been resolved.	-	_	_	_	_	_	_	_	_	_	Y

CR	Module	Level	Description	AR400	AR7x5	AR7×0S	lapier i	lapier w	AT-8800	AT-8600	AT-8700XL	(900-48	AT-9900	AT-9800
CR00017548	Switch, VLAN	3	Previously, when using subnet-based VLANs, only IP traffic matching the source IP network was classified into the subnet-based VLAN. This did not include ARPs.	-	-	-	-	-	-	-	-	Y	Y	-
			This meant that subnet-based VLANs only worked if all traffic flow was between ports in the same subnet-based VLAN, or if static ARP entries were configured.											
			This issue has been resolved. You can now use a hardware filter to send ARP packets to the CPU, which will process them appropriately. This means that if you use subnet-based VLANs, you also need to add the following hardware filter:											
			create classifier=1 ethformat=ethii-untagged protocol=0806 add switch hwfilter=1 classifier=1 action=discard,copy											
CR00017692	Core	3	Stack dump information was not available in the show debug or show system dump commands after a fatal exception. This issue has been resolved.	_	_	Y	_	_	_	_	-	_	_	_
CR00017744	Switch	3	When switch ports were under a heavy traffic load, BPDUs could become corrupted (the CRC was missing from the end of the packet). This issue has been resolved.	_	_	_	_	_	_	_	-	Y	_	_
CR00017851	Firewall	3	When using policy routing in conjunction with Firewall NAT, a policy-routed packet could be sent over an interface while the IP NAT rule that was applied would belong to a different interface. This would result in the packet having a mis-matched source IP address for the interface it was forwarded over.	Y	Y	Y	Y	Y	Y	_	_	_	_	Y
			This issue has been resolved. When using policy routing and Firewall NAT, the source address on the resulting forwarded packet will now follow the IP NAT rule attached to the interface over which the packet is forwarded.											

CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00018017	DHCP	3	When a DHCP client was communicating with a DHCP server through a BootP relay, when the client attempted to re-new its address allocation by using unicast DHCP renew messages, the DHCP server would drop the messages and not reply. This forced the client to resort to using a broadcast DHCP discover message. This issue has been resolved. The DHCP server will no longer drop the unicast DHCP renew messages.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00018018	Firewall	3	The SIP ALG was causing a problem when a SIP server on the private side of the firewall was redirecting an incoming call from an endpoint on the public side back out to another endpoint on the public side. The problem was that as the SIP ALG processed the outgoing SIP Invite (sent by the private-side SIP server to the eventual call recipient) it replaced the IP address of the originating endpoint by the public IP address of the firewall. Therefore, when the call connected, the receiving endpoint sent its voice data to the public IP of the firewall, instead of to the originating endpoint. Hence the originating caller heard no sound from the answering caller. This issue has been resolved, so that the SIP ALG now checks whether the IP address of the originating endpoint is on the public side of the firewall, even if the Invite packet came from the private side. If the originating IP address is on the public side of the firewall, the SIP ALG does not change it.	Y	Y	Y	Y	Y	Y	_	_	_	_	Y
CR00018034	Switch	3	On 48-port switches, hardware filters that used a classifier with the eport parameter did not always filter traffic correctly. This issue has been resolved.	_	_	_	Y	Y	Y	Y	Y	_	_	_

CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	AT-9900	AT-9800
CR00018182	PKI	3	Previously, the PKI certificate timestamp was only verified at router or switch initialisation. This caused problems when the time changed, for example because of NTP or if the router or switch had no battery backup (so the time defaulted to 01-Jan-1999 after a reboot). In either situation, the timestamp updates were not communicated to the PKI certificate code so the certificates remained valid or invalid depending upon the initial timestamp check. This issue has been resolved. PKI periodically verifies the certificate	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
			timestamps and automatically validates or invalidates the certificate. Also, the show pki command output has been updated to include all the debug options (some were missing) and to improve the output.											
CR00018431	Core	3	SNMP access to the MIB object ifInOctets on the Eth port of an AR770S router did not get the actual updated value unless the value was first refreshed with the show interface=eth counter command. This issue has been resolved.	-	_	Y	_	_	_	_	_	_	_	_
CR00019012	Firewall	3	On very rare occasions, the router or switch could reboot when running as a firewall and using passive FTP. This issue has been resolved.	Y	Y	Y	Y	Y	Y	_	_	_	_	Y
CR00019020	GUI	3	In some circumstances, the VPN wizard did not recognise some bundle licences. This issue affected firewall licence recognition. This issue has been resolved.	Y	_	_	_	_	_	_	_	_	_	_
CR00019575	Firewall	3	On rare occasions, the firewall rebooted when processing RTSP or FTP TCP streams. This issue has been resolved.	Y	Y	Y	Y	Y	Y	_	-	_	_	_

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	AT-9900	AT-9800
CR00019703	L2TP	3	When the router or switch was acting as an LNS, it was possible for it to get into a state where it has an active and an inactive L2TP tunnel both tied to one PPP connection. Previously, when the inactive tunnel timed out, the router or switch closed the PPP connection. This situation with two L2TP tunnels arose when the LAC removed the tunnel in a way that made it unable to notify the LNS (for example, if there was a brief network outage between the LAC reactivated the call, it created a second tunnel tied to the same PPP connection. This was because L2TP calls could be attached to PPP connections which were already associated with an L2TP call and were active. This issue has been resolved. L2TP calls can no longer be attached to active PPP connections that are already associated with an L2TP call.	Y	Y	Y	Y	Y	Y	_		Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	AT-9900	AT-9800
CR00012634	QoS, Switch	4	QoS sometimes marked traffic red when no metering parameters had been specified and therefore all traffic should have been green. However, the switch did not drop the red-marked traffic, because metering had not been configured. This issue has been resolved.	_	_	-	_	_	_	_	-	Y	Y	_
CR00013088	IPv6	4	When an ICMPv6 time exceeded packet was sent out, the InTimeExcds counter was incremented, when the OutTimeExcds should have been incremented. This issue has been resolved.	Y	Y	Y	Y	Y	Y	_	_	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00013774	Switch, MSTP	4	If MSTP was enabled and a port was set as the mirror port, it was possible for the switch to send BPDUs out of this port. Note these BPDUs were originated by the switch, not mirrored from another port. This issue has been resolved.	-	_	_	Y	Y	Y	Y	Y	Y	Y	-
CR00013916	Switch	4	 For the ingresslimit and egresslimit parameters of the set switch port command, the output of the "?" help previously said that the range of values was 0 to 4294967295. This issue has been resolved. The "?" help output now gives the correct ranges, which are: 1000 to 127000 (in kbps) for 10/100 Mbps ports 8 to 1016 (in Mbps) for 1 Gbps ports 	-	_	_	Y	Y	Y	Y	Υ	_	_	
CR00015655	User, RADIUS	4	Previously, the router or switch did not log a message if RADIUS authenticated a user logging in over telnet but RSO rejected the login. This issue has been resolved. A message is now logged, with module USER, type RSO, and subtype RJCT. The message reads "Remote Security Officer access rejected from user <i><name></name></i> at <i><ip-address></ip-address></i> ."	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00017449	Switch	4	The set switch port speed command incorrectly accepted a value of 1000mhalf for tri-speed copper SFP ports. This issue has been resolved. If you enter 1000mhalf , the switch displays an error.	-	_	_	_	_	_	_	_	_	Y	-
CR00017971	Utility	4	The "?" help for some parameter options (including add igmp filter= <i>id</i> group= <i>address</i> action=?) did not show all the available options. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00010614	IP Gateway	-	Support for ICMP Router Discovery, as described in RFC 1256, has been added to routers, and to AT-8948, x900-48, and AT-9900 series switches. For more information, see "ICMP Router Discovery Advertisements (CR00010614)" on page 237 Note that the other layer 3 switches already supported this feature.	Y	Y	Y	_	_	_	_	_	Y	Y	-
CR00015525	ADSL, Core	-	 With this software version, AR440S routers with a hardware revision of M1-2 (or later) will support ADSL2 and ADSL2+ connections. You can see the hardware revision of a router by entering the command show system and checking the "Rev" column for the "Base" board. When running this software version, AR440S routers with rev M1-2: have the following new options for the command set adsl standard: adsl2 connect only to devices offering ADSL2+ adsl2plus connect only to devices offering ADSL2+ auto2plus connect at ADSL2+ if this is offered by the other end device (CO), or otherwise automatically fall back to what is offered have a default ADSL standard setting of auto2plus behave as they currently do for other ADSL standard settings When running this software version, existing AR440S routers with a hardware revision of M1-1 or earlier: do not have the new options adsl2, adsl2plus, or auto2plus for the command set adsl standard still use the existing default ADSL standard setting of auto, which allows automatic fallback connection for ADSL standards only. 	Y										

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00016978	STP, MSTP, Switch	-	 STP and MSTP debugging has been enhanced to: make it easier to see state information, and only display information about Topology Change messages. For command syntax and output details, see "STP and MSTP debugging enhancements (CR00016978)" on page 241. 	_			Y	Y	Y	Y	Y	Y	Y	Y
CR00017018	Classifier, DHCP snooping	-	This enhancement enables you to act on traffic that is received on an uplink port and is destined for a particular DHCP client. You can use the new functionality, for example, to track how much traffic each user receives via an uplink port. This enables you to track traffic usage at the uplink port, even if destination IP addresses are dynamically assigned by DHCP and traffic for multiple users is in the same VLAN. For command syntax and more information, see "Acting on traffic destined for a particular DHCP client (CR00017018)" on page 244.	_	_	_	_	_	_	_		Y	Y	
CR00018144	IPv6	-	Routing Header type 0 has been deprecated for IPv6 due to security concerns, as described in the Internet Draft at www.ietf.org/internet-drafts/ draft-ietf-ipv6-deprecate-rh0-01.txt. When the router or switch receives a packet addressed to it that contains RH type 0, it now responds as if it does not understand the header, as specified in RFC 2460. That is, it ignores the header if the number of segments left is zero, or it replies to the sender with an ICMPv6 incorrect parameters error message.	Y	Y	Y	Y	Y	Y	_	_	Y	Y	Y

				3400	87x5	37×05	ipier i	ipier w	-8800	-8600	-8700XL	00-48	0066-	-9800
CR	Module	Level	Description	A	A	Ā	Ra	Ra	F	F	F	×9	Ā	F
CR00018346	VLAN	-	This enhancement adds a new parameter nestedoverride to the command add vlan port .	-	_	_	-	-	-	-	-	Y	Y	-
			The nestedoverride parameter allows you to add the port to a non-nested VLAN as a tagged port even if the port has already been configured as a customer port in a nested VLAN. The vlan parameter specifies the non-nested VLAN to which you want to add the port. You must also specify frame=tagged . The port will behave as a normal customer port for the nested VLAN, and an egress-only port for the non-nested VLAN:											
			Frames received on the port and tagged for the nested VLAN will be sent to the core ports of the nested VLAN, as normal.											
			Frames received on the port and tagged for the non-nested VLAN will be sent to the core ports of the nested VLAN, and will not be sent to other ports of the non-nested VLAN.											
			 IGMP frames received on the port and tagged for the non-nested VLAN will be processed according to the IP multicasting configuration, instead of being discarded. 											
			Frames received on other ports of the non-nested VLAN will be transmitted from the port as tagged frames of the non-nested VLAN according to the FDB/multicast rules.											
			The nestedoverride parameter creates a non-standard configuration, and care should be taken when using this parameter in a live network. The nestedoverride and uplink parameters are mutually exclusive and cannot be specified in the same command.											
			An example configuration would be:											
			create vlan=v22 vid=22 nested											
			create vlan=v20 vid=20											
			add vlan=v22 port=1 frame=tagged nestedoverride											
CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
--	----------	-------	--	-------	-------	--------	----------	----------	---------	---------	-----------	---------	---------	---------
CR00018438 CR00019826 CR00019827	BRI	-	This software version supports the new AR021v3 BRI PIC. The user interface for this PIC is the same as for the AR021v2, except that output of the command show bri counters is simpler—there are no IOM counters and fewer D channel counters.	Y	Y	Y	Y	Y	_	_	_	_	_	-
CR00019152	Bridging	-	The number of ports supported by Bridging has been increased from 32 to 512.	Y	Y	Y	Y	Y	_	-	_	_	_	-
CR00019377	L2TP	-	Previously, the length of the L2TP call name was limited to 15 characters. This limit has been increased to 19 characters.	Y	Y	Y	Y	Y	Y	-	_	Y	Y	Y
CR00019749	OSPF	-	This enhancement increased the maximum acceptable payload size of an OSPF Link State Update from 1452 bytes to 1992 bytes. As an example, previously the maximum number of Router LSAs that could be received in one Link State Update was 119. This has increased to 164.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

Features in 291-10

Software Maintenance Version 291-10 includes the resolved issues and enhancements in the following tables. In the tables, for each product series:

- "Y" indicates that the resolution is available in Version 291-10 for that product series.
- "-" indicates that the issue did not apply to that product series.

Level 1

No level 1 issues

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00016759	Switching, DHCP Snooping	2	Enabling DHCP snooping (correctly) adds a hardware filter to all untrusted ports, to block all IP traffic coming from those ports. Previously, disabling DHCP snooping did not delete these filters. This meant that the switch dropped all IP traffic from the previously-untrusted ports until the switch was restarted. Also, attempting to manually delete the hardware filters did not actually remove them. These issues have been resolved. The switch now removes the filters if you disable DHCP snooping or manually delete the filters.	_	_	_	-	-	-	-	-	Υ	Y	-
CR00018655 CR00018656	IP Gateway	2	If the user did not specify the destination and dmask parameters when entering the set ip filter command, the destination and dmask of the filters were reset to any . Also, it was not possible to delete an IP filter by using the delete ip filter command, even when all required parameters were present. These issues have been resolved.	Υ	Υ	Υ	Y	Y	Y	Y	Υ	Υ	Υ	Υ

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00018663	Switching	2	The resolution to CR 444 meant that packets processed by the CPU are now subjected to the same filtering as packets switched in hardware. However, this filtering did not always return the expected results. Sometimes its IP address matching was incorrect, and it did not correctly process filters with an action of nodrop . These issues have been resolved.	-	-	-	Y	Y	Y	Y	Y	-	-	-
CR00018691	OSPF	2	On a router or switch with OSPF redistribution enabled, OSPF did not redistribute the interface route when an interface came up (for example, after a reboot). This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00018693	QoS	2	QoS policies, traffic classes, and flow groups could not have an ID number of 0 (zero). This issue has been resolved.	-	-	-	Y	Y	Y	Y	Y	Y	Y	Y
CR00018778	IP NAT, Firewall	2	When using IP NAT, the router or switch would reboot when processing TCP SYN packets. This issue only occurred with IP NAT, which is configured by using the add ip nat command. It did not occur with firewall NAT. This issue has been resolved.	Y	Y	Y	-	-	-	-	-	-	-	-

Level 3

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00018514	Ping	3	Traceroute (the trace command) did not work. It returned the error "The destination is either unspecified or invalid" even if the destination was reachable. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

Level 4

No level 4 issues

Enhancements

No enhancements

Features in 291-09

Software Maintenance Version 291-09 includes the enhancement in the following table, which is available for x900-48FE and x900-48FE-N switches.

Level 1-4

No level 1-4 issues

Enhancements

CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00018530	Core	-	 CPU fan monitoring is now disabled by default on x900-48FE and x900-48FE-N switches. Monitoring the fan is unnecessary unless an accelerator card is installed on the switch, so disabling monitoring reduces the number of messages that the switch displays and logs. To enable monitoring, use the command: enable cpufanmonitoring To disable it again, use the command: disable cpufanmonitoring When monitoring is enabled, the command show system displays the CPU fan status in the entry labelled "Main fan". Note that this behaviour is already available on AT-8948 switches. 	-	-	-	-	-	-			Y	-	

Features in 291-08

Software Maintenance Version 291-08 includes the resolved issues and enhancements in the following tables. In the tables, for each product series:

- "Y" indicates that the resolution is available in Version 291-08 for that product series.
- "-" indicates that the issue did not apply to that product series.

Level 1

No level 1 issues

CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00000444	Switching, IGMP, IP Gateway	2	If a packet should have matched a hardware filter with a deny action and have been discarded, but an IP routing entry had not yet been learnt for the packet, then the packet was not discarded. This issue has been resolved and the packet is now discarded.	-	-	-	Y	Y	Y	Y	Y	-	-	-
CR00000484	Switching	2	When a nodrop action was specified on a port as part of an L3 filter, it was observed that the port was still dropping packets. This was observed after the ARP entry for the destination IP expired from the switch's L3 table. This issue has been resolved.	-	-	-	Y	Y	Y	Y	Y	-	-	_
CR00001231	Firewall	2	The router or switch sometimes recorded more events in its deny event queue than was specified by the detail parameter of the set firewall policy attack command. This issue has been resolved.	Y	Y	Y	Y	Y	Y	-	-	-	-	Y

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	AT-9900	AT-9800
CR00003495	Classifier	2	 The following issues existed with classifiers: classifiers matching protocol=ipv6 and ipprotocol=icmp could be created more than once classifiers matching protocol=ipv6 and ipprotocol=1 could be created but were meaningless because 1 represents IPv4 ICMP classifiers matching protocol=ip and ipprotocol=58 could be created but were meaningless because 58 represents IPv6 ICMP. These issues have been resolved. Also, classifiers now default to protocol=ip (IPv4) if: no value is specified for the protocol parameter, or protocol=any and ipprotocol=icmp. 	Y	Y	Y	Y	Y	Y			Υ	Y	Y
CR00004018	VLAN	2	Removing then re-adding ports to a Nested VLAN, with rapid STP enabled, caused the port in the Alternate Discarding state to leak a small number of packets. This issue has been resolved.	-	-	-	-	-	-	-	-	-	Y	-
CR00005472	BGP	2	When BGP was in the OpenSent state and it received an out-of-sequence message (such as a KeepAlive message), BGP would return to the Idle state. This issue has been resolved. BGP now sends a notification message to the other BGP peer, as expected.	Y	Y	Y	Y	Y	Y	-	-	Y	Y	Y
CR00005812	IP Gateway	2	When the router or switch received an IP packet whose length was greater than the MTU on the outgoing link, and the packet contained an IP option that was not designed to be fragmented (such as Timestamp), then the resulting constituent fragments would have incorrect IP header lengths. This could lead to data corruption. On routers, this issue applied to all routed packets. On switches, it applied to packets processed by the CPU, not to packets switched in hardware. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00007178	RIPng	2	 The following issues occurred with RIPng: RIPng dropped requests from peers with non link-local addresses. for a solicited response, if the routes did not exist on the device, RIPng returned a metric of 0 for them instead of returning a metric of 16 RIPng performed split-horizon checking for solicited responses RIPng used the link-local address to respond to all requests, even if the request used a non link-local address and therefore the reply should have also used a non link-local address These issues have been resolved. 	Y	Y	Y	Y	Y	Y	-	-	Y	Y	Y
CR00008847	Install, MIB	2	Previously, the MIB objects configFile and createConfigFile would return the current configuration file, and the MIB object currentConfigFile would return 'no such object'. This issue has been resolved. The objects configFile and createConfigFile now return the boot configuration file. The object currentConfigFile now returns the current configuration file.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00009473	Classifier	2	The output of the show classifier=<i>number</i> command did not show the protocol number. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00010654	Firewall	2	When adding a firewall application rule, it was possible to specify FTP as the application but not specify the command parameter. This meant that the rule would allow all FTP commands through, even if action=deny had been specified. This issue has been resolved by making the command parameter mandatory when the application is specified as FTP.	Y	Y	Y	Y	Y	Y	_	_	-	-	Y
CR00010951	РРР	2	If the router or switch received an LCP packet with an unrecognised code, it responded with a CodeReject packet of incorrect length that did not respect the established MRU of the peer. This issue has been resolved.	Y	Y	Y	Y	Y	Y	-	-	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	AT-9900	AT-9800
CR00010967	РРР	2	If the router or switch received an LCP packet with an unrecognised protocol, it responded with a ProtocolReject packet of incorrect length that did not respect the established MRU of the peer. This issue has been resolved.	Y	Y	Y	Y	Y	Y	-	-	Y	Y	Y
CR00010968	РРР	2	When the established Maximum Receive Unit (MRU) of the remote PPP peer was greater than the established MRU of the local PPP peer, Echo Reply packets did not respect the established MRU of the remote peer. This issue has been resolved.	Y	Y	Y	Y	Y	Y	-	-	Y	Y	Y
CR00011231	Core	2	In most circumstances the stack dump for an AR7x5 router was invalid and did not contain complete information about the cause of a reboot. This issue has been resolved.	-	Y	-	-	-	-	-	-	-	-	-
CR00012218	VPN, GUI	2	Enabling VPN (IPsec) on the GUI caused the GUI VPN page to stop displaying information about some or all of the existing VPN policies. This issue has been resolved.	Y	-	Y	-	-	-	-	-	-	-	-
CR00012727	OSPF	2	Sometimes when a type 7 external LSA was translated to a type 5 external LSA the forwarding address was set to 0.0.0.0 in the translated type 5 LSA. This issue has been resolved, so that the forwarding address is always copied from the type 7 LSA being translated.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00012751	OSPF	2	When the router or switch is acting as an area border router and one of the areas is an NSSA (Not So Stubby Area), the router or switch will create a default route for the NSSA and inject this into the NSSA. Previously, the router or switch was also redistributing this route into other areas as a static route when static route redistribution was turned on. This was not desirable behaviour. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00012871	ΤΤΥ	2	Unexpected characters could appear on the terminal emulator display when the column size was set greater than 80 and the user edited a command that spanned more than one line of the display. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00013597	DVMRP, Frame Relay	2	If a frame relay interface was configured as a DVMRP interface, then the DLC value was not correctly generated in output of the command show config dynam or in the configuration script generated by the command create config . This issue has been resolved.	Y	Y	Y	Y	Y	-	-	-	-	-	-
CR00013660	Core, SNMP	2	Previously, SNMP returned an incorrect product ID number for AR750S-DP routers. This issue has been resolved. The value of the sysObjectID object is now 80 for AR750S-DP routers.	-	-	Y	-	-	-	-	-	-	-	-
CR00013735	LACP, Switching	2	 When moving ports from an LACP-controlled trunk to a manually-configured trunk, ports were incorrectly set in an STP blocking state. Therefore, traffic would not flow over the trunk. This issue has been resolved. Note: When you move ports from an LACP-controlled trunk to a manually-configured trunk, you must delete the ports from LACP. 	-	-	-	-	-	-	-	-	Y	Y	-
CR00013763	OSPF	2	If the obsolete command set ospf rip=both was entered, the router or switch correctly automatically replaced it with the following two commands in the dynamic configuration: add ospf redistribute protcol=rip set ospf rip=export However, if the command create config was used to save the configuration, after system start-up the configuration file did not contain the command add ospf redistribute protocol=rip . This meant that OSPF stopped redistributing RIP routes after a reboot. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00013778	IPv6	2	If a user shortened the prefix length of an IPv6 interface address, then lengthened it, it became impossible to change the prefix length again. This issue has been resolved.	Y	Y	Y	Y	Y	Y	-	-	Y	Y	Y
CR00013893	MSTP	2	Executing the commands disable mstp port= <i>number</i> or enable mstp port= <i>number</i> would not disable or enable the port on all MSTIs. This issue has been resolved.	-	-	-	Y	Y	Y	Y	Y	Y	Y	-
CR00013982	L2TP	2	An L2TP call could be deleted when still attached to the PPP interface. Doing this caused the router or switch to reboot. This issue has been resolved.	Y	Y	Y	Y	Y	-	-	-	-	-	-
CR00014044	IGMP	2	When large numbers of multicast streams were passing through the switch and there was no multicast routing protocol running (such as PIM or DVMRP), the CPU would experience regular periods of extended high utilisation. This could result in lost control packets and network instability. This issue has been resolved.	-	-	-	-	-	-	-	-	-	-	Y
CR00014146	TTY	2	When a file was redirected (for example, by a trigger), if the mail hostname was not available or not configured, the router or switch would reboot. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00014230	TTY	2	If the built-in editor was used to delete the last line of a file, the router or switch could reboot. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00014295	IGMP	2	IGMP snooping would process IGMP protocol packets that had incorrect IP TTL fields (i.e. that had values other than 1). This issue has been resolved.	Y	-	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00014320	OSPF	2	Occasionally, when OSPF was started, not all the Type-7 LSAs were translated into Type-5 LSAs. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00014827	PIM6	2	If an IPv6 accelerator was used, and the upstream router forwarded IPv6 multicast data just before the prune limit timer expired, then the downstream router sometimes did not send the prune until significantly after the timer expired. This issue has been resolved.	-	-	-	-	-	-	-	-	Y	Y	-
CR00015169	MSTP, GUI	2	Using the web-based GUI to set the Point-to-Point Link in the MSTP CIST Port configuration to a non-default value would generate an error. This issue has been resolved.	-	-	-	Y	Y	Y	Y	Y	Y	Y	-
CR00015805	ISAKMP, IPv6	2	During the boot up, the router or switch waited 5 seconds before beginning ISAKMP prenegotiation. For VPN tunnels over IPsec for IPv6, this was not long enough for the router or switch's interfaces to come up before prenegotiation began. Also, the router or switch did not obtain the most recent active ISAKMP SA when multiple SAs existed. These issues have been resolved. The router or switch now waits 6 seconds, and obtains the most recent SA and uses that for Phase 2 negotiations.	Y	Y	Y	Y	Y	Y	-	-	-	-	-
CR00015964	Switching	2	If the switch had a large number of routes in its forwarding database (FDB), and the command show switch fdb was used to display the contents of the FDB, and the switch's CPU was busy at the time, then the switch sometimes rebooted. This issue has been resolved.	-	-	-	-	-	-	-	-	Y	Y	-
CR00016262	Load	2	When attempting to upload files from the switch using TFTP to an IPv4 server address, the router or switch reported an error if IPv6 was not enabled. It was not possible to upload files using TFTP to an IPv6 server address at all. These issues have been resolved.	Y	Y	Y	Y	Y	Y	-	-	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	AT-9900	AT-9800
CR00016340	DHCP Snooping	2	DHCP Snooping has been enhanced to operate in a customised VLAN ID translation (VID translation) environment. Previously, DHCP Snooping was not supported with VID translation. This issue has been resolved.	-	-	-	Y	Y	Y	Y	Y	Y	Y	-
CR00016587	IPv6	2	The timer that governs the interval between repeated neighbour solicitation messages could only be configured by using the ndretrans parameter of the set ipv6 nd command, and not through router advertisements that the router or switch received from other routers. This issue has been resolved. Instead of using the ndretrans parameter of the command set ipv6 nd , use the retrans parameter to configure the timer interval. Also,routers or switches acting as hosts will now correctly update their timer values to the value specified in any router advertisements that they receive.	Y	Y	Y	Y	Y	Y	-	-	Y	Y	Y
CR00016592	DHCP6	2	Previously, it was possible to enter the incomplete commands delete dhcp6 policy=name or set dhcp6 policy=name without specifying any other parameters. This issue has been resolved. If this is done, the router or switch now displays the warning: Warning (2117007): One or more parameters may be missing.	Y	Y	Y	Y	Y	Y	-	-	Y	Y	Y
CR00016840	STP	2	Previously, when the switch was a Spanning Tree root bridge in a network and a user raised the switch's root bridge priority enough to stop the switch from being the root bridge, unnecessary delays in convergence occurred. This issue has been resolved.	-	-	-	Y	Y	Y	Y	Y	Y	Y	Y
CR00016956	IP Gateway	2	The set ip filter command would not accept the protocol parameter. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	AT-9900	AT-9800
CR00016964	ISAKMP	2	When the router or switch negotiated an IPsec tunnel with RFC3947 NAT- T, its NAT-OA payload had two bytes of reserved fields after the ID field instead of the three bytes specified by RFC 3947. This could prevent the tunnel from working properly when the tunnel was between an Allied Telesis router or switch and some other vendor. This issue has been resolved.	Y	Y	Y	Y	Y	Y	-	-	-	-	-
CR00016985	АТМ	2	If a PPP instance was destroyed after an attached ATM channel had been modified using the set atm channel command, the router rebooted. The router could also reboot if an ATM channel was deleted under similar circumstances. This issue has been resolved.	Y	-	-	-	-	-	-	-	-	-	-
CR00016989	IPsec	2	AlliedWare IPsec would not interoperate with Microsoft Windows Vista VPN clients. This was because Microsoft changed the IPSec behaviour in Vista such that Vista's private local IP address is sent as the local identification instead of an FQDN. When an IPSec tunnel between AlliedWare and Vista was brought up, the hosts could not communicate. This issue has been resolved. AlliedWare IPsec can now communicate with peers that send their private local IP address as the local identification.	Y	Y	Y	Y	Y	Y	-	-	-	-	-
CR00017081	Classifier	2	The show classifier command did not allow users to display only the classifiers that had their IP source address and MAC source address parameters set to dhcpsnooping . This issue has been resolved. For example, the command show classifier ipsa=dhcpsnooping now displays those classifiers that have their IP source address set to dhcpsnooping . Also, it is no longer possible to create two identical classifiers with DHCP snooping parameters.	-	-	-	-	-	-	-	-	Y	Y	-

CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	AT-9900	AT-9800
CR00017093	Firewall	2	When the router was acting as a firewall and performing DNS relay, it used the local IP interface private address as the source address for some packets that it sent out the public interface. When the router acts as a DNS relay, it receives DNS requests from the private interface and sends a new packet on the public interface. These new packets were given the wrong address. This issue has been resolved. Such packets now have their source address set to the public interface address as required.	Y	Y	Y	Y	Y	Y	-	-	-	-	Y
CR00017226	IPsec	2	If an IPsec tunnel with no encryption (NULL) was negotiated in AlliedWare over NAT-T, the ESP packets did not contain an RFC 3948 compliant checksum. This means that some vendors may have discarded packets sent by the AlliedWare peer over such a tunnel. This issue has been resolved. Note the null encryption is useful for debugging the traffic over an IPsec tunnel and should not be used in a working IPsec solution.	Y	Y	Y	Y	Y	Y	-	-	-	-	_
CR00017227	lPsec	2	An IPSec checksum recalculation error occurred with UDP traffic when the ESP encapsulation was added. This issue has been resolved.	Y	Y	Y	Y	Y	Y	-	-	-	-	-
CR00017255	Switching	2	Previously, trunk members were given the STP state in hardware of port 1, instead of having the STP state of the lead port in the trunk. The software state (as displayed with the command show stp port) was correct. This issue has been resolved.	-	-	-	Y	Y	Y	Y	Y	-	-	-
CR00017256	Switching	2	When using multi-homed IP interfaces on a VLAN, it was possible that L3 hardware switching would stop for all multi-homed interfaces on that VLAN, if one of the multi-homed interfaces was removed or went into an administratively down state. This issue has been resolved.	-	-	-	-	-	-	-	-	Y	Y	-

				R400	R7x5	R7x0S	apier i	apier w	F-8800	F-8600	F-8700XL	900-48	-9900	F-9800
	Module	Level	Description	A	A	A	Å	ß	4	4	4	5×	4	4
CR00017337	Switching	2	It was possible to set up a classifier that matched MPLS frames at layer 2, but the switch would not correctly match these MPLS frames against the classifier. This issue has been resolved. The switch now correctly matches MPLS frames against such a classifier.	-	-	-	-	-	-	-	-	Y	Y	-
CR00017368	QoS,	2	Some small memory access violations existed in DHCP snooping.	-	-	-	Y	Y	Y	Y	Y	Y	Y	-
	DHCP		These violations have been resolved.											
	Snooping		Also, a new console error message is displayed if a user tries to add a duplicate classifier to a QoS policy. For example, if traffic class 101 belongs to policy 2 and a user tries to add a flow group to traffic class 101 when the flow group's classifier is number 54 and already belongs to policy 2, the following message is displayed: Error (3099297): Duplicate classifier (54) on policy 2. A similar new log message has also been added, which says: Duplicate classifier (<number>) found on <string> <number> Note that a classifier can exist in two separate policies but cannot exist twice in the same policy.</number></string></number>											
CR00017456	IP Gateway	2	The router or switch could reboot when the local interface address had been specified by using the set ip local command, and then the underlying interface from which the local interface took its address was either deleted or had its address changed. In both these cases, the local interface was correctly reset back to an undefined address, but a route to this address was not deleted. This could cause routing difficulties and a reboot when packets for that address were received. This issue has been resolved. The route is now correctly deleted.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00017488	Firewall	2	When a VoIP call using SIP was initiated from the public side of the firewall, occasionally the firewall created two UDP sessions for the call with different UDP source ports. This happened if the first packets of the STP (voice data) stream arrived earlier than the 200 OK message that was supposed to establish the session. The result was that the public side caller could not hear the call. This issue has been resolved.	Y	Y	Y	Y	Y	Y	-	-	-	-	Y
CR00017518	ISAKMP	2	The router or switch sometimes could not establish a VPN when the remote peer was behind a NAT gateway and the router or switch's remote ID was set to default . This issue has been resolved.	Y	Y	Y	Y	Y	Y	-	-	-	-	-
CR00017634	РРР	2	If a PPPoE AC service had been added, but AC mode had not been enabled by using the enable ppp ac command, PADI frames were processed anyway, potentially leading to a reboot. This issue has been resolved.	Y	Y	Y	Y	Y	Y	-	-	Y	Y	Y
CR00017659	ΤΤΥ	2	Previously, it was not possible to configure a TTY service on the router (by using commands like create service). This issue has been resolved.	Y	-	Y	-	-	-	-	-	-	-	-
CR00017662	Core	2	Stopping and restarting two fans on the switch in a particular order could put the fan fault detection mechanism into a state in which the system LED would not flash for a fan fault. This issue has been resolved.	-	-	-	-	Y	-	-	-	-	-	-
CR00017724	IGMP	2	When the switch had a hardware filter configured that would match and discard a received IGMP packet, IGMP snooping still processed the packet and added the details to its snooping database. This issue has been resolved.	-	-	-	Y	Y	Y	Y	Y	-	-	-

CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00017731	IP Gateway, DHCP	2	When the DHCP server was enabled on a router or switch that also had a local IP interface defined by using the set ip local command, outgoing DHCP server packets would use the set ip local command's IP address as their source address. Furthermore, if the broadcast flag was set to TRUE in the DHCP Discover message that the server was replying to, then the server would send the DHCP Offer packet out the wrong IP interface with the wrong source IP address. Microsoft Windows Vista has the broadcast flag set to TRUE. These issues have been resolved. The DHCP server configuration now ignores any local IP interfaces set by using the set ip local command, and the server now sends the Offer message out the interface that it received the Discover on.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00017749	Switching	2	If a multicast route had an odd number of downstream interfaces attached to it, and the last downstream interface was deleted, the second to last downstream interface could experience a loss of packets. This issue has been resolved.	-	-	-	-	-	-	-	-	Y	Y	-
CR00017816	ΡΙΜ	2	PIM would sometimes start forwarding duplicate packets from the RP to downstream interfaces if the SPT Bit had been set and had become unset. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	-	Y	Y	Y
CR00017906	VLAN, MSTP	2	If ports were removed from a VLAN and MSTP was enabled, then the port removal was not included in the configuration displayed by the command show config dynam or saved by the command create config . This issue has been resolved.	-	-	-	Y	Y	Y	Y	Y	Y	Y	-

CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	AT-9900	AT-9800
CR00000503	РКІ	3	Some PKI commands (including add pki Idap , create pki enroll , and create pki keyupdate) only worked if their parameters were entered in a particular order.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00001106		3	The command add fire policy=name rule=number act=allow int=int ip=ipadd list=filename would incorrectly be rejected, with an error message stating that list and ip were mutually exclusive. This issue has been resolved, so that list and ip can be used together in the same firewall rule.	Y	Y	Y	Y	Y	Y	_	_	_	_	Y
CR00001438	TACACS+	3	If TACACS+ was used for authentication and the TACACS+ server went down during an authentication attempt, the router or switch added the attempted login names to the TACACS+ user list (as displayed in output of the show tacplus user command). However, the router or switch correctly did not log users in with those names. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00002587	IP Gateway	3	Sometimes an incorrect error message was printed if a user tried to enable IP multicast switching on a device that did not support it. This issue has been resolved.	-	-	-	Y	Y	Y	Y	Y	-	-	-
CR00003354	Firewall	3	The firewall message "Port scan from <i><source/></i> is underway" was repeated more times than messages about other attack events. This could cause confusion. This issue has been resolved. The message is now displayed with the same frequency as other firewall attack event messages.	Y	Y	Y	Y	Y	Y	-	-	-	-	Y
CR00003356	Firewall	3	The firewall sometimes did not report that an attack had finished until several minutes after it actually finished. This issue has been resolved.	Y	Y	Y	Y	Y	Y	-	-	-	-	Y

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	AT-9900	AT-9800
CR00004004	File	3	The show file command did not check whether the specified file system was valid. If an invalid file system type was entered (such as show file=abc:*.*), the router or switch reported that no files found instead of reporting that the file system abc did not exist. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00005048	GUI	3	 The following issues occurred with the GUI: the menu item and related page title for configuring PPPoE and PPPoA interfaces was incorrectly named "PPP". This issue has been resolved by changing the names to "PPPoE / PPPoA". the UPnP selection option on the firewall pages did not work. This issue has been resolved. Note that if you want to use the GUI to configure a PPP interface over ISDN, use the Dial-up menu option to do so. 	Y	-	Y	-	-	-	-	-	-	-	-
CR00005187	LACP	3	If a user attempted to enable LACP on AT-9800 series switches—which do not support LACP—the switch incorrectly said that the module had been enabled. This issue has been resolved. The switch now displays an error message instead.	-	-	-	-	-	-	-	-	-	-	Y
CR00005894	Classifier	3	Previously, a classifier with protocol=ip matched both IPv4 and IPv6 packets when used with software QoS, instead of only matching IPv4 packets. This issue has been resolved.	Y	Y	Y	Y	Y	-	-	-	-	-	-
CR00005940	BGP	3	There were several cases in BGP where an error was discovered in an incoming packet, but the incorrect error subcode was reported in the accompanying NOTIFICATION message. Also, NOTIFICATION messages did not contain the aberrant data in their data fields, as required by the RFC. These issues have been resolved.	Y	Y	Y	Y	Y	Y	-	-	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00006303	SNMP	3	On AR725 and AR745 routers, which have no VLAN support, an SNMP Get request for dot1qMaxVlanId or dot1qMaxSupportedVlans incorrectly returned a value. This issue has been resolved.	-	Y	-	-	-	-	-	-	-	-	-
CR00006613	Bridge	3	Predefined bridge protocols XEROX PUP and PUP Addr Trans with the encapsulation of EthII and protocol type 0x0200 and 0x0201 are invalid and obsolete, since they are less than the minimum ETHII protocol type of 1500 (decimal). Bridging with these protocols could cause the router to reboot. This issue has been resolved by replacing the predefined protocol types with the more modern equivalents 0x0a00 and 0x0a01. Also, if you enter a protocol type less than the minimum, the router now displays an error message.	Y	Y	Y	-	-	-	-	-	-	-	-
CR00007394	GUI	3	When a user used the GUI to attempt to delete a local interface that was in use by another protocol, the operation (correctly) failed, but the GUI did not display an error message to explain the failure. This issue has been resolved.	Y	Y	Y	Y	-	Y	Y	Y	-	Y	Y
CR00007404	MSTP	3	If a network running MSTP was connected to a network running RSTP and MSTP message debugging was enabled on a switch, the debug output could loop for a very long time with invalid data. This issue has been resolved.	-	-	-	Y	Y	Y	Y	Y	Y	Y	-
CR00007926	Switching, IP Gateway	3	The x900 series switches did not send an ICMP Redirect packet when they received a packet and the route to the packet's destination was back to the packet's sender. The switches routed the packet back to the source but did not send an ICMP Redirect message. This issue has been resolved. The x900 series switches now send an ICMP Redirect message.	-	-	-	-	-	-	-	-	Y	-	-

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	AT-9900	AT-9800
CR00008122	ΤТΥ	3	When prompted to enter a file name while using the command line file editing utility, no more than 23 characters could be typed, even if the existing characters were deleted using the backspace key. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00008378	Firewall	3	The command enable firewall notify=port port= <i>asyn-number</i> was not available on switches, only on routers. If a user created a configuration on a router and used this option, the configuration had to be modified if transferred to a switch. This issue has been resolved. The notify=port option and the port parameter are now available on switches. However, these port parameters have been deprecated in favour of the asyn parameters, so warning messages are printed to indicate this if the commands are used.	-	-	-	Y	Y	Y	-	-	-	-	Y
CR00009086	Switching	3	When the commands enable switch port= <i>number</i> automdi and disable switch port= <i>number</i> automdi were executed from a telnet session, some INFO messages were output to the asyn0 console session instead of the telnet session. This issue has been resolved.	-	-	-	-	-	-	-	-	Y	Y	-
CR00010144	STP, SNMP	3	Previously, newRoot and topologychange traps (located at 1.3.6.1.2.1.17.0) were only generated by the bridging module. This has been extended to the STP module. Please note that this applies only to standard STP, not Rapid STP.	-	-	-	Y	Y	Y	Y	Y	Y	Y	Y
CR00010229	Install, SNMP	3	Previously, MIB objects instRelMajor, instRelMinor and instRelInterim values were only correct for bootrom (default) builds. This issue has been resolved. Now the correct values are returned for these objects when the current install matches the temporary or preferred install.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x 900-48	A⊺-9900	AT-9800
CR00010306	Install	3	If a user attempted to enter a filename with an invalid format, the resulting error message did not correctly describe the format that should have been used. Also, the router or switch returned an incorrect error message when a user attempted to delete a non-existent release licence file. These issues have been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00010315	BGP	3	Previously, it was possible to enter bad BGP peer IP addresses, such as 0.x.x.x, 127.x.x.x and 255.255.255.255. This issue has been resolved.	Y	Y	Y	Y	Y	Y	-	-	Y	Y	Y
CR00010465	Switching	3	The "?" help for the command show switch sock=con inst=value showed a maximum value of 4294967295. This issue has been resolved. Valid instance values are 0 and 1.	-	-	-	Y	Y	Y	Y	-	-	-	-
CR00010538	Firewall	3	When firewall events were recorded in the Notify queue (displayed in output of the command show firewall event=notify), the IP address shown would be the address of the very first packet that belonged to that event flow. For example, if 64 host scan packets were required to trigger a host scan event and the first packet had a target IP of 1.1.1.1 and the 64th had an IP of 1.1.1.64, then the IP address recorded would be 1.1.1.1, even though the event was not actually recorded until the 64th packet arrived. Additionally, the source and destination ports in this display would always show as 0. These issues have been resolved. The IP addresses shown are now those of the particular packet that triggered the event notification, and the source and destination ports used by that packet.	Y	Y	Y	Y	Y	Y	-	-	-	-	Y
CR00010976	РРР	3	If the router or switch received an Echo-Request that did not comply with RFC 1661, it processed and replied to the Echo-Request. This issue has been resolved. Non-complying Echo-Requests are now ignored.	Y	Y	Y	Y	Y	Y	-	-	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00010979	РРР	3	PPP incorrectly ACKed a LCP ConfigureRequest containing the Magic- Number option with a value of 0. This issue has been resolved.	Y	Y	Y	Y	Y	Y	-	-	Y	Y	Y
CR00010984	РРР	3	If the router or switch received an incorrectly formatted PAP request packet, it used to process the packet. This issue has been resolved—now it silently discards the packet. Also, if the router or switch received a PAP request packet with a zero length user ID, it used to send the packet to the authentication database. This issue has been resolved—now it NAKs the packet.	Y	Y	Y	Y	Y	Y	-	-	Y	Y	Y
CR00011223	Core	3	On AT-8948 and AT-9924SP switches with an empty PSU bay, an SNMP walk through of the fanAndPsPsuStatusTable would display lines for the non-existent PSU, with the value of "no such instance". This issue has been resolved. The walk through now only includes installed PSUs.	-	-	-	-	-	-	-	-	Y	Y	-
CR00011259	GUI	3	Some of the features supported in the web-based GUI did not have a complete set of online help pages generated for them. This issue has been resolved.	Y	Y	Y	Y	-	Y	Y	Y	-	Y	Y
CR00011315	IP Gateway	3	When the limit for the number of IP interfaces was reached and a user tried to add another IP interface over a VLAN, the router or switch displayed the following misleading error message: Error (3005273): No more VLAN interfaces may be added. This issue has been resolved. The error message is now: Error (3005273): No more IP interfaces over VLANs may be added.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

Version 291-20 C613-10488-00 REV S

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00011438	Ping	3	When the router or switch pinged a host whose hostname consisted only of the digits 0-9 and the letters A-F, it treated the given hostname as a hexadecimal IPX address even if the hostname was in the host list. This issue has been resolved. Now, when the router or switch pings a host using a hostname, it checks the hostname in the host list first. If it does not find the host in the host list, then it treats the hostname as an IPX address.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00011824	Firewall	3	When a firewall UDP session starts up, the session timeout should be 5 minutes for the first 5 packets of the session, then change to the configured UDP session timeout value. Previously, the timeout changed after the 6th UDP packet belonging to that session, instead of after the 5th packet. This issue has been resolved.	Y	Υ	Y	Y	Y	Y	-	-	_	-	Y
CR00012066	IP Gateway	3	The command show ip cassi command is obsolete but was still available. This issue has been resolved. The command has been removed from the command line. To obtain the same information, use the command show conf dyn=ip .	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00012168	Classifier	3	Output of the show classifier command displayed only the hexadecimal protocol value for IP SNAP, instead of also displaying the protocol name. This issue has been resolved. The output now displays: 0000000800 (IP SNAP)	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00012885	OSPF, GUI	3	If there were virtual OSPF interfaces, then the OSPF Interfaces GUI page showed all interfaces as belonging to the backbone area (0.0.0.0). This issue has been resolved.	Y	Y	Y	Y	-	Y	Y	Y	-	Y	Y
CR00013352	STP	3	The help displayed by the command set stp port=all ? listed some parameters twice. This issue has been resolved.	-	-	-	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x 900-48	A⊺-9900	AT-9800
CR00013494	IP Gateway	3	Once a default local IP address had been set, it could not be deleted. This was because the default interface does not have an interface number, but to delete a local interface, the user must specify the interface's number. This issue has been resolved, by adding an option called default to the delete ip local command. To delete the default local interface's address, use the command: delete ip local=default	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
			does not remove the interface itself.											
CR00013543	DHCP	3	If a user attempted to add a policy option to a DHCP policy by using the set command instead of the add command, then the resulting error message did not clearly indicate the cause of the error. For example, entering the command: set dhcp policy=test arptimeout=234 resulted in the error message: Error (3070061): ARPTIMEOUT not found. This issue has been resolved. The error message now reads: Error (3070279): Option ARPTIMEOUT was not found in policy test or was not added using the ADD DHCP POLICY command.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00013635	Ping, Traceroute	3	In the set trace command, it was possible to specify a minimum TTL value that was higher than the maximum TTL value. This issue has been resolved. The minttl and maxttl parameter are now checked to ensure that the value of minttl is less than or equal to the value of maxttl .	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00013637	Ping, Traceroute	3	If the value specified for the minimum time-to-live parameter (minttl) of the traceroute command exceeded the value set for the maximum time- to-live parameter (maxttl), the router or switch would attempt to execute the trace rather than generate an error message. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	AT-9900	AT-9800
CR00013832	EPSR, SNMP	3	When a user destroyed an EPSR domain, SNMP Requests returned information about the domain even though it no longer existed. This issue has been resolved.	-	-	-	-	-	-	-	-	Y	Y	-
CR00013920	Ping, Traceroute	3	If a user attempted to perform a traceroute without specifying the address to trace (either in the trace or set trace commands), the router or switch attempted to trace 0.0.0.0. This issue has been resolved. The router or switch now displays an error message.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00014103	VRRP, GUI	3	The VRRP priority could not be modified through the GUI—the priority option was there but did nothing. This issue has been resolved.	Y	Y	Y	Y	-	Y	Y	Y	-	Y	Y
CR00014137	РРР	3	A PPPoE Access Concentrator service that had been added by using the acinterface parameter to specify a VLAN (or by using the deprecated vlan parameter) could be deleted without specifying the acinterface parameter (or the deprecated vlan parameter). This issue has been resolved.	Y	Y	Y	Y	Y	Y	-	-	Y	Y	Y
CR00014159	RSTP	3	RSTP (correctly) only uses the top 4 of the available 16 bits for the bridge priority. If a user enters a value that is not a multiple of 4096, the switch rounds the value down. Previously, the switch did not inform users when it rounded the value. This issue has been resolved. The switch now displays an info message when it rounds the bridge priority. Note that this only happens for RSTP. STP uses all 16 bits for the bridge priority.	-	-	-	Y	Y	Y	Y	Y	Y	Y	Y
CR00014203	OSPF	3	When OSPF was disabled and a BGP redistribution definition existed, then the obsolete command set ospf bgplimit=<i>limit</i> did not update the limit in the BGP redistribution definition. This meant that the limit was incorrect when OSPF was enabled again. This issue has been resolved.	Y	Y	Y	Y	Y	Y	_	_	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00014304	LLDP	3	The help displayed for the LLDP port parameter (in such commands as show lldp port=?) incorrectly indicated that the port parameter is a "string 1 to 255 characters long". The port parameter is instead an Ethernet switch port number or a range of numbers. This issue has been resolved. The help is now correct.	Y	-	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00014330	Ping	3	The maximum value for the delay parameter of the ping command was too long. This issue has been resolved by changing the range for the delay from 0-4294967295 to 0-604800. This new maximum is the number of seconds in one week.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00014879	Switching, RSTP, SNMP	3	Previously, an incorrect value was returned for the port number when responding to an SNMP Request for MIB object dot1dSTPRootPort. This issue has been resolved.	-	-	-	Y	Y	Y	Y	Y	Y	Y	Y
CR00015466	Core, Install, PoE	3	The output of the show cpu command on the AT-8624POE switch showed relatively high CPU usage when the device was idle. This issue has been resolved.	-	-	-	-	-	-	Y	-	-	-	-
CR00016183	File	3	If a user attempted to delete a locked file, such as the currently-installed GUI resource file, the router or switch displayed both an operation error message and an operation successful message. This issue has been resolved by removing the incorrect operation successful message.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00016429	OSPF	3	 Previously, OSPF logged the same message for two separate errors. These errors were when OSPF rejected a database description message because: the neighbour was in a state of "down" or "attempt", or the MTU received from the neighbour was larger than the receiving system could handle. This issue has been resolved. Separate error log messages are now generated for these two errors. 	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00016452	РРР	3	It is valid to use the command create ppp= <i>number</i> to create a PPP interface without specifying the underlying layer 1 interface. However, executing this command, or including it in a boot script, resulted in an error. This issue has been resolved.	Y	Y	Y	Y	Y	Y	-	-	Y	Y	Y
CR00016578	IPv6	3	If IPv6 was disabled and a user entered any of the following commands: add ipv6 interface add ipv6 6to4 add ipv6 tunnel create ipv6 interface enable ipv6 advertising then the router or switch correctly displayed a warning message to indicate that IPv6 was disabled and also correctly performed the specified configuration. However, it did not display an "Operation successful" message to indicate that the configuration had changed. This issue has been resolved. The router or switch now displays the "Operation successful" message as well as the warning message.	Y	Y	Y	Y	Y	Y	_	_	Y	Y	Y
CR00016735	ΑΤΜ	3	Sometimes, the router displayed the following error message: Internal Error: speed mismatch causing transmit internal rate underrun error. This was due to a mismatch in the synchronisation between the internal rate of the ATM controller in the CPU and the speed of the ATM PHY connector. This synchronisation mismatch had a small impact on ATM performance. This issue has been resolved.	Y	-	-	-	-	-	-	-	-	-	-
CR00016925	TTY	3	If a user was accessing the router or switch via telnet, and sent a ^P (break) character followed by the character d or D, then the router or switch displayed an unwanted diagnostic message. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x 900-48	A⊺-9900	AT-9800
CR00017019	Port Authentication	3	On termination of an 802.1x session, an accounting message is sent to the Radius server. This enhancement implements the Acct-Input-Octets, Acct-Output-Octets, Acct-Input-Packets, and Acct-Output-Packets fields in the message. Note that this enhancement only applies to ports in single-supplicant mode. These fields in the accounting message for ports in multi-supplicant mode still all have a value of 0.	Y	Y	Y	Υ	Υ	Y	Y	Y	Y	Υ	Y

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00011228	GUI, Switch	4	The Diagnostics > Layer 2 Forwarding Database page of the GUI displayed extra internal (SYS or CPU) entries. This issue has been resolved. The GUI and the command show switch fdb now display the same information.	_	-	_	Y	Y	Y	Y	Y	_	_	_
CR00013409	Switch	4	Previously, if you used the ? or Tab keys to obtain help for the set switch ageingtimer command, the resulting help said that valid entries were from 0 to 4294967295. However, the correct range of values is from 16 to 4080 seconds for AR750S routers and from 10 to 630 seconds for AR770S routers. This issue has been resolved. The "?" help now displays the correct ranges.	_	_	Y		_	_	_	_	_	_	_
CR00014205	OSPF	4	The command purge ospf did not delete OSPF redistribution definitions. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x 900-48	A⊺-9900	AT-9800
CR00014302	TTY	4	If the router or switch configuration file contained the command set tty idle , the router or switch produced a corrupted log message when it started up. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

Enhancements

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00012822	BGP	-	The BGP counter output display has been significantly improved. Also, the command show bgp counter=all now prints out the RIB, UPDATE, DB and PROCESS counters.	Y	Y	Y	Y	Y	Y	-	-	Y	Y	Y
CR00016099	MACFF, DHCP Snooping	-	MAC-forced forwarding has been enhanced for use in a hospitality situation, such as a hotel. The enhanced solution allows hotel guests to connect to the network without having to change their IP settings, while still ensuring privacy for each guest. Typically some guests will obtain their IP address from the hotel's DHCP server and others will have statically configured IP addresses in their PCs.	-	-	-	Y	Y	Y	Y	Y	-	-	-
			The solution is designed to interoperate with a specialised Access Router that is able to deal with the full range of IP addresses that will be in use on the guests' PCs. The Nomadix Access Gateway (from www.nomadix.com) is an example of such a specialised access router.											
			Configuration of the new feature is similar to the existing MAC-forced forwarding configuration. On each edge switch, you also need to enter the following new command before enabling DHCP snooping: disable dhcpsnooping ipfiltering											
			You also need to turn on ARP security and allow authorised clients to send only unicast packets, by entering the following commands: enable dhcpsnooping arpsecurity enable dhcpsnooping strictunicast											
			This enhancement also introduces the ability to add MACFF servers with static MAC addresses, rather than relying on ARP to determine them based on IP addresses. To do this, enter the command: add macff server mac=macaddr											

CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00016662 CR00016891 CR00017335 CR00017937		-	This software release supports the new x900-48FS switch. For an overview of the switch, see "Support for the new x900-48FS switch (CR00016662)" on page 246.	-	-	-	-	-	-	-	-	Y	-	-
CR00016913	PPP	-	This enhancement enables the PPPoE client to establish a session promptly after a restart or power cycle. This is done by sending a PPPoE Active Discovery Terminate (PADT) frame in response to a frame received with an unknown PPPoE session ID.	Y	Y	Y	Y	Y	Y	-	-	Y	Y	Y
CR00017197	SSH, User, RADIUS	-	SSH sessions to the router or switch can now be authenticated via RADIUS. The router or switch attempts to authenticate an SSH user via RADIUS if the user to be authenticated is not configured in the local user database and the router or switch has RADIUS configured.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00017395	Firewall	-	This enhancement enables the firewall to establish accurate MSS (Maximum Segment Size) values for TCP sessions without using the MTU discovery process. MTU discovery depends on ICMP error packets, so does not work in networks that do not forward ICMP error packets. To enable this feature, use the command:	Y	Y	Y	Y	Y	Y	-	-	-	-	Y
			enable firewall policy=name adjusttcpmss The adjusttcpmss parameter enables the firewall to adjust the MSS value stored inside incoming TCP SYN packets, to reflect the lower of the two MTU values on the ingress and egress interfaces. Normally, for example, if a TCP SYN packet arrives from an interface with an MTU of 1500 and leaves on an interface with an MTU of 1000, the MSS inside the SYN packet will remain at 1460. When this feature is enabled, the MSS will be adjusted to 960 because the firewall knows that the egress interface has a smaller MTU. Note that the firewall does not change the original MSS value if it is already lower than the values of the ingress and egress interfaces. To disable this feature, use the command: disable firewall policy=name adjusttcpmss This feature is disabled by default.											

CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00017482	IGMP Snooping	-	The IGMP snooping fast leave option has been enhanced, to make it available when multiple clients are attached to a single port on the snooping switch. For configuration information, see "IGMP snooping fast leave in multiple host mode (CR00017482)" on page 247.	Y	-	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00017532	WAN Load Balancing	-	 WAN load balancing can now also balance traffic across IP interfaces that are configured on VLANs. This means it is now available for the following IP interfaces: eth (such as eth0) ppp (such as ppp0) vlan (such as vlan1) 	Y	-	Y	-	-	-	-	-	-	-	-
CR00017701	IGMP	-	IGMP filtering is now available on AT-8600 series switches. For more information, see the <i>IP Multicasting</i> chapter of the switch's Software Reference, or <i>How To Configure IGMP for Multicasting on</i> <i>Routers and Managed Layer 3 Switches</i> , available from www.alliedtelesis.com/resources/literature/howto.aspx.	-	-	-	-	-	-	Y	-	-	-	-

Features in 291-07

Software Maintenance Version 291-07 includes the resolved issues and enhancements in the following tables. In the tables, for each product series:

- "Y" indicates that the resolution is available in Version 291-07 for that product series.
- "-" indicates that the issue did not apply to that product series.

Level 1

No level 1 issues

Level 2

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	Rapier w	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00017869	IP Gateway	2	If two routes to the same destination were present in a switch, and the route of lower preference was deleted (in other words, the route whose details were present in the hardware routing database), then the hardware routing database was not updated with the remaining route as it should have been. This could cause serious routing issues. This issue has been resolved so that hardware routing database updates are carried out correctly.	-	-	-	-	-	-	-	-	-	Y	Y
CR00018039	Switch	2	Running the command show switch tab=ip could result in a reboot if a large number of routes (10,000 or more) were present on the switch. This issue has been resolved so that the command can run no matter how many routes are present on the switch. However, the output from the command may be truncated due to buffer space restrictions.	-	-	-	-	-	-	-	-	-	Y	Y

Level 3

No level 3 issues

Level 4

No level 4 issues

Enhancements

No enhancements

Features in 291-06

Software Maintenance Version 291-06 provided support for the new Rapier 48w switch. For more information, see "Support for the new Rapier 48w switch" on page 249.
Features in 291-05

Software Maintenance Version 291-05 includes the resolved issues and enhancements in the following tables. In the tables, for each product series:

- "Y" indicates that the resolution is available in Version 291-05 for that product series.
- "-" indicates that the issue did not apply to that product series.

Level 1

No level 1 issues

CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00007737	IGMP Snooping	2	When a port left a multicast group, the router or switch assigned the All Groups port to that multicast group. This could be seen in the output of the command show ip igmp —the list of ports for the group would include the All Groups port. This issue has been resolved.	Y	-	Y	Y	Y	Y	Y	Y	Y	Y
CR00010003 CR00011533	WAN load balancer, Firewall	2	The router rebooted if a user cleared all active WAN load balancer sessions on a router that had more than approximately 15000 active sessions. This issue has been resolved Also, the maximum session limit for the WAN load balancer should be 2 * the firewall session limit. On AR415S and AR442S routers, users can increase the firewall session limit by adding special feature licenses. Previously, if the firewall session limit changed, it was necessary to reboot the router to update the WAN load balancer session limit. This issue has been resolved. The WAN load balancer limit now updates when you enable the firewall session license.	Y	Y	Y	_		_	_	_	_	

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00012980	VLAN	2	Previously, it was possible to destroy a VLAN when it was configured as an IP interface. This issue has been resolved. Now, you can only destroy a VLAN if it has no IP configuration.	Y	-	Y	Y	Y	Y	Y	Y	Y	Y
CR00013041	IPsec	2	The router or switch would establish IPsec Security Associations (SAs) if ISAKMP was enabled but IPsec was disabled. This issue has been resolved. The router or switch only sets up SAs if IPsec is enabled.	Y	Y	Y	Y	Y	-	-	-	-	-
CR00013500	User, 802.1x	2	If the reauthentication period for 802.1x port authentication was set to less than 20 seconds, the router or switch sometimes rebooted. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00013527	OSPF	2	When the router or switch produced an OSPF type 7 LSA, it sometimes specified a route out of an interface that was down. This would stop the router or switch from forwarding traffic to the route's destination. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00014344	GUI	2	Previously, some GUI pages did not display correctly in version 7 of Internet Explorer. This issue has been resolved.	-	-	-	-	-	Y	-	-	-	-
CR00014851	SHDSL	2	Very occasionally, an AR442S router would reboot if SHDSL interface train-up took an excessively long time. This issue has been resolved.	Y	-	-	-	-	-	-	-	-	-
CR00014955	OSPF	2	The router or switch sometimes rebooted when converting OSPF type 7 LSAs to type 5 LSAs. This issue has been resolved by increasing the robustness of the translation mechanism. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00015569	Firewall	2	When only NAT was enabled on the firewall, during some TCP connections in which either end of the connection sends FIN (finished) messages immediately after sending some data and the other end ACKs (acknowledges) the data and the FIN message consecutively, the firewall sometimes incorrectly interpreted the first ACK message (intended for the data) as belonging to the FIN message and prematurely shut the connection down. This could prevent the firewall from opening up new connections using the same port numbers. This issue has been resolved.	Y	Y	Y	Y	Y	-	_	_	-	Y
CR00015592	BGP, IP Gateway	2	When BGP learned new best routes for a particular destination, it did not always clear any active IP flows that used the previous best route. Therefore, the router or switch continued to forward traffic sub-optimally. This issue has been resolved. Now, when BGP inserts new routes into the IP route table, it deletes all active route flows, so any active flows change to using the new route. The time taken to delete a full table of IP flows has also been greatly reduced.	Y	Y	Y	Y	Y	-	_	Y	Y	Y
CR00015736	Switch	2	Sometimes IP routed traffic would be sent out the correct port, but with the destination MAC of another device on the network. This issue was most likely to occur in configurations that use multi-homed interfaces on multiple VLANs for end devices. This issue has been resolved.	-	-	-	-	-	-	-	Y	Y	-
CR00015822	Switch	2	When the command enable ip macdisparity was used, and a static ARP entry was configured with an L2 multicast MAC address, the switch should have broadcast traffic to that multicast MAC address out all ports in the VLAN. This was not happening. This issue has been resolved.	-	-	-	-	-	-	-	Y	Y	-
CR00015861	VRRP	2	After manually disabling the master VRRP router, sometimes a backup router that should assume master status would not do so, and VRRP would cease to function properly. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	AT-9900	AT-9800
CR00015938	DHCPv6	2	For DHCPv6, the router or switch now supports Prefix Delegation according to RFC 3633. The previous implementation was according to an Internet draft and did not interoperate with other DHCPv6 implementations. This issue has been resolved.	Y	Y	Y	Y	Y	-	-	Y	Y	Y
CR00015974	DHCPv6	2	The DHCPv6 client regularly wrote the file client6.dhc, which over time caused unnecessary Flash compactions. This issue has been resolved. The DHCPv6 client now only writes the file when the contents are different from the previous time that the file was written. This greatly reduces the number of Flash compactions caused.	Y	Y	Y	Y	Y	-	-	Y	Y	Y
CR00015984	DHCPv6	2	DHCPv6 authentication did not work correctly. This issue has been resolved. You can now configure the router or switch to authenticate DHCPv6 exchanges.	Y	Y	Y	Y	Y	-	-	Y	Y	Y
CR00015989	TPAD	2	When using the TPAD autodial feature and sending multiple transactions over a TCP/IP connection, the router or switch responded to good APACS packets by sending an ACK. This ACK was unnecessary and could cause interoperability issues. This issue has been resolved. The router or switch no longer sends the ACK in these circumstances.	Y	Y	Y	Y	-	-	-	-	-	
CR00016034	IP Gateway, Firewall	2	Previously it was not possible to add a static ARP entry for the corresponding partner address of a /31 subnet interface. This issue has been resolved. The router or switch will now also allow /31 ARP requests to pass through the firewall.	Y	Y	Y	Y	Y	-	-	-	-	Y
CR00016060	IGMP	2	If a port was disabled from being an All Routers group port for IGMP, and that port received All Routers group traffic, it would incorrectly be added to the All Routers group. This issue has been resolved.	Y	-	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00016128	IPsec, IPv6	2	When the icmptype parameter was changed to none for an IPv6 IPsec policy, an incorrect ICMP type value was displayed in output of the command show config dyn and saved in the configuration file produced by the command create config . This issue has been resolved.	Y	Y	Y	Y	Y	-	-	-	-	-
CR00016180	GUI, Firewall	2	When configuring the firewall with the GUI, the Policy options tab did not update its display when options were changed from the default settings. For example, if the user cleared a checkbox and clicked the Apply button, the router correctly turned off that option, but the GUI showed a check in the checkbox. This issue has been resolved.	Y	-	-	-	-	-	-	-	-	-
CR00016200	Core	2	The router or switch's handling of soft errors has been further improved. Soft errors are spontaneous changes in the information stored in a digital circuit, caused by physical effects.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00016288	SYN	2	The polarity of the CD output of RS-232 DCE and V.35 DCE SYN cables was reversed—it was ON when OFF was selected and vice-versa. This issue affected AR750S, AR770S, and AR44xS series routers. This issue has been resolved.	Y	-	Y	-	-	-	-	-	-	-
CR00016303	Load	2	The upload command did not always work if the server parameter was set with the set load command instead of being specified in the upload command. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00016327	IP Gateway	2	If a policy filter was configured, ping sometimes failed. This happened because the router or switch assigned the ICMP echo replies to an IP flow without checking that the interface for the echo replies matched the interface for the flow. Therefore, the router or switch could use the wrong flow to forward the replies. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00016364	DHCPv6	2	If an IPv6 DHCP client was forced to rebind to a router or switch acting as a DHCP server, the server returned incorrect timing parameters to the client. Some clients were able to cope with this, but others could end up losing their DHCP lease. This issue has been resolved.	Y	Y	Y	Y	Y	-	-	Y	Y	Y
CR00016365	DHCPv6	2	 The following issues occurred with DHCPv6: The option IDs for DNS name server and domain search list were incorrect. This caused interoperability issues with other implementations. The domain names specified in the domain name option were encoded incorrectly. This caused interoperability issues with other implementations. If a user entered two DNS servers for a DHCPv6 policy, then saved the configuration, the command was not saved correctly. When the router or switch ran the configuration on start-up, it added only the second DNS server to the policy. These issues have been resolved. 	Y	Y	Y	Y	Y	-	-	Y	Y	Y
CR00016379	IGMP Proxy, Switch, IP Gateway	2	If IGMP proxy was enabled and multicast data was received on a downstream VLAN interface, that data would be transmitted to other interfaces. Also, the VLAN interface that received the data would forward two copies of the packet to other ports on that VLAN. These issues have been resolved.	Y	-	Y	Y	Y	Y	Y	Y	Y	-
CR00016394	IP Gateway	2	ARP did not work correctly on logical /31 interfaces, which prevented regular IPv4 communications from working over these logical /31 interfaces. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00016418	STP	2	If the switch received IGMP packets on the non-lead port of a trunk group which was participating in a Spanning Tree, in some circumstances the switch would forward the packets out of an STP-blocked port in the trunk. This issue has been resolved.	-	-	-	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	AT-9900	AT-9800
CR00016489	BGP	2	When BGP capability matching was changed to strict , that setting was not displayed in output of the command show config dyn or saved in the configuration file produced by the command create config . When the router or switch ran the configuration file on start-up, the capability matching setting reverted to the default of loose . This issue has been resolved.	Y	Y	Y	Y	Y	-	-	Y	Y	Y
CR00016526	РРР	2	An interoperability issue with a malfunctioning PPP peer meant that the peer could ACK an IP address of 0.0.0.0 when it was required to offer a valid public IP address. This issue has been resolved. The router or switch now refuses to accept this incorrect negotiation and instead resends a configure request for an IP address.	Y	Y	Y	Y	Y	-	-	Y	Y	Y
CR00016576	IPv6	2	The router or switch sometimes rebooted after receiving an IPv6 router advertisement, or after the command set ipv6 interface was entered. This issue has been resolved.	Y	Y	Y	Y	Y	-	-	Y	Y	Y
CR00016621	Switch	2	On 48-port switches, hardware filters with the eport parameter specified did not always behave correctly. This issue has been resolved.	-	-	-	Y	Y	Y	Y	-	-	-
CR00016698	BGP	2	 The following issues occurred when using BGP aggregate specifications (created using the command add bgp aggregate): When an aggregate route was originated from routes learnt from external peers, and then all of the contributing child routes were withdrawn by the external peers, the aggregate route was not removed from the routing table. It could still be advertised to external peers. When a network or import entry (add bgp network or add bgp import) resulted in a route entry that had the same prefix length as the aggregate specification, then BGP (correctly) originated the aggregate route. However, deleting the network or import definition did not remove the aggregate route from the routing table. These issues have been resolved. 	Y	Y	Y	Y	Y	-	-	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00016727	TCP, Telnet	2	The speed of the output from the Telnet server has been increased.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00016762	ISDN	2	For AR44xS series routers with system territory set to USA, the ISDN Q.931 SPIDs failed to initialize to the ISDN exchange/ISDN USA profile simulator (both manual and auto SPIDs) after a reboot. This happened because the router did not write *.spd files to Flash memory, so the SPID initialization failed on reboot because the SPIDs did not exist. This issue has been resolved. The *.spd files are now correctly written to Flash memory, which allows SPIDs to initialise after a reboot.	Y	-	-	-	_	-	-	-	-	-
CR00016804	Bridge	2	If an Ethernet packet, including its FCS (Frame Check Sequence), was encapsulated in PPP and bridged to a VLAN interface, the packet could contain two FCS values. This issue has been resolved.	Y	Y	Y	-	-	-	-	-	_	-
CR00016855	Frame Relay	2	When the MTU of a Frame Relay logical interface was modified (by using the command set interface= <i>fr-int</i> mtu= <i>value</i>), incorrect interface and MTU settings were displayed in output of the command show config dyn and were saved in the configuration file produced by the command create config .	Y	Y	Y	Y	-	-	-	-	-	-
CR00016856	Firewall	2	When the firewall policy for an interface had a NAT type of ENAPT, the firewall did not correctly translate the destination addresses of incoming packets that matched "allow" rules. This issue has been resolved.	Y	Y	Y	Y	Y	-	-	-	-	Y
CR00016911	Classifier	2	When a non-default protocol was specified for a classifier, in some circumstances that protocol setting was not displayed in output of the command show config dyn or saved in the configuration file produced by the command create config . When the router or switch ran the resulting configuration file on start-up, the protocol setting was lost. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	AT-9900	AT-9800
CR00016940	Core	2	Some versions of the AT-G8T GBIC prevented the switch from detecting and setting up the AT-A47 expansion board correctly. This issue occurred on start-up when the GBIC was installed and had a link up. This issue has been resolved.	-	-	-	-	-	Y	-	-	-	-
CR00016941	IP Gateway	2	When there were multiple routes to a destination and the best route was deleted from the switch's hardware routing table, the switch did not use the alternative route. Also, the switch only used the best route, even if ECMP was supported. This issue has been resolved. When multiple routes exist and the best route is deleted from the hardware table, the switch now adds the next best route to the hardware table correctly. If the switch supports ECMP, all routes are now added to hardware, not just the best route.	-	-	-	Y	Y	Y	Y	Y	Y	Y
CR00017006	Switch	2	Previously, the link to the AT-G8T GBIC would not come up automatically when its auto-negotiation slide switch was set to "on". This was because the switch configured the GBIC in a fixed speed mode by default. This issue has been resolved. The link now comes up automatically when the auto-negotiation slide switch is set to "on". To bring the link up when auto- negotiation is set to "off", use the command: set swi port= <i>port-list</i> speed=1000mf	-	-	-	-	-	-	-	-	-	Y
CR00017031	IGMP Snooping	2	If a port on the router or switch joined and left many IP multicast groups, the router or switch sometimes did not transmit all multicast packets to all receivers. This issue has been resolved.	Y	-	Y	Y	Y	Y	Y	Y	Y	Y
CR00017036	Switch	2	In some trunk configurations, the STP state of trunks was incorrectly applied to non-trunk ports. This could result in incorrect traffic flows in the network. This issue has been resolved.	-	-	-	-	-	-	-	Y	Y	-

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	AT-9900	AT-9800
CR00017074	DHCPv6	2	 DHCPv6 prefix delegation contained the followed issues: previously, the command create dhcp6 range accepted ranges with an invalid prefix length. This issue has been resolved. The router or switch now displays an error unless the prefix length is in the range 48-64. previously, when the router or switch requested a prefix to delegate to its appint interfaces, it could only use prefixes of length 48 or 64. This issue has been resolved. The requesting router or switch can now use any prefix that has been delegated to it, as long as the prefix length is less than or equal to 64 bits. The requesting router or switch would allocate an address to the interface 	Y	Y	Y	Y	Y	-	-	Y	Y	Y
			This issue has been resolved. The router or switch no longer does this.										
CR00017076	IPsec	2	When entering the command set ipsec policy , the value of the respondsetbadspi was incorrectly reset to its default of false , unless it was also included in the set command. This issue has been resolved.	Y	Y	Y	Y	Y	-	-	-	-	-
CR00017146	IP Gateway	2	When the router or switch's Local address was pinged, the router or switch responded from the interface address of the interface through which it received the ping, instead of the Local address to which the ping was sent. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00017151	Telnet	2	When Reverse Telnet was enabled the command shell was (correctly) disabled on all ASYN ports apart from ASYNO. However when Reverse Telnet was disabled again, the command shell was not re-enabled on the other ASYN ports. This issue has been resolved.	Y	Y	Y	Y	-	-	-	-	-	-
CR00017239	VLAN, IGMP Snooping	2	When a user configured IGMP static router ports, the configuration file produced by the command create config could be invalid. When the router or switch ran the resulting configuration file on start-up, it produced an error instead of configuring the router ports. This issue has been resolved.	Y	-	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	AT-9900	AT-9800
CR00017257	WAN Load Balancer	2	If two WAN load balancer healthcheck hosts were defined, and one was unreachable and the other was reachable, WAN load balancer resources were (correctly) in the UP state because at least one healthcheck host was reachable. However, removing the reachable host (by using the command delete wanlb healthcheck) should have changed the WAN load balancer resources to the DOWN state, but did not. This issue has been resolved. If the only healthcheck host available is unreachable and the resource is currently in the UP state, the next unreachable healthcheck received from that host now forces the resource to the DOWN state	Y	Y	Υ	-	-	-	-	-	-	-

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00008225	Core	3	 Some early software versions, on some products, supported the command show system temperature. This command was deprecated after version 2.6.4. If a user entered this command on any product, the following message was displayed: Info (1034107): SHOW SYSTEM TEMPERATURE is no longer available. Please use SHOW SYSTEM ENVIRONMENTAL instead. However, only the following products use the show system environmental command to display the temperature: AR750S and AR770S routers, and AT-8600, AT-8800, AT-8948, x900-48, and AT-9900 series switches. Other products use show system instead. On the other products, the above error message was incorrect because it stated that the show system environmental command was available. This issue has been resolved. On products that do not use show system environmental, the following error message is displayed if you enter the show system temperature command: Info (1034090): Command unavailable on this product. 	Y	Y	-	Y			Y			Y
CR00009036	File	3	If a user tried to copy a small file (less than 32 bytes) in Flash when there was not enough free Flash space for the file and its header, the router or switch did not generate an error message, and the copying could appear to have succeeded. This issue has been resolved. The error message: Insufficient space to store file [file name] is now displayed under those conditions.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00010518 CR00010710	Core	3	The show cpu statistics were unnecessarily inaccurate. For example, a router or switch that was effectively idle showed a CPU usage of 10% to 12%. This issue has been resolved. When the router or switch is effectively idle, the CPU usage now displays as less than 5%.	-	Y	-	-	-	-	-	-	Y	-

CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00011629	PIM, PIM6, ECMP	3	Previously, the switch's count of PIM4 and PIM6 bad Bootstrap Messages (BSMs) could be high, because the switch forwarded BSMs over interfaces that contained an Equal Cost Multipath (ECMP) route to the receiving interface. This issue has been resolved. BSMs are no longer forwarded via all interfaces contained in an ECMP group, but only via one interface in the group.	-	-	-	-	-	-	-	Y	Y	-
CR00012495	IGMP	3	When an IGMP filter was destroyed, switch ports that used the filter did not have their IGMP filter setting returned to "None". This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00014324	PPP	3	The interface MIB ifInOctets and ifOutOctets counters displayed by the show ppp counter command incorrectly included the lower layer framing octets and were 5 octets per frame greater than they should have been. This issue has been resolved.	Y	Y	Y	Y	Y	-	-	Y	Y	Y
CR00014919	QoS, DHCP snooping	3	DHCP snooping accepted a minimum of one new client per QoS flow group, instead of a minimum of one new client per port. This meant that DHCP snooping sometimes did not respect the lease limit (maxlease) on a port. This issue has been resolved.	-	-	-	Y	Y	Y	Y	Y	Y	-
CR00015092	АТМ	3	 Previously, the information output by the "?" help for the ATM channel pcr parameter was incorrect. This issue has been resolved. The "?" help now displays: required - decimal in the range 32-155000 (dependant on physical interface) If you enter a value larger than the maximum PCR allowed on a specific physical interface, the router now displays the following message for ADSL: The PCR supplied was too large, the maximum is 1024 and the following message for SHDSL: The PCR supplied was too large, the maximum is 4608 	Y	-	-	-	-	-	-	-	-	-

CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00015558	ASYN	3	Under some circumstances, when a PC terminal emulator was opened to communicate with a router or switch after the router or switch had fully booted up, the login prompt did not immediately display. To display the login prompt, it was necessary to remove and re-insert the cable. This issue applied to all models' ASYN ports except ports on the AR024 PIC. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00015690	DHCP6	3	In the command create dhcp6 range , the ip parameter correctly has the syntax <i>prefix1[-prefix2]</i> . However, the second prefix was previously not optional. This issue has been resolved, so that the second prefix (of the form <i>ipv6address/ prefixlength</i>) is no longer required. If you do not enter a second prefix, it is now calculated from the first prefix. The second prefix has the same prefix length at the first and has all 1s in the non-significant part of the address. For example, the second prefix for 3ffe:1:2:3::/64 would be 3ffe:1:2:3:ffff:ffff:ffff:ffff:ffff.	Y	Y	Y	Y	Y	-	-	Y	Υ	Y
CR00015881	SNMP, Switch	3	The SNMP objects dot3StatsSQETestErrors and dot3StatsCarrierSenseErrors are not supported on AR750S, AR410, and AR450S routers. Previously SNMP GET got a random value for these objects. This issue has been resolved. SNMP GET now gets 0 for these objects.	Y	-	Y	-	-	-	-	-	-	-
CR00015969	WAN load balancer	3	After the command reset wanlb resource=all was entered, WAN load balancer resources would show their state as "UP" even if the underlying IP interface was down. This issue has been resolved.	Y	Y	Y	-	-	-	-	-	-	-
CR00016001	DHCPv6	3	When a DHCPv6 client was soliciting for servers, the selection of the best server did not proceed in the way specified by the RFC. This issue has been resolved.	Y	Y	Y	Y	Y	-	-	Y	Y	Y
CR00016177	Switch, MIB	3	The default value of the MIB object ifJackType for the GBIC slot on AT-8800 series switches was incorrect if no GBIC card was plugged in. This issue has been resolved. The default value is now "other(1)".	-	-	-	-	Y	-	-	-	-	-

				3400	37x5	37×05	apier i	-8800	-8600	-8700XL	00-48	0066-	-9800
CR	Module	Level	Description	AF	A	A	Ra	F	F	F	×9	A	F
CR00016228	QoS	3	If a QoS policy uses the same classifier more than once, the router or switch now displays a warning message. You should not use a classifier more than once in a policy because the operation of such policies is unpredictable.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00016463	DHCPv6	3	 For the command create dhcp6 range, DHCPv6 now checks that the specified address or prefix range is valid for the specified type of range. Valid options are: address1-address2 (e.g. 3ffe:1:2:3:4:5::1-3ffe:1:2:3:4:6::ffff) This is a range of addresses for address assignment (type=normal or type=temporary). address/prefixLen (e.g. 3ffe:1:2:3:4:5::/96) This is a range of addresses for address assignment (type=normal or type=temporary). address/prefixLen (e.g. 3ffe:1:2:3:4:5::/96) This is a range of addresses for address assignment (type=normal or type=temporary). address/prefixLen-address/prefixLen (e.g. 3ffe:1:2::/48-3ffe:1:40::/48) This is a range of prefixes for prefix assignment (type=pd). 	Y	Y	Y	Y	Y	-	-	Y	Y	Y
CR00016799	Core	3	For revision M1 of AR770S routers, the low-end threshold for monitoring the 1.2 volt rail was too high. This caused power supply monitoring false alarms. To check the router revision, use the command show system and check the "Rev" entry underneath the time and date. This issue has been resolved—the threshold is now correct.	-	-	Y	-	-	-	-	-	-	-
CR00017008	Core	3	Revisions M3-1and later of the AR745 router do not support Redundant Power Supplies. Therefore, for these routers, RPS monitoring information has been removed from output of the command show system , and it is no longer possible to use the command set sys rpsmonitor .	-	Y	-	-	-	-	-	-	-	-

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00000396	IGMP	4	If a static IGMP port went link down, it was not shown in the "Static Ports" list in the output of the show ip igmp command. This was only a display issue. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00011560	Install	4	It is no longer possible to specify a compact flash file as the boot configuration file. If the command set config=cf: <i>filename.cfg</i> is entered, the router or switch does not change the current boot configuration file and instead displays the following error message: Cannot specify configuration file in Compact Flash	-	-	Y	-	_	-	-	Y	Y	Y
CR00013976	IGMP	4	The list of parameters output by the "?" help for show ip igmp ? incorrectly included "IGMP". This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00015543	Bridge	4	In output of the command show bridge spanning , the bridge identifier was correctly displayed as a hexadecimal number, but it was not obvious that the number was hexadecimal. This issue has been resolved. The output now has 0x in front of the hexadecimal number, to make it clear that it is hexadecimal.	Y	Y	Y	-	-	-	-	-	-	-
CR00016126	QoS, Switch	4	When a QoS policy was associated with a port that was set to a speed less than the maximum speed of the port, a warning message would be displayed on the console session and in the log when the port state changed to UP. This message stated that the QoS policy operation may be affected by the speed setting of the port. Having this message displayed on the console was considered unnecessary and potentially confusing. This issue has been resolved. The message is now only displayed in the log.	-	-	-	Y	Y	Y	Y	Y	Y	Y
CR00016451	IP Gateway	4	When a second metric was displayed in the output of the command show ip route (because of OSPF, for example) this metric was truncated to 2 characters. This issue has been resolved. The output now displays both metrics in a field up to 10 characters long.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

Enhancements

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00014288	GUI	-	An ADSL connection option has been added to the Wizards page of the GUI for AR44xS routers. This option links to the xDSL configuration section, which lets you configure all basic ADSL or SHDSL settings on one convenient page. If your router GUI does not open at the Wizards page, click on the Wizards button at the top of the left-hand menu to access it.	Y	-	-	-	-	-	-	-	-	-
CR00014667	РРР	-	This enhancement increases the amount of time that the router or switch waits for a CHAP Success message. This enables the router or switch to successfully complete authentication, even in particularly slow networks. The first authentication attempt still times out after 3 seconds, but the second attempt takes 6 seconds to time out, and any further attempts take 9 seconds.	Y	Y	Y	Y	Y	-	-	Y	Y	Y
CR00015432	ADSL, GUI	-	 The GUI for AR440S and AR441S routers now displays statistics for the ADSL port. You can now see: a pop-up summary box, by clicking on the port on the System Status page ADSL port details, by selecting the new ADSL Statistics page in the Diagnostics menu ADSL port counters, by selecting the new ADSL Counters page under Layer 1 Counters in the Diagnostics menu 	Y	-	-	-	-	-	-	-	-	-
CR00016078	Software QoS, PPP, Ethernet, VoIP	-	The router or switch now supports software QoS on PPPoE interfaces. Note that this enhancement is not available on AR770S routers.	Y	Y	Y	Y	-	-	-	-	-	-

198

CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00016150	IPsec, IPv6	-	To establish a tunnelled IPsec connection for IPv6, you may need to specify the source IP interface in the IPsec and ISAKMP policies. This enhancement enables you to do so. To specify the source interface, use the srcinterface parameter in the commands: create ipsec policy=name <other parameters=""> set ipsec policy=name <other parameters=""> create isakmp policy=name <other parameters=""> set isakmp policy=name <other parameters=""> set isakmp policy=name <other parameters=""> the global address of the source interface (if available) will be used as the local address of the policy.</other></other></other></other></other>	Y	Y	Y	Y	Y	_	-		_	-
CR00016221	Load, MIBs	-	 With this enhancement, you can use SNMP to: set parameters for uploading files from the router or switch, and upload files to a TFTP server SNMP already lets you save the current configuration to a file on the router or switch. You can use this with the new options to back up the configuration to a TFTP server. For more information, see "Backing up the configuration with SNMP (CR00016221)" on page 250. 	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	AT-9900	AT-9800
CR00016234	DHCP Snooping	-	 This enhancement enables the router or switch to log discarded ARP requests when ARP security is enabled. By default, discarded ARP requests are not logged. To turn logging on, use the command: enable dhcpsnooping log=arpsecurity To turn it off, use the command: disable dhcpsnooping log=arpsecurity To see whether it is enabled, use the existing command: show dhcpsnooping and check the new "Logging enabled" entry. To view the log entries, use the command: show log 	-	-	-	Y	Y	Y	Y	Y	Y	-
CR00016285	MACFF	-	It is now possible to use MAC-forced forwarding on non-private VLANs. Because MAC-forced forwarding is primarily a security feature, the switch displays a warning message if you do so. This enhancement allows you to use MAC-forced forwarding to limit broadcast traffic in a network where private VLANs are not appropriate.	-	-	-	Y	Y	Y	Y	Y	Y	-
CR00016361	Switch	-	AT-8948, AT-9900 and x900-48 series switches now support AT-SPTX tri-speed Cu SFPs.	-	-	-	-	-	-	-	Y	Y	-
CR00016437	MSTP	-	In the command set mstp configname= <i>name</i> , the switch now accepts the character "." in the <i>name</i> .	-	-	-	Y	Y	Y	Y	Y	Y	-

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00016459	Core	-	 This enhancement disables CPU fan monitoring on AT-8948 switches. Monitoring the fan is unnecessary unless an accelerator card is installed on the switch, so disabling monitoring reduces the number of messages that the switch displays and logs. To enable monitoring, use the command: enable cpufanmonitoring To disable it again, use the command: disable cpufanmonitoring When monitoring is enabled, the command show system displays the CPU fan status in the entry labelled "Main fan". 	-	-	-	-	-	-	_	Υ	_	_
CR00016523	SNMP	-	This enhancement enables you to specify whether SNMP adds 0x00 padding when the most significant 9 bits of an object's value are all 1, or whether the encoding follows the ASN.01 BER rule, which cuts off the most significant byte of 0xff. This setting has an impact on all integer type MIB objects, including 32 bit and 64 bit counter objects. To add the padding, use the command: set snmp asnberpadding={on yes true} For examples, see "SNMP ASN.01 BER Padding (CR00016523)" on page 253.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00016758	IP NAT	-	 This enhancement enables you to turn off TCP state and sequence checking in IP NAT. It also allows all ICMP packets go through IP NAT. To do this, use the command: enable ip nat bypasstcp When bypasstcp is enabled, IP NAT performs IP address and port translation for TCP packets and forwards the packets, regardless of the TCP sequence number and the current TCP state. It also allows ICMP echo reply and other ICMP packets to initiate a session and get forwarded. To disable the bypasstcp Bypassing is disabled by default because it degrades the security of IP NAT. However, it is useful when you need NAT on VRRP routers. Note that this enhancement does not apply to firewall NAT. 	Y	Y	Y	-	-	-	-	-	-	-
CR00016776	IP Gateway	-	 This enhancement allows ARPs to move between ports on the router's VLAN interfaces. This assists with wireless station roaming. To enable this feature, use the command: enable ip arp silentroam To disable it, use the command: disable ip arp silentroam 	Y	-	Y	-	-	-	-	-	-	-
CR00016785	Core	-	The default summertime dates have been updated to reflect the changes for North America made by the American Energy Policy Act of 2005. By default, summertime now starts on the second Sunday in March and ends on the first Sunday in November.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00016977	Script	-	This enhancement enables you to use aliases in commands in script files. The router or switch expands the aliases when it runs the script (except when it runs the script at start-up).	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

Features in 291-04

Software Maintenance Version 291-04 includes the resolved issues and enhancements in the following tables. In the tables, for each product series:

- "Y" indicates that the resolution is available in Version 291-04 for that product series.
- "-" indicates that the issue did not apply to that product series.

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00013787	ISAKMP, Logging	1	It was possible for invalid log messages to overwrite the log message buffer and cause the router or switch to reboot. Such invalid log messages could occur with VPN tunnels, for example. This issue has been resolved.	Y	Y	Υ	Y	Y	Y	Y	Y	Y	Y
CR00013813	TTY, User	1	When a user telnets into the router or switch, to login via RADIUS authentication, the telnet connection establishes and then user login authentication starts. Previously, if the remote user closed the telnet connection before RADIUS responded to the authentication request, then the router or switch rebooted when it received the RADIUS Reply message. This issue has been resolved. The router or switch now does not reboot if the telnet connection is closed before the RADIUS Reply message arrives.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00013963	Switch	1	Under heavy broadcast traffic, it was possible for the switch forwarding database (FDB) to lock up. This issue has been resolved.	_	_	-	_	_	_	_	Y	Y	_

CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	AT-9900	AT-9800
CR00014145	Core DHCP Snooping	1	DHCP Snooping determines when a client lease will expire by taking the current time and adding the client's assigned lease period to it. Previously, DHCP Snooping did not update this expiry time if the switch's clock time changed, which can happen because of NTP, summertime, or a user manually re-setting the time. Therefore, if the switch's clock time changed, DHCP clients could expire and lose connectivity. This issue has been resolved. If the switch's clock changes, DHCP Snooping now updates its client expiry times.			_	Υ	Y	Y	Y	Y	Y	
CR00016314	Core	1	AR442S routers did not run the user-specified configuration script at start up. Also, they incorrectly displayed the message "INFO: Initialising Flash File System" twice during start up. These issues have been resolved.	Y	-	_	_	_	_	_	_	_	_

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	AT-9900	AT-9800
CR00010511	BGP	2	Turning defaultoriginate on or off for a BGP peer (by using the command a dd bgp peer) did not cause BGP to generate an update, even if automatic updating was enabled (enable bgp autosoftupdate). This issue has been resolved.	Y	Y	Y	Y	Y	_	_	Y	Y	Y
CR00012564	L2TP	2	Setting a timeout on L2TP packet debugging caused the router or switch to reboot. This issue has been resolved.	Y	Y	Y	Y	Y	_	_	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00013592	НТТР	2	A badly formed response from a particular HTTP server caused the router or switch to reboot when it attempted to load a non-existent file from that server. This issue has been resolved.	Y	Y	Y	Y	Y	Υ	Y	Y	Y	Y
CR00013700	IP Gateway	2	When an IP packet was queued by the ENCO module or other applications, and the IP flow for the packet became invalid while the packet was queued, the router or switch sometimes rebooted. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00013791	IGMP, VLAN	2	Disabling IGMP snooping correctly increased the number of L3 filter matches available. However, if the configuration was saved and then run after a reboot, the switch incorrectly limited the number of L3 filter matches to the number available when IGMP snooping was enabled. If the maximum number of matches had been configured, this meant that some matches were missing after a reboot. This issue has been resolved.	_	_	_	Y	Y	Y	Y	_	_	_
CR00013823	Switch	2	In very rare circumstances, a port could stop transmitting traffic if its speed was modified or it was reset while under heavy traffic load. This issue has been resolved.	_	_	_	_	_	_	_	_	_	Y
CR00013929	ADSL ATM Ethernet	2	 When performing RFC1483 encapsulation of Ethernet frames, the AR44xS routers did not pad frames out to the 64-byte minimum frame size (the RFC does not require such padding to be performed). This resulted in an interoperability issue with ATM switches that discarded (rather than padded) the undersize frames upon decapsulating them. The effect of this was that when an AR44xS router was connected to an ATM network that contained such switches, the router could fail to connect at the PPP session level. This issue has been resolved. The router now always pads undersize Ethernet frames to the 64-byte minimum frame size before it performs RFC1483 encapsulation. This avoids the possibility of this interoperability issue. 	Y	_	_	_	_	_	_	_	_	-

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00014228	Switch	2	When the router generated packets (such as ARP requests) and sent them out multiple LAN ports, it always sent them as untagged packets. This issue has been resolved, so that LAN traffic will be tagged or untagged as specified in the VLAN port configuration.	_	_	Y	_	_	_	_	_	_	_
CR00014269	Switch	2	 If a user explicitly set the learn limit to zero by entering the command: set switch port=number learn=0 intrusion=discard and the learn limit had either not been explicitly set previously or had been explicitly set to a non-zero value, then the switch would not learn any MAC addresses. It treated 0 as meaning "learn 0 addresses" instead of meaning "no limit". This issue has been resolved. A learn limit of 0 means "no limit" in all circumstances. 	_	_	_	_	_	_	_	Y	Y	_
CR00014298	Switch	2	Packet loss sometimes occurred when an IGMP snooping group timed out. This issue has been resolved.	-	-	-	_	Ι	I	-	Y	Y	_
CR00014323	Switch EPSR	2	When EPSR was used in a network with a 10Mbps multicast or broadcast flow, the EPSR ring frequently alternated between a state of failed and complete. This issue has been resolved.	-	_	_	_	Ι	I	_	Y	Y	-
CR00014340	Bridge, Switch, VLAN	2	Bridging STP did not work if a VLAN was added as a bridge port. This issue has been resolved.	Y	-	Y	_	_	_	_	_	_	-
CR00014437	Core Install Stacking	2	If a switch's configuration was saved (by using the command create config= <i>filename</i>), and then the command set config= <i>filename</i> was entered, the configuration file should have been propagated through the stack to other switches that did not have a file of that name. This did not happen. This issue has been resolved.	-	_	_	Y	Y	Y	Y	Y	Y	_
CR00014673	Load	2	Attempts to upload a file to a TFTP server failed if a invalid IP address was specified in previous attempts. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00014714	PIM	2	If a PIM interface was set as the BSR candidate interface (by using the command add pim bsrcandidate interface= <i>interface</i>) and that interface went down, PIM would select another interface as the BSR candidate interface. The router or switch also set the new interface as the BSR candidate interface in the dynamic configuration. This issue has been resolved. PIM only looks for a new interface to use as the BSR candidate address if the user has not specified an interface.	Y	Y	Y	Y	Y	_	_	Y	Υ	Y
CR00014748	Reverse Telnet	2	Reverse Telnet used to filter out Ctrl-D characters, making it impossible to perform certain actions on the remote device. This issue has been resolved.	Y	Y	Y	Y	_	_	_	_	-	_
CR00014795	RIP∨6	2	When a user disabled RIPv6 or deleted a RIPv6 interface, the router or switch correctly set the metric of any affected RIPv6 routes to 16, indicating that the route was unavailable. However, the router or switch continued to try to use such routes to route packets if no alternative better routes existed. This issue has been resolved. When a route's metric is 16, it is no longer used to route traffic.	Y	Y	Y	Y	Y	_	_	Y	Y	Y
CR00014834	Switch	2	When STP detected a topology change and therefore the switch flushed its ARP table entries, sometimes the switch did not remove entries for non-lead trunk ports. Therefore, ARP entries for these ports contained incorrect routing information. These incorrect entries were not replaced until after they timed out. This issue has been resolved.	_			Y	Y	Y	Y	Y	Y	Y
CR00014925	IP Gateway	2	When the switch had a static route to a destination, and a user added a more specific static route to the same destination, then the switch should have removed the less specific route from its hardware switching table, but did not. This stopped the switch from routing packets to that destination. This issue has been resolved.	_	_	_	Y	Y	Y	Y	_	-	

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00014987	Core Switch	2	If a terminal emulator started up after the router started up, the router did not display a login or command prompt. This issue occurred with some terminal emulators (including Tera Term Pro) when connecting to the AR415S router. This issue has been resolved.	Y	_	_	_	_	_	_	_	_	
CR00015032	РКІ	2	When adding a certificate to PKI, if the length of the public key in the certificate was longer then 2048 bits (256 bytes) the router or switch could reboot. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00015071	IP Gateway	2	Routing over a PPP interface could fail if the switch had a default route out an Ethernet port. The default route switched all packets, even those destined for the PPP interface. This issue has been resolved. The resolution involves adding routes over the PPP interface to the switch hardware tables with an instruction to trap these packets to the CPU. Therefore these routes now appear in the hardware tables, and can be displayed by using the command show switch table=ip .	_	_	_	_	_	_	_	Υ	Y	Y
CR00015087	Classifier, DHCP snooping, Switch, MACFF	2	When MAC-forced forwarding (MACFF) was running, the switch did not filter multicast packets correctly. This issue has been resolved.	-	_	_	Y	Y	Y	Y	-	_	
CR00015156	Switch	2	On AR750S, AR750S-DP, and AR400 Series routers, if a user set a switch port to autonegotiate speed and duplex mode (by using the command set switch port=number speed=auto), the link went down. This issue has been resolved.	Y	_	Y	_	_	_	_	_	_	
CR00015207	Firewall	2	If a VoIP call came in through the SIP ALG from the public side of the firewall and was then transferred by the device on the private side, the firewall session was not always updated. When this happened, the person to whom the call was transferred could not hear the person who had called. This issue has been resolved.	Y	Y	Y	Y	Y	_	_	_	_	Y

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00015348	GUI	2	The GUI could not be used to access the dual power supply AR750S-DP router. This issue has been resolved. The GUI resource file to use is 750s_281-06_en_d.rsc.	_	-	Y	_	-	-	_	_	_	_
CR00015396	IP Gateway	2	If you defined an IP filter without specifying the optional type parameter, the default value of type=traffic was added to the filter in the dynamic configuration. This prevented you from using the configuration file with software version 2.7.6 and older releases. This issue has been resolved. The type parameter is only added to the dynamic configuration if you enter a value for it.	Y	Y	Υ	Υ	Y	Υ	Y	Y	Y	Y
CR00015474	Ethernet	2	If an AR020 PRI E1/T1 PIC was installed on an AR415S, the router's Ethernet interface stopped receiving unicast or multicast packets correctly—it only received broadcasts correctly. This issue has been resolved.	Y	-	-	-	-	-	_	_	-	_
CR00015638	Switch	2	On AR770S routers, when generating multicast or broadcast CPU traffic out a VLAN that had multiple active switch ports in it, the traffic would only egress port 1. This issue has been resolved.	_	_	Y	_	_	-	_	_	-	-
CR00015697	Switch	2	Mirroring the traffic on port 1 of any line card caused the switch to lose packets.	_	_	_	_	_	_	_	_	_	—
CR00015925	ADSL	2	The ADSL Annex B firmware has been updated on AR441S routers. This improved interoperability with some DSLAMs.	Y	_	_	_	_	_	_	-	-	_

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	AT-9900	AT-9800
CR00015936	Switch	2	It was not possible to set a tri-speed SFP to a fixed speed in the configuration script that the AT-9924SP switch runs when it starts up. This issue has been resolved, so the SFP can be set to a fixed speed from the configuration script Also, it was possible to use the command set swi port=number speed on an empty SFP bay. The command reported that the operation had been successful, but an inserted SFP was instead set to its previous or default setting. This issue has been resolved. It is no longer possible to set the speed of an empty SFP bay.	_	_	_	_	_	_	_	_	Y	
CR00015949	IPv6	2	Sometimes, when a router or switch received an IPv6 router advertisement message, it incorrectly created a duplicate of an already-existing interface route. If a user then deleted the IPv6 interface that these two routes belonged to, the router or switch could reboot. This issue has been resolved.	Y	Y	Y	Y	Y	_	_	Y	Y	Y
CR00015971 CR00015937 CR00015864	WAN Load Balancing	2	 The following issues occurred with WAN load balancing (WANLB): when a WANLB resource port became unavailable, existing sessions on the unavailable resource did not move to a backup resource if packets were sent over a WANLB session, then that session timed out, and then the same packets were sent again, a new session did not establish. This stopped the packets from being sent the second time. when WANLB was used with Firewall NAT, the orphan timeout setting of WANLB sessions was not updated correctly. This could mean that WANLB resources appeared to be available when they were not. 	Y	Y	Y	_	-	_	_	_	-	-
CR00016037	User	2	If the router or switch used RADIUS authentication and all the RADIUS servers were unavailable, then the device correctly checked its user database for a RADIUS backup user and authenticated that user. However, if that user then logged out, they were unable to log in again until after the RADIUS server Dead Time timer had expired. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	AT-9900	AT-9800
CR00007000	GUI, IGMP	3	The graphical user interface (GUI) listed an invalid local interface in the Interface drop-down list on the page for adding a static IGMP association. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y		Y	Y
CR00009274	Switch IP Gateway	3	If many VLANs simultaneously went from up to down, or down to up, the switch became unresponsive for a period of time. This issue has been improved by reducing the processing overhead for VLAN state changes.	_	_	_	_	_	_	_	Y	Y	
CR00009302	Switch	3	The number of filters that can be created on an AT-8848 switch is limited by the number of filter matches available. Previously, if a user attempted to create a filter, and an existing filter already used the same filter match as the new filter, the switch counted this as two matches being used. This reduced the number of available filters. This issue has been resolved.	_	_	_	-	Y	_	_		_	_
CR00009478	BGP	3	When a peer's inroutemap filter assigned an incoming route to a well-known BGP community, the router or switch did not use the community's restricted advertisement settings, such as NoExport or NoAdvertise. This issue has been resolved. Also, output of the command show bgp peer now shows whether a route has been assigned to a community. This is indicated by a flag "m", as shown in bold in the following route entry example: > 192.2.2.0/24 192.168.1.2 IGP - 100 m SEQ 1; The flag "m" indicates that this route has at least one community attached to it.	Y	Y	Y	Y	Y	_	_	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00010136	IP Gateway	3	If an IP interface was added and deleted many times, an excessive number of memory buffers became full. Also, when an IP interface was deleted, the IGMP query timer (set ip igmp int=interface querytimeout=value) sometimes continued running and later caused the router or switch to reboot. These issues have been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00012230	IP Gateway	3	When running the boot ROM release, it was possible to configure the router or switch as a DHCP client by using the command add ip interface= <i>int</i> ip=dhcp . However, the boot ROM release does not include the DHCP client feature, so the router or switch did not receive an IP address via DHCP. This issue has been resolved. It is no longer possible to configure the router or switch as a DHCP client when running the boot ROM release.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00012493	IP Gateway, IGMP Proxy	3	 Where IGMP proxy is enabled, only one upstream interface may be defined. Previously, when the command add ip interface=int ip=ipadd igmpproxy=upstream was used to try to create a second upstream interface, an error message was correctly displayed. However, the interface was still added, using igmpproxy=off. This issue has been resolved. The second interface is no longer added if this error occurs. Also, if an interface had been set as the upstream interface and was later changed to a downstream interface, a different upstream interface could not be specified, even though there was no active upstream interface. This issue has been resolved. 	Y	Y	Y	Y	Y	Y	Y	Y	Y	

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00012585	User	3	When authenticating users via RADIUS, the number of times that the router or switch attempts to contact the RADIUS server is determined by the Server Retransmit Count (displayed in output of the command show radius). Previously, this count incorrectly included the initial request. For example, a Retransmit Count of 3 meant that up to 3 attempts were made to contact the server. This issue has been resolved, so that the Retransmit Count no longer counts the initial request. For example, a Retransmit Count of 3 now means that up to 4 attempts are made to contact the server.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00012832	BGP	3	When the router or switch had thousands of static routes and BGP static import was periodically turned on and off, BGP used an excessive number of memory buffers. Excessive buffer use could also occur with BGP in other rare circumstances. This issue has been resolved.	Y	Y	Y	Y	Y	-	1	Y	Y	Y
CR00012858	DHCP	3	Previously, it was not possible to have multiple static DHCP entries with the same client ID (MAC address), even if the static entries were for different DHCP ranges. This issue has been resolved. You can now add static DHCP entries for a given MAC address to multiple ranges. Note that you cannot have multiple entries for a given MAC address on the same range.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00013150	File	3	If a boot configuration script included a command to delete a file followed by a command to create a file of the same name, a fatal exception occurred when the router or switch ran that script on reboot. This issue has been resolved so that the fatal exception no longer occurs. However, you should avoid putting such file operations into boot configuration scripts. To enhance multi-tasking, the file handler performs file operations in the background. This is not possible when executing a boot configuration script, so the file operations may be queued until after boot-up. In this case, this means that the file deletion will not be finished before the file creation command tries to execute.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	AT-9900	AT-9800
CR00013629	IGMP	3	When IGMP fast leave was enabled and the switch received a leave message via a trunk port, the switch only removed the port from the multicast group if the port was the master trunk port. This issue has been resolved. When fast leave is enabled, non-master trunk ports now leave multicast groups as soon as the switch receives a leave message.	_	_	_	Y	Y	Y	Y	Y	Y	
CR00013694	Switch, IP Gateway	3	For layer 3 Jumbo frames, this software version improves initial layer 3 flow setup and handling of flows that exceed the layer 3 MTU mid-flow.	-	_	_	_	_	_	_	_	Y	
CR00014038	IGMP IP Gateway	3	The IGMP Default Timeout Interval is automatically calculated by IGMP in accordance with RFC 2236, but the following command allows you to over-ride the calculated value: set ip igmp timeout= <i>value</i> Previously, the router or switch sometimes set the interval to the calculated value instead of using the value entered in the command above. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00014047	DHCP Snooping	3	Previously, DHCP snooping correctly refused to allocate new DHCP leases once the maxleases value had been exceeded, but it did so by discarding the server's acknowledgement message instead of forwarding it to the client. Therefore, the DHCP server recorded the address as allocated, which meant the IP address range could be exhausted. This issue has been resolved. The server no longer records addresses as allocated once the maxleases value is exceeded.	_	_	_	Y	Y	Y	Y	Y	Y	_
CR00014152	Switch	3	On AR415S, AR44xS, AR750S and AR770S routers, when a switch port went down or was reset by using the command reset switch port= <i>number</i> , this deleted the dynamically-learned forwarding entries for all ports. This issue has been resolved. Now entries are only deleted for the port that went down or was specified in the command.	Y	_	Y	_	_	_	_	_	_	

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00014163	Firewall	3	When the firewall was performing NAT on UDP video streams and two streams started up at the same time, sometimes one or both streams displayed excessive jitter. This issue has been resolved.	Y	Y	Y	Y	Y	_	_	_	_	_
CR00014178	Core	3	 The following issues occurred with environmental monitoring: on AR750S and AR770S routers, the values reported by the show system command were incorrect for the first few seconds after a cold restart on AR770S routers, the router did not indicate power supply problems through log messages or the system LED These issues have been resolved. 	_	_	Y	_	_	_	_	_	_	_
CR00014285	BGP	3	The default setting for BGP capability matching is now loose instead of strict . This matches the requirements of RFC 4271.	Y	Y	Y	Y	Y	-	-	Y	Y	Y
CR00014305	Switch	3	On AT-8748XL and Rapier 48i switches, mirroring did not work when: only one (not both) of the uplinks had an expansion module installed and that uplink (port 49 or 50) was the mirror port This issue has been resolved.	-	_	_	Y	_	_	Y	_	_	_
CR00014313	GUI, Log	3	If the user cleared the Queue Output checkbox on the Modify Log Output Definition page of the GUI, it displayed an error instead of making the change. This issue has been resolved. The GUI can now be used to turn off queuing of logging output.	Y	Y	Y	Y	Y	Y	Y	_	Y	Y
CR00014327	MSTP, GUI	3	When using the GUI to configure the MSTP CIST, users had to specify the external and internal port path costs. If these were not specified, the GUI gave an error instead of configuring the CIST. This issue has been resolved. By default, the GUI now specifies "default" for the path costs. This value of "default" leaves the current setting unchanged.	-	-	_	Y	Y	Y	Y	Y	Y	

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00014328	IP Gateway, Switch	3	If a port had static ARP entries defined for a VLAN, then adding the port to another VLAN made those static ARP entries inactive. Also, deleting a port from a VLAN would delete all static ARP entries that were defined on that port, including entries for other VLANs. Note that this deletion issue did not occur on Rapier i, AT-8800, AT-8700XL, or AT-8600 Series switches. Both of these issues have been resolved.	Y	_	Y	Y	Y	Y	Y	Y	Y	Y
CR00014652	PIM6	3	If a user changes the PIMv6 BSR candidate priority to the same value as the currently-elected BSR's priority, then the router or switch should be elected as the BSR if its IPv6 address is higher than the currently-elected BSR. This did not happen. This issue has been resolved.	Y	Y	Y	Y	Y	_	_	Υ	Υ	Y
CR00014659	DHCP	3	On the DHCP server, a user could create two static DHCP entries for the same client in one range. This was only possible if the client had first obtained a dynamic address from the server. This issue has been resolved. It is now impossible to add the same static client twice, even when that client has a pre-existing dynamic entry.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00014724	IGMP Snooping	3	When the router or switch received an IGMP Leave message, it did not update IGMP Snooping counters correctly in some circumstances. This issue has been resolved.	Y	_	Y	Y	Y	Y	Y	Y	Y	Y
CR00014746	WANLB, IP Gateway	3	It was possible to delete an IP interface that was configured as a WAN load balancer resource. This issue has been resolved.	Y	Y	_	_	_	_	-	_	_	_

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00014755	BOOTP IP Gateway	3	It was possible to add a BOOTP relay destination using an interface that was not running IP. It was also possible to delete an IP interface even though BOOTP relay destinations were defined for the interface. Both of these situations could allow the router or switch to be mis-configured. This issue has been resolved by adding checks for these situations to the command handlers. It is no longer possible to add a BOOTP relay destination using an interface not in use by IP, and no longer possible to delete an IP interface if BOOTP relay has destinations defined using that interface.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00014782	PIMv6	3	The command show pim6 staterefresh sometimes corrupted the terminal display output with random characters. To recover, it was necessary to reset the terminal session. This issue has been resolved.	Y	Y	Y	Y	Y	_	_	Y	Y	Y
CR00014872	GUI	3	The router or switch rebooted if the Opera browser was used to browse to its GUI. This issue has been resolved. However, note that the GUI does not fully support Opera. Some functionality may not be available.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00015107	GUI	3	HTTP pipelining did not operate correctly on some web browsers when browsing to the GUI. This made some images very slow to load. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	_	Y	Y
CR00015126	IP Gateway	3	For IP filters of type=routing , the first filter entry could not be set to match on the following IP address/mask pair: source=0.0.0.0 smask=255.255.255.255 This IP address/mask pair corresponds to the default route. This issue has been resolved. You can now match on the default route in the first entry of a filter.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	AT-9900	AT-9800
------------	-----------------------	-------	---	-------	-------	--------	----------	---------	---------	-----------	---------	---------	---------
CR00015148	IP Gateway DHCP	3	When a router or switch was configured to use DHCP to assign an address on an interface, and then set to have a static address on that interface, the DHCP client in the router or switch would continue to negotiate with the DHCP server. This tied up a DHCP lease. This issue has been resolved. Assigning a static address to an interface will stop the DHCP client from requesting an address from a DHCP server.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00015155	Load	3	File upload via the IPv6 version of TFTP was not operating correctly. This issue has been resolved.	Y	Y	Y	Y	Y	_	_	Y	Y	Y
CR00015159	IP Gateway	3	If the router or switch received an IP subnet broadcast packet that was directed to a unicast MAC address, it incorrectly responded with an ICMP unreachable message, unless an appropriate IP helper configuration existed. This issue has been resolved. When there is no IP helper configuration, the behaviour now depends correctly on the setting of the directedbroadcast parameter for the IP interface. If directedbroadcast=on , the packet is sent out as a MAC broadcast. If directedbroadcast=off , the packet is dropped. ICMP unreachable messages are not sent in any case.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00015258	IGMP snooping VLAN	3	The command add igmpsnooping vlan=vlan routerport=port adds a static IGMP router port, for a specific VLAN and port pair. Previously, it was possible to remove the port from that VLAN without updating the static router port association. This issue has been resolved. When you remove a static router port from a VLAN, the router or switch now removes that port from the static router port list and updates all layer 2 entries.	Y	_	Y	Y	Y	Y	Y	Y	Y	Y
CR00015346	Switch	3	The 64-bit counter type objects in the ifXTable of the Interfaces Group MIB (RFC 2863) returned non-zero values for ports that had never been up. This issue has been resolved.	Y	_	Y	_	_	_	_	_	_	_

CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	AT-9900	AT-9800
CR00015666	IP Gateway	3	Subnet broadcast packets would not be routed correctly when the interface to which the subnet broadcast was destinated was an interface on the device, but its link status was down. Even though an alternate route to the destination existed, the device would send the packets incorrectly. This issue has been resolved. When a subnet broadcast is received, it will be correctly forwarded to an alternate route even if the destination interface is down.	Y	Y	Y	Y	Υ	Y	Y	Υ	Y	Y
CR00015798 CR00016058	Switch	3	If the switch received a packet on a port and therefore started using MAC-based authentication to authenticate the port, and then received another packet during the authentication process, then occasionally the switch dropped the second packet. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	_
CR00015915	Ethernet	3	The AR415S router processed some IP multicast packets incorrectly on its eth0 interface. This issue has been resolved.	Y	_	_	_	-	_	_	-	_	_

Level 4

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00004677	Core	4	When the router or switch rebooted, its internal clock lost approximately 1 second. This issue has been resolved. The time loss on reboot has been reduced.	Y	Y	Y	Y	Y	_	Y	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00009087	Core, Utility	4	The following issues occurred with the commands show debug active and disable debug active :	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
			The command did not adequately warn users if an invalid module number had been entered into the active parameter.										
			This issue has been resolved. The router or switch now displays an error unless the value is between 1 and 142.										
			The CLI "?" help description for the active parameter listed an incorrect number range and also listed modules that cannot be manipulated through this command.										
			This issue has been resolved. The "?" help description is now correct.										
CR00011695	QoS	4	The "?" help description for switch commands that accept a value in bytes (or similar units such as kbytes or bytes/s) incorrectly indicated that the units were bps. The commands this issue applied to depend on the switch model, but include commands such as: create qos trafficclass=value maxburst=? create qos policy=value dtcmaxburst=? set qos red=value start1=? set swi port=value bcl=?	_	_	_	Y	Y	Y	Y	Y	Y	Y
			This issue has been resolved. The "?" help description now displays the correct units.										
CR00012602	MSTP	4	If the command set mstp cist port=value was entered with no other parameters, the resulting error message ("One or more parameters may be missing") was displayed as an INFO message. This issue has been resolved. The message now displays as an ERROR message.	_	_	_	Y	Y	Y	Y	Y	Y	_
CR00013045	SNMP, Core, TTY	4	The MIB object hrSystemNumUsers displayed the number of login users since the router or switch started up, instead of the number of currently-active login users. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00013112	IP Gateway	4	The blackhole parameter of the commands add and set ip route had no "?" help description. This issue has been resolved.	_	_	_	_	_	-	-	Y	Y	_
CR00013188	LACP	4	Previously, when an attempt to add a port to LACP was unsuccessful, the switch displayed an appropriate warning message followed incorrectly by an "operation successful" message. This issue has been resolved. The switch no longer displays "operation successful" when port addition fails.				Y	Y	Y	Y	Y	Y	_
CR00013221	IP Gateway	4	The output of the command show ip route did not contain any spaces between the route tag value and the metric value when the tag value was long. This issue has been resolved by adding the missing spaces. The content and relative position of the values have not changed.	Y	Y	Y	Y	Y	Y	Υ	Y	Y	Y
CR00013260	TACPLUS	4	If a user added a TACACS+ server when TACACS+ was not enabled, previously the router or switch displayed a single "info" message that indicated that the module was not enabled, but did not display a message confirming the server addition. However, the router or switch did add the server. This issue has been resolved. TACACS+ is now consistent with other modules— the router or switch displays the following "warning" and "info" messages: Warning (2111049): The TACP module is not enabled. Info (1111003): Operation successful.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00013463	Ping	4	Previously, if you used the ? or Tab keys to obtain help about the timeout parameter for the ping command, the resulting help said that the maximum timeout was 65535. However, the correct maximum is 60 seconds. This issue has been resolved. The "?" help now displays the correct range of values.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00013589	Install	4	 When a router or switch was using a trial licence for release software and the trial period elapsed, the router or switch rebooted without indicating the reason for the reboot. This issue has been resolved. The following error messages now explain why the router or switch is rebooting: ERROR: There are no valid licences available for the current software release. The device will now reboot. 	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
			ERROR: The trial licence for the current software release has expired. The device will now reboot.										
CR00013640	NTP	4	Output of the command show ntp displays a "Host Address" field. This is the address of the interface from which the router or switch sends NTP packets. Previously, if the IP address changed, the "Host Address" field did not change, even though NTP used the new address. This issue has been resolved.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00014106	Core	4	If the router or switch runs a configuration file on start-up that contains the command set summertime before the command enable summertime , a log message on start-up says that summertime needs to be enabled. However, summertime is correctly applied to the router or switch. Previously, if you configured summertime then saved the configuration by using the command create config , set summertime came before enable summertime in the resulting configuration file. This issue has been resolved. When you save the configuration, enable summertime now comes before set summertime in the resulting configuration file, so the log message is not produced.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00014151	VLAN	4	The following error message: "Error (3089399): Operation not allowed on a .NESTED port." contained an extraneous "." before the word "NESTED". This issue has been resolved. The "." has been removed.	_	_	_	_	_	_	_	Y	Y	_

CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00014170	Core	4	The show exception command did not display the correct exception type for watchdog exceptions on AR750S, AR750S-DP, or AR770S routers. This issue has been resolved. The correct exception type is now displayed.	_	_	Y	_	_	_	_	_	_	_
CR00014250	LLDP	4	In output of the command show lldp localdata , the field lldpLocSysDesc gives information about the router or switch model and software version. Previously, this information was sometimes split incorrectly across 3 rows. This issue has been resolved. The information now displays correctly.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00014318	DDNS	4	If a user made a configuration change to DDNS (dynamic DNS) when DDNS was not enabled, previously the router displayed a message that indicated that the module was not enabled, but did not display a message confirming the change. However, the router did make the change. This issue has been resolved. DDNS is now consistent with other modules—the router displays the following "warning" and "info" messages: Warning (2142049): The DDNS module is not enabled. Info (1142003): Operation successful.	Y	_	Y	_	_	_	_	_	_	
CR00014367	GUI	4	The GUI included pages for configuring MAC-based port authentication. However, this feature is not available on AT-9800 Series switches. This issue has been resolved. The GUI pages have been removed.	-	-	_	_	_	_	-	_	_	Y
CR00014712	Firewall	4	If the router or switch renumbered a firewall rule, it displays a message. Previously, this message had a status of "info" instead of "warning". This issue has been resolved.	Y	Y	Y	Y	Y	_	_	_	_	Y
CR00014750	DHCP	4	Previously, when a user entered the command delete dhcp range= <i>range</i> ip= <i>ipadd</i> , the router or switch would display an "Operation successful" message, even when the client entry in question was unused. This issue has been resolved. For unused clients, this command now results in the following new message: "Nothing to delete, client is unused."	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00014778	VLAN, Bridging	4	It was possible to specify a value of 0 for the ageingtimer parameter in the command add and set vlan=v/an bridge , even though this value was meaningless. This issue has been resolved. The lowest valid value for ageingtimer is 1.	Y	_	Y	Y	-	-	_	-	-	_
CR00015080	АТМ	4	When an SHDSL or ADSL interface re-trained after having been in a "link up" state, spurious error messages could appear on the console. This issue has been resolved. The messages were not genuine error messages and no longer appear.	Y	_	_	_	_	_	_	_	_	_
CR00015130	Switch	4	The following commands have been deprecated in software versions 2.9.1 and later, and therefore (correctly) have no effect on the switch: set switch port= <i>number</i> thrashlimit= <i>value</i> set switch port= <i>number</i> thrashrefill= <i>value</i> Previously, if a user entered these commands, the switch incorrectly displayed an "Operation successful" message. This issue has been resolved. The switch now displays a warning message indicating that the commands are deprecated. For information about the commands that replace these commands, see the "Limiting Rapid MAC Movement" section of the Switching chapter of the Software Reference.	_	_	_	_	_	_	_	Y	Y	_

Enhancements

CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CB00002026	Coro		It is now possible to botswap NSMs on NEPS compliant Papier i switches								^		
	Cole	-	To hotswap the NSM, press the Hot Swap button beside the NSM, check that the Swap LED turns on and the In Use LED turns off, then remove the NSM. Place the new NSM in the bay, then press the Hot Swap button again to make the NSM available for use.				Ι						
CR00012881	IP Gateway	-	The IP implementation has been enhanced to accept IP interfaces with a /31 netmask. This results in a slightly non-standard subnet that has no network address or broadcast address. This has become a popular extension to IP, because it reduces wastage of IP addresses on point-to-point links.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00013129	Many	-	This enhancement extended the "?" help for VRRP, OSPF, SNMP, IP routes, user database, VLANs, logging, and file management. The "?" help for these (and several other) modules now gives information about all command parameters.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CR00013449	Firewall	-	The firewall now supports FTP sessions that use the security extensions defined in RFC 2228. Previously, the firewall dropped sessions that used those security extensions. This enhancement makes more-secure FTP available between private-side clients and public-side servers, and between public-side clients and private-side servers.	Y	Y	Y	Y	Y	_	_	_		Y
CR00013610	Telnet TTY	-	This enhancement enables you to select whether the system name appears at the login prompt for telnet client sessions. By default, the system name appears. To prevent it from appearing, use the command: SET TELnet LOGINSYStemname=OFF Note that the login prompt appears before you log into the router or switch.	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	AT-9900	AT-9800
CR00013992	Core	-	 AR770S routers have a CPU fan that the software now monitors in the same manner as the main fan. The state of the CPU fan is displayed along with that of the main (chassis) fan in the output of the show system command. If a problem develops with the CPU fan, the router notifies you in the following ways: The system LED flashes in a single flash pattern An SNMP trap is issued on the fanAndPSMainFanStatus atRouter private MIB object A log message is generated that says "CPU fan status is not good". 	_	_	Y	_	_	_	_	_	_	_
CR00014067	File	-	The commands create file , add file , reset file permanentredirect , and show file permanentredirect were not supported on AR725 and AR745 routers. These commands enable you to save the output of other router commands in text files on the router. For more information about these commands, see the "Managing the File System" chapter of the Software Reference.	_	Y	_	_	_	-	_	_	_	_

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00014172	BOOTP	-	This enhancement enables you to associate a BOOTP relay destination with a given interface. To do this, use the new optional interface parameter in the command: ADD BOOTP RELAy= <i>ipadd</i> INTerface= <i>interface</i>	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
			BOOTP packets received on this interface are relayed to the specified relay destination only. You can define the same interface for multiple relay destinations; the router or switch relays any BOOTP packets received to each relay destination.										
			If you do not specify an interface, the destination becomes a "generic" destination. If the router or switch receives a BOOTP message on an interface for which no specific destination is defined, the router or switch relays the message to all generic destinations. This is the same as the behaviour prior to this enhancement.										
			To remove a destination that is associated with an interface, use the command: DELete BOOTD RELAY=ipadd INTerface=interface										
			To see the interfaces that each destination is associated with, use the pre-existing command: SHow BOOTp RELAy										
CR00014238	DHCP Snooping	-	DHCP snooping records its client database into a file in NVS (if possible) or Flash memory. In previous versions, that file was named bindings.dsn. From this version, the file structure has changed and the file is now named bind0002.dsn.	-	-	-	Y	Y	Y	Y	Y	Y	_
			When you upgrade a switch to this version, the switch creates the new client database file 10 seconds after initialising the new version. After that, you can safely delete the old bindings.dns file, if desired.										
			Note that the functionality of DHCP snooping has not changed, only the filename.										

CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00014241	BGP IP Gateway	-	 This enhancement enables you to force BGP to select the best route on the basis of network prefix alone, instead of on the basis of preference, then metric, then network prefix. To do this: Give the desired dynamic routing protocol a preference of 0, which is the preference of interface routes, by using the command: SET IP ROUte PREFerence=0 PROTocol={BGP-ext BGP-int OSPF-EXT1 OSPF-EXT2 OSPF-INTEr OSPF-INTRa OSPF-Other RIP ALL} Create a route map to give matching routes the same metric as your interface routes. To change the metric, use the command: ADD IP ROUTEMap=routemap ENTry=14294967295 SET METric=1 Add the route map as a filter to the BGP peers by using the command: ADD BGP PEer=ipadd REMoteas=165534 INRoutemap=routemap [other optional parameters] The above process gives matching routes the same preference and metric as interface routes. This forces IP routing to compare the network prefixes of the interface route and the other routes. IP routing then chooses the most specific route as the best route of that destination, instead of automatically choosing the interface route as the best route without considering any other routes which may have more specific network prefixes. 	Y	Y	Y	Y	Y		_	Y	Y	Y

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00014300	DHCP Snooping, MACFF	-	 The following enhancements have been made to DHCP snooping, to support MAC-forced forwarding: MAC-forced forwarding checks the DHCP snooping database to find out which router has been assigned to each DHCP client. DHCP snooping determines this from the router list in DHCP acknowledgement messages. However, some clients do not request a router. DHCP snooping now modifies request messages from such clients, to ensure that they request a router. This enables MAC-forced forwarding to interoperate with such clients. Output from the command show dhcpsnooping database now displays the list of routers that are assigned to each client, as shown in bold in the following example: Current valid entries MAC Address IP Address Expires(s) VLAN Port ID Source Router list 00-00-cd-28-06-7b 192.168.99.1 52 1 13 2 Dynamic 192.168.199.254 			_	Y	Υ	Y	Υ	Y	Y	
CR00014354	Ethernet Switch	-	This enhancement enables you to use 100 Mbps fiber SFPs with AR770S routers. Support has been added for AT-SFPX/15 and AT-SFPX/40 SFPs.	_	_	Y	_	-	_	_	-	_	_

CR	Module	Level	Description	R400	R7x5	R7×0S	apier i	T-8800	T-8600	T-8700XL	900-48	T-9900	T-9800
	Wodule	Level		٩	◄	◄	~	<	∢	٩	×	A	<
CR00014715	DNS	-	A new log message has been added to provide more information about rejected DNS requests. The message has a log type of 052 / IPDNS and subtype 002 / UNRES, and reads: DNS request for <domain-name> rejected by server. Code <number></number></domain-name>	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
			<pre>explanation>.</pre>										
			The following codes and explanations exist:										
			0: No Error—no error occurred										
			1: Format Error—there was a problem with the message construction										
			2: Server Failure—there was a problem with the server itself										
			3: Name Error—the name does not exist in the domain										
			4: Query Not Implemented—the received query was not supported										
			5: Refused—Refused for policy, rather than technical, reasons										
			6: YX Domain—the name exists when it should not										
			7: YX RR Set— a resource record exists that should not exist										
			8: NX RR Set— a resource record that should exist does not exist										
			9: Not Authoritative—the receiving server is not authoritative										
			10: Not Within Zone—the specified name is not within the zone specified in the message										
CR00014728	DDNS	-	When you activate a Dynamic DNS (DDNS) update (by entering the command activate ddns update), the router now warns you of possible negative consequences and prompts you for whether or not to continue.	Y	-	Y	-	_	-	_	_	_	-
			Also, if you attempt to activate a DDNS update when DDNS is disabled, the router displays a warning message that indicates that DDNS is disabled.										

CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	АТ-9800
CR00014845	IP Gateway OSPF		 When OSPF is running over an on-demand PPP link and the link goes down, IP notifies OSPF that the link is down and OSPF stops sending Hello packets over the link. In a network in which routes over the PPP link are all dynamically learnt through OSPF, the PPP link will not come back up because without OSPF there are no routes to direct traffic at that link. This enhancement enables you to stop IP from notifying OSPF that the PPP link is down. OSPF keeps sending Hello messages, which bring the link back up again. To enable this feature, set the new optional notifyospfdown parameter to no in one of the commands: ADD IP INTerface=<i>int</i> NOTIfyospfdown={NO YES} [other parameters] SET IP INTerface=<i>int</i> NOTIfyospfdown={NO YES} [other parameters] The default value for this parameter is yes, which means that IP notifies OSPF when the interface goes down and OSPF sets the interface state to Down. OSPF does not send Hello messages to the interface, and OSPF is inactive on the interface until it receives an Up notification. This is the behaviour prior to this enhancement. Also note the following points: The parameter applies to the entire IP interface. The parameter only applies to on-demand PPP links. IP always sends notifications for other interfaces, even if this parameter is set to no. 	Y	Y	Y	Y	Y			Y	Y	Y
CR00015269	Switch, EPSR	-	EPSR uses a classifier-based hardware filter to select packets in the control VLAN. The hardware filter now only uses 2 of the available 16 bytes to match packets. This increases the number of other classifier-based features you can use when running EPSR.	-	_	_	_	-	-	_	Y	Y	-
CR00015628	Switch	-	The switch now fully recognises the latest revision of the AT-SPTX SPF, so all of the features of the SFP can be utilised.	_	-	_	_	_	_	-	-	Y	-

Features in 291-03

Software Maintenance Version 291-03 includes the resolved issues and enhancements in the following tables. In the tables, for each product series:

- "Y" in a white column indicates that the resolution is available in Version 291-03 for that product series.
- "-" in a white column indicates that the issue did not apply to that product series.
- a grey-shaded column indicates that Version 291-03 has not been released on that product series.

"-" in a grey column indicates that the issue did not apply to that product series.

"Y" in a grey column indicates that the issue applied to that product series. These issues are resolved in the next Version (291-04).

Level 1

No level 1 issues

Level 2

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00014960	Switch RIPng	2	Creating a large number of IPv6 RIPng interfaces (more than 250) sometimes caused the switch to reboot. This issue has been resolved.	_	_	-	l	_		-	Y	Y	
CR00015102	IPv6	2	If a large number of IPv6 multicast routes were added (more than1000) on a switch with an IPv6 accelerator card, the switch could reboot. This issue has been resolved.	_	_	-	_	_			Y	Y	_
CR00015585	АТМ	2	AR442S routers sometimes rebooted while using the Test Facility to test the SHDSL interface. This issue has been resolved.	Y	-	-	_	_	_	_	-	-	_

CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	A⊺-9900	AT-9800
CR00015678	IPv6	2	When a switch was heavily loaded with IPv6 traffic, it could reboot because a large quantity of traffic was queued while waiting for a neighbour's MAC address to resolve. This issue has been resolved by limiting the number of packets that can be	Y	Y	Y	Y	Y	_	_	Y	Y	Y

Level 3

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	AT-9900	AT-9800
CR00013270	QoS	3	By default, queue lengths were set to the maximum possible values for each port type. This could make low-priority queues inappropriately starve higher-priority queues of buffer resource.	_	_	_	_	_	_	_	Y	Y	-
			This issue has been resolved. The default queue length has been reduced to 128 frames for all port types. If required, you can change them by using the existing command:										
			SET QOS POrt={port-list ALL} EGRessqueue[=queue-list] [Length=163648] [other optional parameters]										
CR00014306	LLDP Switch	3	The switch included a permanent L3 filter to stop CDP (Cisco Discovery Protocol) packets from being forwarded. This made one less L3 filter match available to users.	_	_	-	Y	Y	Y	Y	-	-	-
			This issue has been resolved. CDP still requires an L3 filter, but the filter is automatically created when CDP is enabled and destroyed when CDP is disabled.										

CR	Module	Level	Description	AR400	AR7x5	AR7×0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	АТ-9900	AT-9800
CR00014959	QoS	3	Destroying a traffic class or flow group also destroyed all classifiers that were associated with that traffic class or flow group. This issue has been resolved. User-created classifiers are no longer destroyed. Automatically-created classifiers are still destroyed, such as classifiers for DHCP snooping.	_	_	_	Y	Y	Y	Y	Y	Y	_
CR00015510	Switch	3	When the switch performed layer 3 routing across a trunk, it did not balance traffic across all ports in the trunk group. This issue has been resolved.	_	_		Y	Y	Y	Y	_	_	

Level 4

No level 4 issues.

Enhancements

CR	Module	Level	Description	AR400	AR7x5	AR7x0S	Rapier i	AT-8800	AT-8600	AT-8700XL	x900-48	AT-9900	AT-9800
CR00014222	IGMP snooping, Switch, VLAN	-	IGMP snooping learns which ports have routers attached to them, so it can forward relevant IGMP messages out those ports. By default, snooping identifies router ports by looking for ports that receive specific multicast packets (such as IGMP queries, PIM messages, OSPF messages, and RIP messages).	Y	-	Y	Y	Y	Y	Y	Y	Y	Y
	VLAN		 In some network configurations, this learning process cannot identify all router ports. For such networks, this enhancement enables you to statically configure particular ports as multicast router ports. To specify the static router ports, use the new command: add igmpsnooping vlan={vlan-name 14094} routerport=port-list To stop ports from being static router ports, use the new command: delete igmpsnooping vlan={vlan-name 14094} routerport=port-list To list the static router ports, use the existing command: show igmpsnooping and check the new "Static Router Ports" field. 										

Features in 291-02

Version 291-02 was not released.

Features in 291-01

Version 291-01 was not released.

MAC-forced forwarding enhancements (CR00017819)

This enhancement improved MAC-forced forwarding in the following ways:

The commands add and set macff server both now allow you to optionally specify a MAC and/or IP address for the static entry. The complete syntax is now:

add macff server interface=vlan [description=description] [ipaddress=ipadd] [macaddress=macadd]

set macff server interface=vlan [description=description] [ipaddress=ipadd] [macaddress=macadd]

- The IP address is the main identifier in the static entry. It must be unique. You can specify the add command multiple times to specify multiple IP addresses for a single MAC address. It is also possible to have a single IP address resolve itself to duplicate MAC addresses, although not recommended.
- If you specify a MAC address without specifying an IP address, this associates the MAC address with an IP address of 0.0.0.0. You can only associate one MAC address with the IP address 0.0.0.0. The switch will make no attempt to resolve the MAC address.
- If you specify an IP address without specifying a MAC address, the switch attempts to resolve the address by ARPing. If there are multiple MAC addresses for the IP address, the switch uses the first ARP reply.
- If you specify both an IP address and a MAC address, the switch does not attempt to resolve the addresses. Even if it later dynamically learns a different IP address for that MAC address, the static entry takes precedence. However, if the switch learns of a discrepency, it now produces a log entry. You should investigate the discrepency—it is likely to be because of a configuration error.
- The command delete macff server now allows you to identify the server to delete by entering only its IP address. If the MAC address is not associated with an IP address, you can instead enter only the MAC address.
- Debugging is now on a global basis, not a per-interface basis. Therefore, the commands are now enable macff debug=options and disable macff debug=options. Also, information about debugging options has been removed from the output of show macff interface and instead put in the output of show macff [counters].

IGMP Group MIB (CR00018418)

AlliedWare now includes an IGMP Group MIB. This MIB is available in the file at-igmp.mib.

The IGMP Group has the object identifier prefix igmp ({ modules 139 }), and contains a collection of objects and traps for monitoring IGMP group membership.

The following objects are defined:

- igmpIntInfo ({ igmp 1 }) is a collection of objects for managing IGMP-capable interfaces:
 - igmpInterfaceTable ({ igmpIntInfo 1 }) is a table of IGMP-capable IP interfaces, indexed by interface.
 - igmpIntStatsTable ({ igmpIntInfo 2}) is a table of statistics for IGMP-capable IP interfaces.
- igmpIntMember ({ igmp 9 }) is a collection of objects for managing IGMP group membership:
 - igmpIntGroupTable ({ igmpIntMember 1 }) is a table of IP multicast group memberships.
- igmpSnooping ({ igmp 10 }) is a collection of objects for managing IGMP snooping:
 - igmpSnoopAdminInfo ({ igmpSnooping 1 })
 - igmpSnoopAdminEnabled ({ igmpSnoopAdminInfo(1) 1 }) is a boolean value indicating whether IGMP Snooping is globally enabled.
 - igmpSnoopVlanTable ({ igmpSnooping 2 }) is a table of layer 2 interfaces performing IGMP snooping.
 - igmpSnoopGroupTable ({ igmpSnooping 3 }) is a table of IGMP groups snooped on layer 2 interfaces.
 - igmpSnoopPortTable ({ igmpSnooping 4 }) is a table of ports in layer 2 interfaces that are currently members of multicast groups.
 - igmpSnoopHostTable ({ igmpSnooping 5 }) is a table of hosts receiving multicast data.

ICMP Router Discovery Advertisements (CR00010614)

Router discovery

The router or switch supports all *RFC 1256, ICMP Router Discovery Messages* as it applies to routers. If this feature is configured, the router or switch sends router advertisements periodically and in response to router solicitations. It does not support the Host Specification section of this RFC.

Benefits

Before an IP host can send an IP packet, it has to know the IP address of a neighbouring router that can forward it to its destination. ICMP Router Discovery messages let routers automatically advertise themselves to hosts. Other methods either require someone to manually keep these addresses up to date, or require DHCP to send the router address, or require the hosts to be able to eavesdrop on whatever routing protocol messages are being used on the LAN.

Router discovery process

When	Then
Router Discovery advertising starts on a router or switch interface because: - the router or switch starts up, or - advertisements are enabled on the switch or on an interface	the router or switch multicasts a router advertisement and continues to multicast them periodically until router advertising is disabled.
a host starts up	the host may send a router solicitation message.
the router or switch receives a router solicitation	the router or switch multicasts an early router advertisement on the multicast interface on which it received the router solicitation.
a host receives a router advertisement	the host stores the IP address and preference level for the advertisement lifetime.
the lifetime of all existing router advertisements on a host expires	the host sends a router solicitation.

The following table summarises what happens when Router Discovery advertisements are enabled for interfaces on the router or switch.

When (Continued)	Then (Continued)
a host does not receive a router advertisement after sending a small number of router solicitations	the host waits for the next unsolicited router advertisement
a host needs a default router address	the host uses the IP address of the router or L3 switch with the highest preference level.
Router Discovery advertising is deleted from the physical interface (delete ip advertise command), or the logical interface has advertise set to no (set ip interface command)	the router or switch multicasts a router advertisement with the IP address(es) that stopped advertising, and a lifetime of zero. It continues to periodically multicast router advertisements for other interfaces.
the router or switch receives a router advertisement from another router	the router or switch does nothing but silently discards the message.

Advertisement messages

A router advertisement is an ICMP (type 10) message that contains the following:

- in the destination address field of the IP header, the interface's configured advertisement address, either 224.0.0.1 (all) or 255.255.255 (limited).
- in the lifetime field, the interface's configured advertisement lifetime.
- in the Router Address and Preference Level fields, the addresses and preference levels of all the logical interfaces that are set to advertise.

The router or switch does not send router advertisements by default.

Solicitation messages

A router solicitation is an ICMP (type 10) message containing:

- source Address: an IP address belonging to the interface from which the message is sent
- destination Address: the configured Solicitation Address, and
- Time-to-Live: 1 if the Destination Address is an IP multicast address; at least 1 otherwise.

The router advertisement *interval* is the time between router advertisements. For the first few advertisements sent from an interface (up to 3), the router or switch sends the router advertisements at intervals of at most 16 seconds. After these initial transmissions, it sends router advertisements at random intervals between the minimum and maximum intervals that the user configures, to reduce the probability of synchronization with the advertisements from other routers on the same link. By default the minimum is 450 seconds (7.5 minutes), and the maximum is 600 seconds (10 minutes).

Preference level

The *preference level* is the preference of the advertised address as a default router address relative to other router addresses on the same subnet. By default, all routers and layer 3 switches have the same preference level, zero. While it is entered as a decimal from -2147483648 to 2147483647, it is encoded in router advertisements as a twos-complement hex integer from 0x8000000 to 0x7fffffff. A higher preference level is preferred over a lower value.

Lifetime

The *lifetime* of a router advertisement is how long the information in the advertisement is valid. By default, the lifetime of all advertisements is 1800 seconds (30 minutes).

Configuration procedure

Do the following to configure the router or switch to send router advertisements.

4. Set the physical interface to advertise.

For each physical interface that is to send advertisements, add the interface. In most cases the default advertising parameters work well, but you can change them if required. By default, the router or switch sends advertisements every 7.5 to 10 minutes, with a lifetime of 30 minutes. These settings are likely to work in most situations and not cause extra traffic, even if there are several routers or switches on the LAN. If you change these settings, keep the following proportions:

```
lifetime=3 x maxadvertisementinterval
```

minadvertisementinverval=0.75 x maxadvertisementinterval

To change these settings, use one of the commands:

- add ip advertise interface=*interface* [advertisementaddress={all|limited}] [maxadvertisementinterval=4..1800] [minadvertisementinterval=3..maxadvertisementinterval] [lifetime=maxadvertisementinterval..9000]
- set ip advertise interface=interface [advertisementaddress={all|limited}] [maxadvertisementinterval=4..1800]
 [minadvertisementinterval=3..maxadvertisementinterval] [lifetime=maxadvertisementinterval..9000]

5. Stop advertising on other logical interfaces.

By default, logical interfaces are set to advertise if their physical interface is set to advertise. If the physical interface has more than one logical interface (IP multihoming), and you only want some of them to advertise, set the other logical interfaces not to advertise with one of the commands:

add ip interface=interface ipaddress={ipadd|dhcp} advertise=no [other-ip-parameters]

```
set ip interface=interface advertise=no [other-ip-parameters]
```

6. Set preference levels.

By default, every logical interface has the same preference for becoming a default router (mid range, 0). To give a logical interface a higher preference, increase **preferencelevel**. To give it a lower preference, decrease this value. If it should never be used as a default router, set it to **notdefault**.

```
add ip interface=interface ipaddress={ipadd|dhcp} preferencelevel={-2147483648..2147483647|notdefault} [other-ip-parameters]
```

```
set ip interface=interface
[preferencelevel={-2147483648..2147483647|notdefault}] [other-ip-parameters]
```

7. Enable advertising.

To enable router advertisements on all configured advertising interfaces, use the command:

enable ip advertise

8. Check advertise settings.

To check the router advertisement settings, use the command:

show ip advertise

STP and MSTP debugging enhancements (CR00016978)

Debugging command and output enhancements

STP and MSTP debugging have been enhanced in the following ways:

• A new STP and MSTP debugging option turns on real-time switch port state debugging. This option displays a message every time STP/MSTP asks for the state of a port to be changed. To enable the new debugging, use one of the commands:

enable stp[={stp-name|ALL}] debug=swi

enable mstp debug=swi

The output takes the form "<timestamp> <port> <new state>". For example, the output "13:37:47/6.4/Discarding" shows that port 6.4 moved in to the discarding state at 13:37:47.

New switch debugging options report the same output as the new STP/MSTP debug option, but displays the output when the STP/MSTP state changes within the switching module, instead of within the STP/MSTP module. Therefore, the STP/MSTP debugging shows the change that STP/MSTP asked for and the switch debugging shows the change that switching made. These two changes should be compatible. To enable the new switch debugging, usethe command:

```
enable switch debug={stp|mstp}
```

A new tconly parameter limits message debugging so that an incoming or outgoing message is only displayed if it is a topology change message (the TC-flag is set within the message). This is useful when debugging IGMP topology change notification. To turn this feature on and off, use one of the commands:

```
enable stp[={stp-name|ALL}] debug=msg tconly={on|off|yes|no}
```

```
enable mstp debug=msg tconly={on|off|yes|no}
```

The default is **off**.

■ All STP and MSTP debugging output is now time-stamped.

New show commands

The following new commands display the current port states (in hardware) of all ports that are taking part in STP or MSTP:

show switch stp show switch mstp

The following example shows the output of the **show switch stp** command.

```
Switch STP Port State Information at 12:09:52:
ST
     Port
                  State
     _ _ _ _
                  ____
_ _
0
     2
                   Fo
0
     3
                   Fo
0
     5
                   вl
0
     6
                   Li
```

The following example shows the output of the **show switch mstp** command.

```
Switch MSTP Port State Information
Switch STP Port State Information at 04:50:37:
ST
     Port
            State
            ____
_ _
     _ _ _ _
1
     33
            Fo
1
     48
            Fo
2
     33
            Fo
2
     48
            Fo
3
     33
            Fo
3
     48
            Fo
```

The following table lists the fields in this output.

Parameter	Me	aning
ST	The	ID number of the Spanning Tree that the port belongs to.
Port	The	switch port whose state is displayed.
State	The	STP state of the port.
	Bl	Blocking: forwarding disabled, learning disabled, BPDUs received
	Li	Listening : forwarding disabled, learning disabled, BPDUs received (only on AT-9800 series switches)
	Le	Learning: forwarding disabled, learning enabled, BPDUs received
	Fo	Forwarding: forwarding enabled, learning enabled, BPDUs received
	Di	Disabled: forwarding disabled, learning disabled, BPDUs discarded

Acting on traffic destined for a particular DHCP client (CR00017018)

This enhancement enables you to act on traffic that is received on an uplink port and is destined for a particular DHCP client. It expands the classifier functionality so that the switch can use DHCP snooping records to determine which traffic is destined for each client. Once the classifier has identified the traffic, you can apply a QoS policy or hardware filters to it.

The enhancement applies to AT-8948, x900-48, and AT-9900 series switches.

For example, you can use the new functionality to track how much traffic each user receives via an uplink port. This enables you to track traffic usage at the uplink port, even if destination IP addresses are dynamically assigned by DHCP and traffic for multiple users is in the same VLAN.

To configure such tracking:

9. Configure DHCP snooping.

10. Create the required classifiers.

For each DHCP client, create a classifier using the following new options:

create classifier=id ipdaddress=dhcpsnooping snoopport=port-number snoopvlan=vlan-id

The **dhcpsnooping** option for the **ipdaddress** parameter causes the switch to dynamically create appropriate classifiers when DHCP snooping deems that an appropriate DHCP lease event has occurred.

The **snoopport** parameter specifies the switch port that traffic egresses for the target DHCP client.

The snoopvlan parameter specifies the VLAN for traffic to that client.

11. Put the classifiers into a QoS heirarchy.

12. Apply the QoS policy to the uplink port.

13. Use the traffic class counters to see how much traffic is destined for each client.

The new options have also been added to the set classifier command and output of the show classifier command.

Example

For example, consider the following figure. In this example, the QoS policy on the uplink port includes the following classifier:

create classifier=1 ip=dhcpsnooping snoopport=x snoopvlan=y

When the client receives a DHCP lease, all traffic that comes in through the uplink port and is destined for the client will match classifier 1.



Version 291-20

Support for the new x900-48FS switch (CR00016662)

The x900-48FS is a new model in the x900 Series of layer 3 gigabit and fast Ethernet switches. Its key features are:

- Multi-layer Fast Ethernet switch
- 48-port 100BASE-X SFP sockets, 100 Mbps, full or half duplex
- 4-port 1000BASE-X SFP uplink sockets, 1000 Mbps, full duplex
- Support for hot-swappable SFP modules
- Hot-swappable, load sharing PSUs
- 1U height, rack-mountable
- Non-blocking Layer 2 and Layer 3 IP switching
- IPv6-ready hardware for accelerated unicast and multicast routing
- 4096 Layer 2 multicast entries
- 1024 Layer 3 IPv4 multicast entries
- 4096 logical IPv6 interfaces
- 32MBytes of fixed flash
- 256MBytes of Synchronous DRAM, expandable to 512MBytes with DIMM
- CompactFlash slot for hot-swappable expansion of flash memory up to 128MBytes

x900-48FS front panel



For more information about the x900 Series and expansion options, see the Hardware Reference. The Hardware Reference is available from www.alliedtelesis.co.nz/documentation/manuals.html.

IGMP snooping fast leave in multiple host mode (CR00017482)

The IGMP snooping fast leave option has been enhanced, to make it available when multiple clients are attached to a single port on the snooping switch. Fast leave now has two modes available:

- multiple host mode—the new feature. In multiple host mode, the snooper tracks which clients are joined to a given IP multicast group on a given port. As soon as the last client leaves a group on a port, the snooper shuts off the multicast to that port.
- single host mode—the existing functionality. In single host mode, as soon as the snooper receives a leave message for a group on a port, it shuts off the multicast. This mode assumes that there are no other clients on the port that are still interested in receiving the multicast, so is suitable only when clients are directly attached to the snooper.

To specify the new multiple mode, use the command:

```
set igmpsnooping vlan={vlan-name|1..4094|all} fastleave=multiple
```

To specify single mode, use either of the commands:

set igmpsnooping vlan={vlan-name|1..4094|all} fastleave=single

set igmpsnooping vlan={vlan-name|1..4094|all} fastleave=on

The command **show igmpsnooping vlan** has also been enhanced. The new command syntax is:

show igmpsnooping vlan={vlan-name|1..4094|all} [group={multicast-ip-address|allgroups}] [detail]

The group parameter lets you display information for only one group or for only the All Groups port (the allgroups option).

The **detail** parameter displays more detailed information, including expiry times for each port, and in the case of multiple host fast leave mode, the list of hosts on a port. The following example shows this.

IGMP Snooping	
Status Enabled Disabled All-groups ports None	
Vlan Name (vlan id) default (1) Fast Leave Multiple Host Topol Query Solicitation Off Static Router Ports None Group List 2 groups	Γοđλ
Group 224.0.1.22 Port 24 Hosts: 1 00-00-cd-27-be-f5 (172.20.176.200)	Timeout in 256 secs Timeout in 257 secs Timeout in 257 secs
Group 239.255.255.250 Port 24 Hosts: 1 00-00-cd-27-be-f5 (172.20.176.200)	Timeout in 258 secs Timeout in 259 secs Timeout in 259 secs

Support for the new Rapier 48w switch

The Rapier 48w is a new model in the Rapier Series of layer 3 gigabit and fast Ethernet switches. Its key features are:

- 48-port 10BASE-T/100BASE-TX (RJ-45 connectors)
- Two 1000BASE SFP ports
- Two asynchronous serial console ports with DB9 connectors
- One Network Service Module bay, with support for various WAN interface cards
- Auto-negotiating Layer 3 Managed Switch
- Enhanced switching core
- Replaceable air filters and fan-only modules (FOMs) for NEBS applications

Rapier 48w front panel



Rapier 48w rear panel



For more information about the Rapier Series and expansion options, see the Hardware Reference. The Hardware Reference is available from www.alliedtelesis.co.nz/documentation/manuals.html.

Backing up the configuration with SNMP (CR00016221)

With this enhancement, you can use SNMP to:

- set parameters for uploading files from the router or switch, and
- upload files to a TFTP server

SNMP already lets you save the current configuration to a file on the router or switch. You can use this with the new options to back up the configuration to a TFTP server. To do this, perform the following steps.

1. Save the configuration

To save the current configuration, use SNMP SET createConfigFile. The following screenshot shows this for a file called tst.cfg.

Set - createConfig	JFile.0	×
<u>%</u> 🖉 😽		2
Remote SNMP agent		
172.20.73.221		- 🖻
OID to Set		
1.3.6.1.4.1.207.8.4.4.4.49.5.0		
Value to Set		
tst.cfg		💽 📓 🕐
- Syntax		
C Integer32	C Timeticks	C Counter64
C UInteger32	O IP address	🔿 Opaque
C Counter32	O OID	🔿 Nsapaddr
C Gauge32	Octets	🔿 Bits
SNM	Pv2c Success.	

2. Set the load parameters

To specify the server IP address, use SNMP SET loadServer. To set the filename, use SNMP SET loadFilename. The following screenshot shows setting the filename to tst.cfg.

Set - loadFilenam	e.1	×
🕺 🖉 💫		2
Remote SNMP age	ent	
172.20.73.221		- 🎽
OID to Set		
1.3.6.1.4.1.207.8.4.4.4.48.1.1.4.1		
Value to Set		
tst.cfg		▼ S C
- Syntax		
C Integer32	C Timeticks	C Counter64
O UInteger32	O IP address	🔿 Opaque
Counter32	C OID	🔿 Nsapaddr
○ Gauge32	 Octets 	O Bits
SNMI 🖉 🖉	Pv2c Success.	

3. Upload the file

To upload the file, use SNMP SET loadStatus and set it to a value of 8. The following screenshot shows this.

Set - loadStatus.0	- actionupload(8) 🗴	
🐒 🖉 😼		2	
 Remote SNMP age 	ent		
172.20.73.221	- 🔁		
OID to Set			
1.3.6.1.4.1.207.8.4.4.4.48.2.0		I	
Value to Set			
8		💽 🖄 🖸	
- Syntax			
Integer32	C Timeticks	C Counter64	
O UInteger32	C IP address	C Opaque	
Counter32	C OID	O Nsapaddr	
🔿 Gauge32	C Octets	O Bits	
⊘ ⊘ ⊘ BNMPv2c Success.			
SNMP ASN.01 BER Padding (CR00016523)

This enhancement enables you to specify whether SNMP adds 0x00 padding when the most significant 9 bits of an object's value are all 1, or whether the encoding follows the ASN.01 BER rule, which cuts off the most significant byte of 0xff. This setting has an impact on all integer type MIB objects, including 32 bit and 64 bit counter objects.

To add the padding, use the command:

set snmp asnberpadding={on|yes|true}

To use the ASN.01 BER rule, which is the default, use the command:

set snmp asnberpadding={off|no|false}

The following table lists examples.

Bits	Value (decimal)	Value (hex)	asnberpadding setting	Encoding
counter32	4289592837	0xFFADFE05	on	41 05 00 ff ad fe 05
			off	41 03 ad fe 05
counter64	18410715280977201498	0xFF800000ff80895A	on	46 09 00 ff 80 00 00 ff 80 89 5a
			off	46 07 80 00 00 ff 80 89 5a

To see whether or not padding is added, use the command:

show snmp

and check the new "ASN.01 BER Padding" field.

253