



## **TQ6602 Wireless Access Point Version 7.0.1-4.3 Software Release Notes**

Read this document before using the management software. The document has the following sections:

- ☐ “Firmware File,” next
- ☐ “Resolved Issues” on page 1
- ☐ “Known Issues” on page 2
- ☐ “Limitations” on page 4
- ☐ “Limitations When Using With Channel Blanket” on page 4
- ☐ “Supported Countries” on page 5
- ☐ “Contacting Allied Telesis” on page 7

### **Firmware File**

---

The firmware filename for the TQ6602 version 7.0.1-4.3 access point is:

- ☐ AT-TQ6602-7.0.1-4.3.img

For instructions on how to upgrade the firmware on the TQ6602 access point, see the TQ6602 *Wireless Access Point Management Software User's Guide* at [www.alliedtelesis.com/library](http://www.alliedtelesis.com/library).

### **Resolved Issues**

---

The following issues were resolved in Version 7.0.1-4.3 for the TQ6602 wireless access point:

- ☐ When specifying an encryption key to download a Technical Support file, sometimes the retrieval would fail.
- ☐ An error in BLOCK ACK processing would sometimes cause the AP to reboot.
- ☐ Following the detection of a wireless chip abnormality, the recovery process would start but sometimes fail, causing the AP to unexpectedly reboot.

## Known Issues

---

Here are the known issues for the TQ6602 version 7.0.1-4.3 management software:

- ☐ The client's User ID and password are not included in the technical support file.
- ☐ The access point saves a value for the secondary RADIUS IP or secondary RADIUS server key even when only one of them is entered. Saving incomplete secondary RADIUS server information does not affect any operation.
- ☐ The access point might send NTP packets before obtaining its IP address from DHCP servers.
- ☐ When a wireless client's password includes the "%" symbol, the access point does not allow the wireless client to connect to a WEP VAP.
- ☐ The access point issues an error log when a radio interface starts up.
- ☐ When Band steering is enabled on Radio1 and Hidden SSID is enabled on VAPs, the access point does not allow wireless clients to connect to the VAPs on Radio1.
- ☐ The TX and RX rates on the Associated Clients page are displayed incorrectly.
- ☐ An ad hoc device is displayed as an AP in the type field on the Neighbor AP page.
- ☐ A wireless client fails to connect to the access point using PMKSA cache.
- ☐ The access point issues an error log when the firmware is upgraded or the access point is reset to the Factory Default.
- ☐ The access point might send a Neighbor AP detection report without an SSID to Vista Manager.
- ☐ The access point might detect radar incorrectly.
- ☐ The access point displays the Neighbor AP with WEP security to None.
- ☐ The access point might issue a radar detection log when the channel is changed.
- ☐ The access point displays WPA3 Enterprise (GCMP) as WPA3 Enterprise (CCMP) on the Neighbor AP page.
- ☐ If a wireless client's IP address and Virtual IP address are on the same subnet, the Captive Portal authentication page will not appear.
- ☐ The access point issues a detect beacon transmission log when the configuration of the access point is changed.
- ☐ When Client Isolation is enabled on Channel Blanket, Client Isolation must be disabled on the radio settings of the access point. If Client Isolation is enabled on the radios of the access point, wireless clients connected to a Channel Blanket VAP might be able to communicate among them.
- ☐ When all of the access points that belong to the same Channel Blanket start at the same time, it takes approximately three minutes for wireless clients connected to the Channel Blanket VAP to start communicating among them. However, wireless clients and devices on the wired network might start communicating less than three minutes even while wireless clients cannot communicate among them.
- ☐ When a wireless client is denied connection by the MAC Address filter, a disconnection log entry that the access point issues does not include a reason, which the MAC Address filtering denied the client.

- ❑ Enabling IPv6 communication with IP auto-configuration of IPv6 Router Advertisement does not function on VAPs with dynamic VLAN enabled.
- ❑ EngineBoots and EngineTime values of SNMPv3 Trap are sent with a value of 0.
- ❑ More than 50 pages in Walled Garden is registered even though the access point only supports up to 50 pages.
- ❑ Wireless clients might be disconnected if the access point in Channel Blanket failed to a communication check from the wired network.
- ❑ Combining WDS and radar channels (W53 and W56) is not supported. When using WDS, do not select W53 or W56 channel.
- ❑ When IEEE802.11r/11k/11v is enabled, for some access points with Hidden SSID enabled, information is not shared correctly.

## Limitations

---

Here are the limitations for the TQ6602 version 7.0.1-4.3 management software:

- ☐ Zero Wait DFS is not supported.
- ☐ Displaying of Client Traffic Counter, which is operated by Vista Manager EX, is not supported for the access point.
- ☐ Wireless clients may not be able to connect via the Radio 1 interface in certain conditions. Allied Telesis verified that this behavior occurred when the number of enabled VAPs of Radio 1 and number of surrounding APs (BSSID) exceeded the numbers shown in the table.

Number of Enabling VAPs	Number of Surrounding APs (BSSID)
1	120
3	95
5	75
10	55
16	35

In real environments, this behavior may occur even if the numbers are not exceeded. It is likely caused in conditions when the wireless spatial is congested by low-rate packets.

## Limitations When Using With Channel Blanket

---

The Channel Blanket feature has the following limitations:

### Limitations on the Access Point

- ☐ Band Steer is not supported.
- ☐ Neighbor AP Detection is not supported.
- ☐ All access points on Channel Blanket need to have the same Radio settings.
- ☐ WDS is not supported.
- ☐ Association Advertisement is not supported.

### Limitations on the Blanket Radio Interface

- ☐ The value of the RTS Threshold cannot be changed.
- ☐ Airtime Fairness is not supported.
- ☐ OFDMA is not supported.
- ☐ MU-MIMO is not supported.

**Limitations on Channel Blanket-enabled VAP**

- ☐ The value of the Broadcast Key Refresh Rate cannot be changed.
- ☐ The value of the Session Key Refresh Rate cannot be changed.
- ☐ The value of the Session Key Refresh Action cannot be changed.
- ☐ RADIUS Accounting is not supported.
- ☐ Fast Roaming is not supported.
- ☐ Dynamic VLAN is forced to be disabled.
- ☐ The Session-Timeout RADIUS attribute is forced to be disabled.
- ☐ The value of the Inactivity Timer cannot be changed.
- ☐ IEEE802.11w(MFP) needs to be disabled.

**Limitations on the Blanket Settings**

- ☐ The Management VLAN ID and Control VLAN ID cannot be specified to the same VLAN.
- ☐ The VAP VLAN ID and Control VLAN ID cannot be specified to the same VLAN.

**Limitations on the Blanket Behavior**

- ☐ When the access point is turned off or rebooted, it takes approximately two minutes to restore the communication with wireless clients that is connected to the access point.

**Supported Countries**

---

Version 7.0.1-4.3 continues to support the following countries:

- ☐ Australia
- ☐ Austria
- ☐ Belgium
- ☐ Bosnia and Herzegovina
- ☐ Bulgaria
- ☐ Canada
- ☐ China
- ☐ Croatia
- ☐ Cyprus
- ☐ Czech Republic
- ☐ Denmark
- ☐ Estonia
- ☐ Finland
- ☐ France
- ☐ Germany
- ☐ Gibraltar
- ☐ Greece

- ☐ Hong Kong
- ☐ Hungary
- ☐ Iceland
- ☐ India
- ☐ Ireland
- ☐ Italy
- ☐ Japan
- ☐ Latvia
- ☐ Liechtenstein
- ☐ Lithuania
- ☐ Luxembourg
- ☐ Macedonia
- ☐ Malaysia
- ☐ Monaco
- ☐ Montenegro
- ☐ Netherlands
- ☐ New Zealand
- ☐ Norway
- ☐ Poland
- ☐ Portugal
- ☐ Romania
- ☐ Serbia
- ☐ Singapore
- ☐ Slovakia Republic
- ☐ Slovenia
- ☐ Spain
- ☐ Sweden
- ☐ Switzerland
- ☐ Taiwan
- ☐ Thailand
- ☐ Turkey
- ☐ Ukraine
- ☐ United Kingdom
- ☐ United States
- ☐ Viet Nam

## Contacting Allied Telesis

---

For more information, go to **[www.alliedtelesis.com](http://www.alliedtelesis.com)**.

Copyright © 2025 Allied Telesis Inc., Inc.

All rights reserved. No part of this publication may be reproduced without prior written permission from Allied Telesis Inc., Inc. Allied Telesis Inc. and the Allied Telesis Inc. logo are trademarks of Allied Telesis Inc., Incorporated. All other product names, company names, logos or other designations mentioned herein are trademarks or registered trademarks of their respective owners. Allied Telesis Inc., Inc. reserves the right to make changes in specifications and other information contained in this document without prior written notice. The information provided herein is subject to change without notice. In no event shall Allied Telesis Inc., Inc. be liable for any incidental, special, indirect, or consequential damages whatsoever, including but not limited to lost profits, arising out of or related to this manual or the information contained herein, even if Allied Telesis Inc., Inc. has been advised of, known, or should have known, the possibility of such damages.