



# GS950 PS Series Gigabit Ethernet PoE+ Switch Versions 1.0.6 and 3.0.8 Software Release Notes

Read this document before updating the management software. The document has the following sections:

- ❑ “Supported Platforms and Versions,” next
- ❑ “New Features” on page 2
- ❑ “Resolved Issues” on page 2
- ❑ “Contacting Allied Telesis” on page 3

## Supported Platforms and Versions

---

The following table indicates the firmware version and file name for each switch model:

Model	Firmware Version	Firmware File Name
GS950/28PS	v.1.0.6	AT_GS950_28PS-AT-S126-V1-0-6-(1-00-025)-ALL.hex
GS950/10PS	v.3.0.8	AT_GS950_10PS-AT-S110-V3-0-8-(1-00-038)-ALL.hex
GS950/16PS		AT_GS950_16PS-AT-S112-V3-0-8-(1-00-036)-ALL.hex
GS950/48PS		AT_GS950_48PS-AT-S111-V3-0-8-(1-00-036)-ALL.hex

For instructions on how to upgrade the firmware on these switches, see the *GS950 PS Gigabit Ethernet PoE+ Switches Command Line Interface User’s Guide*, *AT-GS950/10PS Switch Web Interface User’s Guide*, *AT-GS950/16PS Switch Web Interface User’s Guide*, or *AT-GS950/48PS Switch Web Interface User’s Guide* at [www.alliedtelesis.com/library](http://www.alliedtelesis.com/library).

## New Features

---

The following new features are added to versions 1.0.6 and 3.0.8:

- ❑ TLS version 1.3 is supported.
- ❑ Microsoft Edge is supported for the Web Interface.

## Resolved Issues

---

The following issues were resolved in versions 1.0.6 and 3.0.8:

- ❑ The valid end date of the SSL certificate was incorrect.
- ❑ The switch occasionally shut down when being logged in using HTTPS with Google Chrome.
- ❑ The switch rebooted when unexpected operations were conducted on the login page.
- ❑ The switch with SSL enabled rebooted when it was accessed repeatedly.

The following issues are only applied to the GS950/10PS switch and resolved in version 3.0.8:

- ❑ A switch port's link repeated up and down and PoE power feed repeated to stop and restart.
- ❑ The PoE MAX LED turned red unnecessarily.
- ❑ The PoE LED turned green and amber repeatedly.
- ❑ PoE information on the Web Interface was not displayed correctly.
- ❑ PoE settings were not changed from the Web Interface. Pressing the apply button on the page showed an SNMP error message and did not update the settings.
- ❑ PoE related logs were generated repeatedly and incorrectly.

## Contacting Allied Telesis

---

If you need assistance with this product, you may contact Allied Telesis technical support by going to the Services & Support section of the Allied Telesis web site at **[www.alliedtelesis.com/support](http://www.alliedtelesis.com/support)**. You can find links for the following services on this page:

- ❑ Helpdesk (Support Portal) - Log onto Allied Telesis interactive support center to search for answers to your questions in our knowledge database, check support tickets, learn about Return Merchandise Authorizations (RMAs), and contact Allied Telesis technical experts.
- ❑ Software Downloads - Download the latest software releases for your product.
- ❑ Licensing - Register and obtain your License key to activate your product.
- ❑ Product Documents - View the most recent installation guides, user guides, software release notes, white papers and data sheets for your product.
- ❑ Warranty - View a list of products to see if Allied Telesis warranty applies to the product you purchased and register your warranty.
- ❑ Allied Telesis Helpdesk - Contact a support representative.

To contact a sales representative or find Allied Telesis office locations, go to **[www.alliedtelesis.com/contact](http://www.alliedtelesis.com/contact)**.

Copyright © 2022 Allied Telesis Inc., Inc.

All rights reserved. No part of this publication may be reproduced without prior written permission from Allied Telesis Inc., Inc. Allied Telesis Inc. and the Allied Telesis Inc. logo are trademarks of Allied Telesis Inc., Incorporated. All other product names, company names, logos or other designations mentioned herein are trademarks or registered trademarks of their respective owners. Allied Telesis Inc., Inc. reserves the right to make changes in specifications and other information contained in this document without prior written notice. The information provided herein is subject to change without notice. In no event shall Allied Telesis Inc., Inc. be liable for any incidental, special, indirect, or consequential damages whatsoever, including but not limited to lost profits, arising out of or related to this manual or the information contained herein, even if Allied Telesis Inc., Inc. has been advised of, known, or should have known, the possibility of such damages.