

iGS950 Series Layer 2 Gigabit Ethernet PoE+ WebSmart Switches Version v1.00.005 Software Release Notes

Read this document before updating the management software:

- □ "Supported Platforms," next
- □ "Firmware Release v1.00.005" on page 1
- □ "Firmware Release v1.00.004" on page 2
- □ "Open Issues" on page 2

To learn about Allied Telesis products and services, go to www.alliedtelesis.com.

Supported Platforms

This firmware release applies to the following switches in the iGS950 Series:

- □ AT-iGS950/10PS
- □ AT-iGS950/20PS
- □ AT-iGS950/28PS
- □ AT-iGS950/52PS

This table lists the new and previous firmware versions.

Series	New Firmware Version	Previous Firmware Version
iGS950	v1.00.005	v1.00.004

For instructions on upgrading the firmware on the switches, refer to the *iGS950 Series Web Browser User Guide* at **www.alliedtelesis.com/library**.

Firmware Release v1.00.005

New Feature

□ DHCP server - The switch uses the DHCP server to automatically assign IPv4 addresses to the devices on its network.

Firmware Release v1.00.004

Resolved Issues

- ☐ The AT-iGS950/52PS Switch had difficulty initializing its operating system when there was a heavy PoE load from network devices on its ports. This issue has been resolved.
- □ iGS950 Switches periodically experienced difficulty maintaining the traffic packet counters. This issue has been resolved.
- □ iGS950 Switches periodically experienced difficulty maintaining the Link Layer Discovery Protocol (LLDP). This issue has been resolved.

Open Issues

None.

Copyright © 2025 Allied Telesis, Inc.

All rights reserved. No part of this publication may be reproduced without prior written permission from Allied Telesis, Inc. Allied Telesis, Inc. and the Allied Telesis, Inc. logo are trademarks of Allied Telesis, Incorporated. All other product names, company names, logos or other designations mentioned herein are trademarks or registered trademarks of their respective owners.

Allied Telesis, Inc. reserves the right to make changes in specifications and other information contained in this document without prior written notice. The information provided herein is subject to change without notice. In no event shall Allied Telesis, Inc. be liable for any incidental, special, indirect, or consequential damages whatsoever, including but not limited to lost profits, arising out of or related to this manual or the information contained herein, even if Allied Telesis, Inc. has been advised of, known, or should have known, the possibility of such damages.

Manufacturer: Allied Telesis, Inc. 3041 Orchard Parkway San Jose, CA 95134 USA alliedtelesis.com



Document Library