


Overview

The AT-LX3801 blank slot cover protects the fiber optic connectors on the backplane from becoming dirty, and helps maintain proper air flow through the chassis.

**Note**

Allied Telesyn strongly recommends that a blank slot cover be inserted in any slot that does not contain a functioning AT-LX3811/x Multi-Service Line Card.

Related Documents

For details on the features and functions of your Allied Telesyn AT-LX3800U Multi-Service Transport System, refer to the following documents on our web site, www.alliedtelesyn.com:

- *AT-LX3800U Multi-Service Transport System Installation and Maintenance Guide* (part number 613-50549-00)
- *AT-S65 Management Software User's Guide* (part number 613-50604-00)

Verifying Package Contents

Make sure that the correct components are included in your package:

- AT-LX3801 Blank Slot Cover
- Warranty Card
- This installation guide

If any item is missing or damaged, contact your Allied Telesyn sales representative for assistance.


Installing an AT-LX3801 Blank Slot Cover

To install an AT-LX3801 Blank Slot Cover, perform the following procedure:

1. Remove the AT-LX3811 Blank Slot Cover from its shipping package and store the package in a safe place. You must use the original package if you need to

Overview

The AT-LX3801 blank slot cover protects the fiber optic connectors on the backplane from becoming dirty, and helps maintain proper air flow through the chassis.

**Note**

Allied Telesyn strongly recommends that a blank slot cover be inserted in any slot that does not contain a functioning AT-LX3811/x Multi-Service Line Card.

Related Documents

For details on the features and functions of your Allied Telesyn AT-LX3800U Multi-Service Transport System, refer to the following documents on our web site, www.alliedtelesyn.com:

- *AT-LX3800U Multi-Service Transport System Installation and Maintenance Guide* (part number 613-50549-00)
- *AT-S65 Management Software User's Guide* (part number 613-50604-00)

Verifying Package Contents

Make sure that the correct components are included in your package:

- AT-LX3801 Blank Slot Cover
- Warranty card
- This installation guide

If any item is missing or damaged, contact your Allied Telesyn sales representative for assistance.


Installing an AT-LX3801 Blank Slot Cover

To install an AT-LX3801 Blank Slot Cover, perform the following procedure:

1. Remove the AT-LX3811 Blank Slot Cover from its shipping package and store the package in a safe place. You must use the original package if you need to

Overview

The AT-LX3801 blank slot cover protects the fiber optic connectors on the backplane from becoming dirty, and helps maintain proper air flow through the chassis.

**Note**

Allied Telesyn strongly recommends that a blank slot cover be inserted in any slot that does not contain a functioning AT-LX3811/x Multi-Service Line Card.

Related Documents

For details on the features and functions of your Allied Telesyn AT-LX3800U Multi-Service Transport System, refer to the following documents on our web site, www.alliedtelesyn.com:

- *AT-LX3800U Multi-Service Transport System Installation and Maintenance Guide* (part number 613-50549-00)
- *AT-S65 Management Software User's Guide* (part number 613-50604-00)

Verifying Package Contents

Make sure that the correct components are included in your package:

- AT-LX3801 Blank Slot Cover
- Warranty card
- This installation guide

If any item is missing or damaged, contact your Allied Telesyn sales representative for assistance.


Installing an AT-LX3801 Blank Slot Cover

To install an AT-LX3801 Blank Slot Cover, perform the following procedure:

1. Remove the AT-LX3811 Blank Slot Cover from its shipping package and store the package in a safe place. You must use the original package if you need to

Overview

The AT-LX3801 blank slot cover protects the fiber optic connectors on the backplane from becoming dirty, and helps maintain proper air flow through the chassis.

**Note**

Allied Telesyn strongly recommends that a blank slot cover be inserted in any slot that does not contain a functioning AT-LX3811/x Multi-Service Line Card.

Related Documents

For details on the features and functions of your Allied Telesyn AT-LX3800U Multi-Service Transport System, refer to the following documents on our web site, www.alliedtelesyn.com:

- *AT-LX3800U Multi-Service Transport System Installation and Maintenance Guide* (part number 613-50549-00)
- *AT-S65 Management Software User's Guide* (part number 613-50604-00)

Verifying Package Contents

Make sure that the correct components are included in your package:

- AT-LX3801 Blank Slot Cover
- Warranty card
- This installation guide

If any item is missing or damaged, contact your Allied Telesyn sales representative for assistance.


Installing an AT-LX3801 Blank Slot Cover

To install an AT-LX3801 Blank Slot Cover, perform the following procedure:


1. Remove the AT-LX3811 Blank Slot Cover from its shipping package and store the package in a safe place. You must use the original package if you need to

return the unit to Allied Telesyn.


2. Select the slot in the AT-LX3800U chassis where you want to install the blank slot cover.
3. If an AT-LX3811/x Line Card is installed in the slot, do the following:
 - a. Disconnect the cables from the SFP transceiver in the line card.
 - b. Reinstall the SFP dust cap.
 - c. Remove the line card from the slot.
 - d. Put dust caps on the fiber optic connectors.
4. Locate the left and right alignment guides in the slot.



5. Align the back edge of the blank slot cover with the left and right alignment guides.
6. Slide the blank slot cover into the slot until the faceplate is flush with the front.



7. Use a Phillips head screwdriver to tighten the captive screws.




8. Repeat this procedure to install additional AT-LX3801 Blank Slot Covers.


Copyright © 2004 Allied Telesyn, Inc. All rights reserved. No part of this publication may be reproduced without prior written permission from Allied Telesyn, Inc. www.alliedtelesyn.com

return the unit to Allied Telesyn.


2. Select the slot in the AT-LX3800U chassis where you want to install the blank slot cover.
3. If an AT-LX3811/x Line Card is installed in the slot, do the following:
 - a. Disconnect the cables from the SFP transceiver in the line card.
 - b. Reinstall the SFP dust cap.
 - c. Remove the line card from the slot.
 - d. Put dust caps on the fiber optic connectors.
4. Locate the left and right alignment guides in the slot.



5. Align the back edge of the blank slot cover with the left and right alignment guides.
6. Slide the blank slot cover into the slot until the faceplate is flush with the front.



7. Use a Phillips head screwdriver to tighten the captive screws.




8. Repeat this procedure to install additional AT-LX3801 Blank Slot Covers.


Copyright © 2004 Allied Telesyn, Inc. All rights reserved. No part of this publication may be reproduced without prior written permission from Allied Telesyn, Inc. www.alliedtelesyn.com

return the unit to Allied Telesyn.


2. Select the slot in the AT-LX3800U chassis where you want to install the blank slot cover.
3. If an AT-LX3811/x Line Card is installed in the slot, do the following:
 - a. Disconnect the cables from the SFP transceiver in the line card.
 - b. Reinstall the SFP dust cap.
 - c. Remove the line card from the slot.
 - d. Put dust caps on the fiber optic connectors.
4. Locate the left and right alignment guides in the slot.



5. Align the back edge of the blank slot cover with the left and right alignment guides.
6. Slide the blank slot cover into the slot until the faceplate is flush with the front.



7. Use a Phillips head screwdriver to tighten the captive screws.




8. Repeat this procedure to install additional AT-LX3801 Blank Slot covers.


Copyright © 2004 Allied Telesyn, Inc. All rights reserved. No part of this publication may be reproduced without prior written permission from Allied Telesyn, Inc. www.alliedtelesyn.com

return the unit to Allied Telesyn.


2. Select the slot in the AT-LX3800U chassis where you want to install the blank slot cover.
3. If an AT-LX3811/x Line Card is installed in the slot, do the following:
 - a. Disconnect the cables from the SFP transceiver in the line card.
 - b. Reinstall the SFP dust cap.
 - c. Remove the line card from the slot.
 - d. Put dust caps on the fiber optic connectors.
4. Locate the left and right alignment guides in the slot.



5. Align the back edge of the blank slot cover with the left and right alignment guides.
6. Slide the blank slot cover into the slot until the faceplate is flush with the front.



7. Use a Phillips head screwdriver to tighten the captive screws.



8. Repeat this procedure to install additional AT-LX3801 Blank Slot covers.

Copyright © 2004 Allied Telesyn, Inc. All rights reserved. No part of this publication may be reproduced without prior written permission from Allied Telesyn, Inc. www.alliedtelesyn.com