



AT-S116 V2.0.2 [1.00.015]

AT-GS950/48 Gigabit Ethernet Smart Switch

Software Release Notes

Please read this document before you begin to use the AT-S116 V2.0.2 [1.00.015] Management Software.

Supported Platforms

AT-S116 V2.0.2 [1.00.015] Management Software is supported on the AT-GS950/48 Gigabit Ethernet Smart Switch running a previous version of AT-S116.

The AT-GS950/48 Gigabit Ethernet Smart Switch supports the following 100 MB SFP modules:

- ☐ AT-SPFX/2
- ☐ AT-SPFX/15
- ☐ AT-SPFX/40

The AT-GS950/48 Gigabit Ethernet Smart Switch supports the following 1000 MB SFP modules:

- ☐ AT-SPSX
- ☐ AT-SPLX10
- ☐ AT-SPTX
- ☐ AT-SPBD10-13 and AT-SPBD10-14

Product Documentation

Refer to the Allied Telesis web site at www.alliedtelesis.com/support/documentation for the latest installation and user guides.

V2.0.2 Resolved Issues

- ☐ A security vulnerability in switch management is fixed.

Operational Notes

- ☐ A Telnet interface is not supported on this switch.
- ☐ SSH is not supported on this switch.
- ☐ Combo SFP ports must remain in Automatic mode.

V2.0.2 New Features

- ☐ None

Feature History

Version 2.0.0

- ☐ 48 10/100/1000T ports
- ☐ 4 Gig SFP uplink ports
- ☐ Web Based Management
- ☐ IPv4 and IPv6
- ☐ 802.1X Security
- ☐ Port-Based VLANs (up to 256 groups)
- ☐ Port Setting (Speed, Availability, Flow Control)
- ☐ Port Mirroring
- ☐ Link Aggregation
- ☐ Loopback Detection
- ☐ Broadcast Storm Control
- ☐ IGMP Snooping (v1/v2) and DHCP Snooping
- ☐ Static multicast group
- ☐ Spanning Tree, 802.1d/s/w
- ☐ GARP VLAN Registration Protocol (GVRP)
- ☐ Quality of Service (QoS) and Class of Service (CoS)
- ☐ SNMP (v1/v2/v3) and RMON
- ☐ Link Layer Discovery Protocol (LLDP)
- ☐ LED Eco-Friendly mode
- ☐ IEEE 802.3az Energy-Efficient Ethernet
- ☐ Desktop or Rack/Wall Mountable
- ☐ 100FX SFP support
- ☐ 802.1x Port Security with enhancements
- ☐ Network Time Protocol
- ☐ Password Protected “Factory Default Reset”
- ☐ IGMP Querier

Resolved Issues History

Version 2.0.0



Warning

Once upgraded to version 2.0.0, you cannot downgrade.

- ☐ AT-SPSX Revisions B, C, and D would not link up in the previous software version. This issue is now resolved.
- ☐ The average ping response time from the switch management is now 3 ms, or less, under normal operating conditions.

Contacting Allied Telesis

If you need assistance with this product, you may contact Allied Telesis technical support by going to the Support & Services section of the Allied Telesis web site at **www.alliedtelesis.com/support**. You can find links for the following services on this page:

- ☐ 24/7 Online Support - Enter our interactive support center to search for answers to your questions in our knowledge database, check support tickets, learn about RMAs, and contact Allied Telesis technical experts.
- ☐ USA and EMEA phone support - Select the phone number that best fits your location and customer type.
- ☐ Hardware warranty information - Learn about Allied Telesis warranties and register your product online.
- ☐ Replacement Services - Submit a Return Merchandise Authorization (RMA) request via our interactive support center.
- ☐ Documentation - View the most recent installation guides, user guides, software release notes, white papers and data sheets for your product.
- ☐ Software Updates - Download the latest software releases for your product.
- ☐ For sales or corporate contact information, go to **www.alliedtelesis.com/purchase** and select your region.

Copyright © 2016 Allied Telesis, Inc.

All rights reserved. No part of this publication may be reproduced without prior written permission from Allied Telesis, Inc.

Allied Telesis and AlliedWare Plus are trademarks of Allied Telesis, Inc. All other product names, company names, logos or other designations mentioned herein are trademarks or registered trademarks of their respective owners.

Allied Telesis, Inc. reserves the right to make changes in specifications and other information contained in this document without prior written notice. The information provided herein is subject to change without notice.