



TQ6702 and TQm6702 GEN2 Wireless Access Points Version 8.0.0-0.2 Software Release Notes

Read this document before using the management software. The document has the following sections:

- ❑ “Firmware File,” next
- ❑ “Known Issues” on page 1
- ❑ “Limitations” on page 2
- ❑ “Supported Countries” on page 2
- ❑ “Contacting Allied Telesis” on page 4

Firmware File

The firmware filename are:

- ❑ AT-TQ6702GEN2-8.0.0-0.2.img
- ❑ AT-TQm6702GEN2-8.0.0-0.2.img

For instructions on how to upgrade the management software on the TQ6702 and TQm6702 GEN2 wireless access point, see the *TQ6K GEN2 Wireless Access Point Management Software User's Guide*, available on the Allied Telesis Inc. website at www.alliedtelesis.com/library.

Known Issues

Here are the known issues for the TQ6702 and TQm6702 GEN2 Version 8.0.0-0.2 management software:

- ❑ When the radio setting is changed, the Radar Detecting Channel List is cleared.
- ❑ The access point sends broadcast frames with a random data rate.
- ❑ A wired port takes approximately 30 seconds to start communication after the wired port links up.
- ❑ The Authentication with PMKSA Cache fails on IEEE 802.11r VAP.
- ❑ The access point might fail to assign a VLAN after the IEEE802.11r roaming is selected.
- ❑ When the access point is powered with the AC adapter, a wired port might take a minute to link up after the wired cable is connected or disconnected.

Limitations

Here are the limitations for the TQ6702 and TQm6702 GEN2 Version 8.0.0-0-0.2 management software:

- SNMP is not supported.
- LAG, LACP and Cascade mode for the LAN2 Port are not supported.
- Changing value of the RTS threshold is not supported.
- The 80+80MHz option for the Bandwidth setting is not supported.
- MU-MIMO is not supported
- OFDMA is not supported.
- Airtime Fairness is not supported.
- Zero Wait DFS is not supported.
- WEP Authentication is not supported.
- Proxy ARP is not supported.
- Captive Portal is not supported.
- QR code is not supported.
- AWC Plug-in does not support the TQ6702 and TQm6702 GEN2 access points and other models in the same management group.

Supported Countries

The TQ6702 and TQm6702 GEN2 access points version 8.0.0-0-0.2 management software support the following countries:

- Australia
- Austria
- Belgium
- Bulgaria
- Canada
- Croatia
- Cyprus
- Czech Republic
- Denmark
- Estonia
- Finland
- France
- Germany
- Greece
- Hungary

- Ireland
- Italy
- Japan
- Latvia
- Lithuania
- Luxembourg
- Malta
- Netherlands
- New Zealand
- Poland
- Portugal
- Romania
- Slovakia Republic
- Slovenia
- Spain
- Sweden
- United States of America (USA)

Contacting Allied Telesis

If you need assistance with this product, you may contact Allied Telesis technical support by going to the Services & Support section of the Allied Telesis web site at **www.alliedtelesis.com/support**. You can find links for the following services on this page:

- ❑ Helpdesk (Support Portal) - Log onto Allied Telesis interactive support center to search for answers to your questions in our knowledge database, check support tickets, learn about Return Merchandise Authorizations (RMAs), and contact Allied Telesis technical experts.
- ❑ Software Downloads - Download the latest software releases for your product.
- ❑ Licensing - Register and obtain your License key to activate your product.
- ❑ Product Documents - View the most recent installation guides, user guides, software release notes, white papers and data sheets for your product.
- ❑ Warranty - View a list of products to see if Allied Telesis warranty applies to the product you purchased and register your warranty.
- ❑ Allied Telesis Helpdesk - Contact a support representative.

To contact a sales representative or find Allied Telesis office locations, go to **www.alliedtelesis.com/contact**.

Copyright © 2022 Allied Telesis Inc., Inc.

All rights reserved. No part of this publication may be reproduced without prior written permission from Allied Telesis Inc., Inc. Allied Telesis Inc. and the Allied Telesis Inc. logo are trademarks of Allied Telesis Inc., Incorporated. All other product names, company names, logos or other designations mentioned herein are trademarks or registered trademarks of their respective owners. Allied Telesis Inc., Inc. reserves the right to make changes in specifications and other information contained in this document without prior written notice. The information provided herein is subject to change without notice. In no event shall Allied Telesis Inc., Inc. be liable for any incidental, special, indirect, or consequential damages whatsoever, including but not limited to lost profits, arising out of or related to this manual or the information contained herein, even if Allied Telesis Inc., Inc. has been advised of, known, or should have known, the possibility of such damages.